	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	432521	NA	(2)(d)10	00	9599	M		
2	432321	NA	(16)(a)2.4	1	110	М		
3	432499	NFPA 1, 13.4.8	NA	10	003	М		513
4	405756	NA	(16)(a)2	3	306A	М		
5	432344	NA	(16)(a)2.4	3	308A	М		
6	432343	NA	(16)(a)2.4	3	308B	М		
7	432520	NA	(8)(a).1	3	317	М		
8	432328	NA	(16)(a)2.4	7	705B	М		
	0							

	8								
	Citation Number		69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	397956		69A-58.00 81 (11)(d)	(10)(i)4	00	0000	С		1205
2	434379	)	NA	(12)(d)2	4	103	М		
3	420291	L	NA	(9)(d)4	Р	9941	С	M-24	
4	420288	3	NA	(9)(d)4	Р	9942	С	M-23	
	0								

	4							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	403979	NA	(6)(b)	00	0000	М		
2	345450	NA	(2)(i)	00	9599	С		

	2							
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	258731	69A-58.00 5 (2)(a)7	(13)(x)4	00	0000	С		30
2	425493	NFPA 101, 9.11.1	NA	00	0000	М		509
3	377286	NFPA 101, 15.3.6	NA	1	0000	CS	First Floor Corridors	30:
4	377290	NFPA 101, 15.3.6	NA	1	0000	CS	Third Floor Corridors	30:
5	377292	NFPA 101, 15.3.6	NA	1	0000	CS	Second floor Corridors	303
6	425514	NA	(7)(c)3.1	1	8089	М		
7	408111	69A-58.00 5(2)(a)7.7	(16)(a)6a	2	090	os		808
8	408260	69A-58.00 81(11)(d)	(10)(i)4.3	4	101	С		120
9	408012	69A-58.00 5(2)(a)7.7	(16)(a)6a	6	190	OS		808
10	408262	NFPA 101, 7.1.10.1.A	NA	7	007	OS		210
11	408268	NFPA 101, 7.1.10.1.A	NA	7	010	OS		210
12	408274	NFPA 101, 7.1.10.1.A	NA	7	012	OS		210
13	408283	NA	(10)(b)	7	102	М		
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
14	337875	NA	(5)(a)	7	106	С		
15	408275	69A-58.00 81(11)(d)	(10)(i)4.3	7	117B	С		120
16	408129	69A-58.00 81(11)(d)	(10)(i)4.3	9	213	С		120

	8								
	Citation Number		69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	423459	9	NA	(2)(f)3	00	0000	С		
2	423452		69A-58.00 81(11)(d)	(10)(i)4.3	2	119	С		1205
	0			•	•	•	•	•	

ſ		2							
		Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
ľ	1	392089	NA	(3)(a)	1	0000	С		
٠		ı	•	1	ı	ı	1		
		0						•	

	1							
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	422545	NA	(3)(c)	00	0000	М		
2	422529	NA	(3)(a)	1	0000	М	Roof	
3	422530	NA	(2)(a)5	1	0000	М	Roof	
4	406594	NA	(10)(f)	1	264A	М		
5	392325	NA	(10)(f)	1	265A	М		
6	422591	NA	(16)(b)1.3	1	265A	М		
7	422528	NA	(3)(a)	2	0000	М	Roof	
8	406675	NA	(9)(a).4	2	0000	М	Roof	

9	406592	NA	(10)(f)	2	101A	М		
		INA				IVI		
10	406617	NFPA 101, 9.6.1.3	NA	2	127A	М		410
11	406618	NFPA 101, 9.6.1.3	NA	2	127A	М		410
12	422503	NFPA 101, 7.9.2.4	NA	2	139	М		206
13	422483	NFPA 70, 110.3(B)	(17)(b)	2	162	М		899
14	422571	NA	(10)(f)	2	201A	М		
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
15	392301	NA	(10)(f)	2	202A	М		
16	392303	NA	(9)(a)	2	202A	М		
17	392264	NA	(10)(f)	2	301A	М		
18	422549	NA	(9)(a).4	2	Stair B	М		
19	422526	NA	(2)(a)5	3	0000	M		
20	406671	NA	(9)(a).4	3	0000	М	Roof	
21	422514	NA	(16)(a)2.4	3	111	М		
22	422607	NA	(10)(i)5	3	371A	М		
23	406596	NA	(10)(f)	3	371A	М		
24	422497	NA	(2)(a)5	4	0000	М		
25	422495	NFPA 101, 9.6.1.3	NA	4	102	М		410
26	422638	NA	(3)(c)	5	0000	М		
27	422501	NFPA 101, 7.9.2.4	NA	6	0000	М		206
28	422500	NA	(7)(c)3	Р	9792	М		
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
29	422499	NA	(7)(c)3	P	9793	М		

2	29							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	422200	NFPA 101, 9.11.1	NA	1	0000	М		509
	0							

	1							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	345323	NA	(5)(a)	00	0000	С	Buildings 4,5, and 6 Exterior Stairs	
2	353888	NA	(2)(a)8	00	0000	С		
3	430613	NFPA 101, 9.11.1.A	NA	00	0000	М		
4	430799	NA	(16)(b)1.1	10	0000	М		
5	398264	NA	(16)(a)3	2	290	М		
6	353770	NFPA 664, 8.2.2.1.4	(13)(q)7	3	107	С		699
7	430929	NA	(16)(b)1.1	4	307	М		
8	430772	NA	(11)(e)	5	108C	М		
9	430731	NA	(16)(a)3	6	190	М		
10	430655	NA	(7)(c)	7	005	М		

Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	357200	NA	(2)(f)(7)b	00	0000	С		
2	392721	N/A	(5)(a)	00	0000	С		
3	423002	NFPA 101, 9.11.1.A	NA	00	0000	M		
4	423067	NFPA 101, 7.1.10.1.A	NA	1	130	OS		210
5	423062	NFPA 101, 7.1.10.1.A	NA	1	131	OS		210
6	423017	NA	(15)(a)	2	170	М		
7	423094	NA	(16)(a)2.2	2	180	М		
8	423113	NA	(8)(a).5	3	108	М		
9	423115	NA	(16)(a)3	3	109A	М		
10	423118	NA	(8)(a).5	3	114	М		
11	423140	NA	(16)(a)2.4	4	0000	М		
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
12	392611	NA	(16)(a)3	4	291	С		
13	423104	NA	(16)(a)3	5	190	M		

	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1		NFPA 101, 9.11.1.A	NA	00	0000	М		
2	431981	NA	(1)(e)3.1	1	193	М		
3	432097	NA	(16)(a)3	12	0000	М	Chiller Compound	
4	335132	NA	(2)(i)	Р	0000	С		
	0							

69A-58.008 TYPE ROOM Row Citation SREF BLDG ROOM CODE DESCRIPTION Number Chapter 5 1 352338 NA (5)(a) 00 0000 С 2 422829 69A-58.00 (10)(i)4.3 2 113 С 1205 81(11)(d) 3 422818 69A-58.00 2 119 1205 (10)(i)4.3 С 81(11)(d) 69A-58.00 4 409382 (10)(i)4.3 2 207 С 1205 81(11)(d) 5 409383 69A-58.00 (10)(i)4.3 2 208 С 1205 81(11)(d) 6 422862 69A-58.00 2 209 С 1205 (10)(i)4.3 81(11)(d) (10)(i)4.3 7 422845 69A-58.00 2 225 С 1205 81(11)(d) 8 409349 2 233 С 1205 69A-58.00 (10)(i)4.3 81(11)(d) 9 422853 NA (10)(h).1 2 235 Μ 10 409354 (10)(i)4.3 2 238 С 1205 69A-58.00 81(11)(d)

Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
			·					
								Total
								Total
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	.427526	NA	(2)(k)4	00	9599	M		
2	427483	NA	(16)(a)2.4	2	114	M		
3	427507	NA	(16)(a)2.4	2	222A	М		
	427505	NA	(16)(a)2.4	2	224A	М		
	0	1			<u> </u>			

	4							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	357799	NA	(2)(f)(7)b	00	0000	С		
2	429228	NA	(17)(b).4	11	114	М		899
3	429096	NFPA 70, 110.3(B)	(17)(b)	11	127	М		899
4	429085	NA	(16)(a)3	14	190	М		
5	429279	NFPA 101, 4.5.8.A	(10) (a)10a.1	16	009	М		299
6	429141	NFPA 101, 4.5.8.H	(8)(a)	16	009	М		299
7	429142	NA	(8)(a).1	16	009	М		
8	412743	69A-58.00 81(11)(d)	(10)(i)4.3	16	103	С		1205
9	429143	NFPA 101, 15.7.4.3	(12)(a).1	16	107	0		1203
10	429240	NA	(12)(d)2	16	116	М		
11	412761	69A-58.00 81(11)(d)	(10)(i)4.3	16	201	С		1205
12	412758	69A-58.00 81(11)(d)	(10)(i)4.3	16	202	С		1205
13	412756	69A-58.00 81(11)(d)	(10)(i)4.3	16	206	С		1205
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
14	412754	69A-58.00 81(11)(d)	(10)(i)4.3	16	210	С		1205
15	412753	69A-58.00 81(11)(d)	(10)(i)4.3	16	216	С		1205
16	412750	69A-58.00 81(11)(d)	(10)(i)4.3	16	217	С		1205
17	412751	69A-58.00 81(11)(d)	(10)(i)4.3	16	219	С		1205
18	429282	69A-58.00 5(2)(a)7.7	(16)(a)6a	16	292	OS		808
19	429242	NA	(17)(b).4	2	109A	М		899

20	429125	NA	(9)(a).4	3	101	М		
21	429112	NA	(16)(a)2.4	3	123A	М		
22	429111	NFPA 70, 110.3(B)	(17)(b)	3	126	М		899
23	429138	NA	(8)(a).5	5	101	М		
24	429144	NFPA 70, 408.4	NA	5	109	М		802
25	429268	69A-58.00 81(1)(e)	NA	5	124	0		299
26	429262	NA	(16)(a)2.4	6	114A	M		
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
27	429152	NA	(16)(a)2.2	7	105	М		
28	429059	NA	(16)(a)2.4	8	112A	М		
29	429073	NA	(16)(a)2.4	8	113A	М		
30	429070	NA	(16)(a)2.2	8	115	М		
31	429076	NA	(16)(a)2.4	8	118A	М		
32	429075	NA	(16)(a)2.4	8	119A	М		
33	429072	NA	(9)(a)	9	102A	М		

3	33							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	l .	ROOM DESCRIPTION	CODE
1	391245	NA	(2)(k)4	00	0000	М		
2	1	NFPA 101, 9.11.1	NA	00	0000	М		509
3	405602	NA	(7)(c)3	1	0000	М		

4	345178	69A-58.00 81 (11)(d)	(10)(i)4	1	0000	С		1205
5	435814	NA	(8)(a).5	1	100B	М		
6	435821	NA	(16)(a)2.2	1	121A	М		
7	435788	NA	(8)(a).8	1	145A	М		
8	435832	69A-58.00 81(16)(a).1	(16)(a)2	1	166D	М		999
9	435960	NA	(16)(a)2.2	1	195A	М		
10	420521	NA	(16)(a)2.4	1	196A	М		
11	435802	NA	(8)(a).5	2	113A	М		
12	435842	NA	(16)(a)2.2	Р	6055	М	P-2	
13	435847	NA	(12)(d)2	Р	6056	М	P-3	
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE

							Total Total
Row Citation Number	69A-58.008	SREF Chapter 5				ROOM DESCRIPTION	CODE
2 422715	NFPA 101, 10.3.1.D	(2)(a)8	00	0000 146F	C		303
3 422751	NA	(16)(a)3	1	291	М		

	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1		NFPA 101, 9.11.1.A	NA	00	0000	М		
2	419576	NA	(5)(a)	2	0000	С		
	0							<u> </u>

	2							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	392958	NA	(16)(a)3	1	195	М		
	0							

	1							
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	431759	NFPA 101, 9.11.1.A	NA	00	0000	М		
2	417513	NA	(16)(a)2.4	1	121	М		
3	431619	69A-58.00 81(20)	NA	1	141	М		299
4	417213	NA	(16)(a)2.4	1	164	М		
5	417210	NA	(16)(a)2.4	1	165	М		
6	417177	NA	(16)(a)2.4	1	167	М		
7	417209	NA	(16)(a)2.4	1	168	М		
8	417176	NA	(16)(a)2.4	1	169	М		
9	431631	NA	(16)(a)2.4	1	170	М		
10	417174	NA	(16)(a)2.4	1	171	М		
11	417163	NA	(16)(a)2.4	1	173	М		
12	431608	NA	(16)(a)2.2	1	185	М		

13	400050	NA	(11)(e)	1	186	С		
14	431642	NA	(9)(a).4	3	0000	М		
15	431654	NFPA 101, 7.10.5.2.1	(10)(i)6	3	0000	М		202
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
								Total
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	378449	NA	(2)(i)	00	0000	С		

	2 431194	1 NA	(16)(a)3	1	291	М	
l							
ſ	0						

	2							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	425690	NFPA 101, 9.11.1	NA	00	0000	М		509
2	382700	NA	(16)(b)1	11	0000	М	Exterior Chiller Area	
3	382525	NA	(17)(a)1	2	131	М		
4	426367	NFPA 1, 13.4.8	NA	2	193	М		513
5	409131	NA	(1)(f)	7	101	С		

	5							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	431303	69A-58.00 4(2)(a)	NA	00	0	0		1299
2	431312	NFPA 101, 9.11.1.A	NA	00	0000	М		
3	431330	69A-58.00 81(11)(d)	(10)(i)4.3	00	0000	С		1205
4	431406	NFPA 101, 4.5.8	(10)(a)10a	00	0000	М		299
5	431432	. NA	(7)(c)3	00	0000	М		
6	431304	NFPA 101, 9.6.1.3	NA	1	101A	М		410

7	431530	NFPA 101, 9.6.1.3	NA	11	101	М		410
8	431531	NA	(7)(c)	11	101	М		
9	431542	NA	(10)(b)	12	0000	0		
10	431537	NFPA 101, 7.1.10.1.A	NA	12	004	OS		210
11	431533	NFPA 101, 9.6.1.3	NA	12	016	М		410
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
12	431541	69A-58.00 81(15)(c)	(10)(a)4	12	181	OS		210
13	431588	NA	(16)(a)3	12	204	М		
14	431539	NA	(16)(a)3	12	290	М		
15	431524	NA	(16)(a)2.4	15	103	М		
16	431522	NA	(16)(a)2.4	15	104	М		
17	414935	69A-58.00 81(11)(d)	(10)(i)4.3	2	118	С		1205
18	414853	NA	(16)(b)1.1	2	293	М		
19	431573	69A-58.00 5(2)(a)7.9	(17)(b)2c	2	294	os		808
20	431564	NA	(16)(a)2.4	3	202	М		
21	431325	NA	(16)(a)3	4	191	М		
22	431565	NFPA 101, 4.5.8	(10)(a)10a	5	0000	М		299
23	431438	69A-58.00 81(9)(c)	(8)(a).9	5	105	М		210
24	431443	NA	(16)(a)3	5	127	0		
25	431355	69A-58.00 81(9)(c)	(8)(a).9	5	131	М		210
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
26	431353	NA	(12)(d)2	5	132	М		
27	431426	69A-58.00 5(2)(a)7.7	(16)(a)6a	5	196	os		808
28	431393	NA	(16)(a)2.4	5	209	М		

29	431554	NA	(16)(a)3	5	296	М	
30	431442	NFPA 101, 4.6.12.1	(9)(a).1	6	0000	М	304
31	431388	NA	(16)(a)3	6	101	М	
32	431379	NA	(17)(a).1	6	105A	0	
33	414901	NA	(16)(b)1.1	6	195	М	
34	431461	NA	(12)(d)2	7	104	М	
35	431504	69A-58.00 5(2)(b)1.1	NA	7	183	М	410
36	414800	NFPA 101, 9.7.5.A	NA	8	191	М	
37	355440	NA	(2)(a)8	Р	0000	С	
	4	•	•		•		

3	33								
	Citation Number	69A-		SREF hapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	434932	2 NA	(2)(k)4	4	00	0000	М		
2	434942	2 NA	(16)(a	.)3	00	0000	М	Chiller Yard	
3	434943	B NA	(5)(a)		00	0000	М	Chiller Yard	
4	435156	NFPA 4.5.8. <i>A</i>		a)10a.1	1	006	М		299
5	435260	) NA	(3)(a)		4	009	М		
6	419174	1 NA	(9)(d)		Р	6040	М	50-104	
7	435154	1 NA	(9)(d)		Р	6041	М	50-105	
	0		•		•	•	•		

		Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	1	ROOM DESCRIPTION	CODE
	1	338052	NA	(14)(b)3a	00	0000	С		
ĺ	2	404337	NA	(7)(c)3	00	0000	М		
Γ		0							

2 69A-58.008 BLDG ROOM TYPE ROOM CODE Row Citation SREF Number Chapter 5 DESCRIPTION 1 429580 NFPA 101, 191 NA 10 Μ 9.11.1.A 0

 1

 Row Citation Number
 69A-58.008 Chapter 5
 SREF Chapter 5
 BLDG ROOM DESCRIPTION
 TYPE ROOM DESCRIPTION
 CODE DESCRIPTION

 1 420798
 NA
 (16)(a)3
 00 0000
 M
 M

	1							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	423336	NA	(16)(a)2.4	8	807A	М		
	0					•		

1						
Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	ROOM DESCRIPTION	CODE

1	434149	NA	(2)(a)9	00	0000	М	
2	434214	NA	(16)(a)3	1	191	М	
3	353120	69A-58.00 83(6)(a)	(13)(p)9	1	209	С	699
4	325593	NA	(2)(i)	3	004	С	
5	434207	69A-58.00 5(2)(a)7.6	(13)(x)4.4	4	002	0	302
6	434208	NFPA 70, 400.3	(17)(b)1e.2	4	002	0	803
7	232690	NFPA 101, 13.2.5.6.6( 6)	NA	4	102	С	299
8	434206	NA	(9)(d)	4	106	М	
9	434247	NFPA 101, 7.1.10.1.A	NA	5	107	OS	210
10	434250	69A-58.00 81(7).3	NA	6	003	OS	211
	2	<b>'</b>	<b>'</b>		1		<b>'</b>

	8							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	427231	NFPA 101, 9.11.1.A	NA	00	0000	М		
2	427240	NA	(16)(a)3	1	199	М		
3	427236	NA	(10)(h).1	Р	9158	М	P-4	
	0							

	3							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	428932	NA	(17)(a)1.1	00	0000	М		

2		NFPA 101, 9.11.1.A	NA	00	0000	М	
3		NFPA 13, 8.1.1 (1)	NA	1	107	С	520
4	397125	NFPA 13, 8.1.1 (1)	NA	12	190	С	520
5	397136	NFPA 13, 8.1.1 (1)	NA	12	290	С	520
6	397105	NA	(8)(a)	2	203	М	
	0						

	6							
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	428643	NA	(4)	00	0000	М		
2	402684	NA	(1)d	00	0000	М		
3	402666	NA	(16)(a)2	1	103A	М		
4	402667	NA	(16)(a)2	1	103B	М		
5	416455	69A-58.00 81(7).1	(8)(c)1.1	1	107A	MS		699
6	402680	NA	(16)(a)2	1	109M	М		
7	402679	NA	(16)(a)2	1	109P	М		
8	428793	NA	(16)(a)2.2	1	113	М		
9	428824	NA	(16)(a)2.4	1	124	М		
10	428825	NA	(16)(a)2.4	1	125	М		
11	416456	69A-58.00 81(11)(d)	(10)(i)4.3	1	130	С		1205
12	402682	NA	(16)(a)2	1	153	М		
13	428613	NA	(16)(a)2.4	1	158A	М		
14	428612	NA	(16)(a)2.4	1	158C	М		
15	428611	NA	(16)(a)2.2	1	182	М		

	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
16	428610	NA	(16)(a)2.2	1	184	М		
17	416527	69A-58.00 81(11)(d)	(10)(i)4.3	3	118	С		1205
18	416531	69A-58.00 81(11)(d)	(10)(i)4.3	3	122	С		1205
19	402823	69A-58.00 81 (11)(d)	(10)(i)4	3	125	С		1205
20	428630	NFPA 101, 9.11.1.A	NA	3	180	М		
21	402835	NA	(16)(a)2	3	214	М		
22	402836	NA	(16)(a)2	3	216	М		
	1							

2	21							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	434785	NFPA 1, 10.11.1.1.	NA	00	0000	М		1308
		Α						
	0							

	1							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	190809	NFPA 70, 700.16	NA	00	0000	С		299
2	429798	NA	(16)(a)2.4	2	219	М		
3	429795	NA	(16)(a)2.4	2	222C	М		
4	395981	NA	(16)(a)2	2	223C	М		
5	395972	NA	(16)(a)2	2	224C	М		
6	429794	NA	(16)(a)2.4	2	232C	М		

7 416692	NA	(16)(a)2.4	2	234C	М	
0		,				

,	7							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	431665	NA	(16)(a)2.2	4	409C	М		
2	431675	NA	(16)(a)2.2	4	414C	М		
	0							

	2								
	Citation Number		69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	255411	L	NA	(2)(i)	00	0000	С		
2	190959	9	NFPA 101, 7.2.2.4.4.2	(13)(a)	1	299	С		299
3	275166	3	69A-58.00 4 (2)(a)	N/A	11	0000	N/A		
4	416657	7	69A-58.00 81(11)(d)	(10)(i)4.3	2	0000	С		1205
5	255459	9	NFPA 101, 7.2.2.4.1.1	NA	5	299	С	Stairs	299
6	275161	L	69A-58.00 4 (2)(a)	N/A	6	0000	N/A		
	0								

	4							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	l .	ROOM DESCRIPTION	CODE
1		69A-58.00 81(11)(d)	(10)(i)4.3	1	124	С		1205
2		69A-58.00 81(11)(d)	(10)(i)4.3	1	143	С		1205

	2							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	436880	NFPA 101, 9.11.1.A	NA	1	0000	М		
2	436983	B NA	(16)(a)2.4	1	0000	М		
3	436954	NA NA	(16)(a)2.4	1	106E	М		
4	436881	. NA	(12)(d)2	1	109	М		
5	420606	NA NA	(12)(d)2	1	147	М		
6	361709	) NA	(2)(i)	Р	0000	С		
		•	•	·		•		•

	6							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	l	NFPA 101, 9.11.1.A	NA	00	0000	М		
2	l	69A-58.00 81 (11)(d)	(10)(i)4	1	0000	С		1205

2							
	Citation Iumber	69A-58.008	SREF Chapter 5	BLDG	ROOM	ROOM DESCRIPTION	CODE

1	364234	NA	(2)(i)	00	0000	С	
2	364240	NA	(2)(i)	00	0000	С	
_	00.2.0						
3	428698	NA	(1)(e)3.1	1	0000	М	
4	428677	NA	(16)(a)2.4	1	002A	М	
5	428678	NA	(16)(a)2.4	1	002B	М	
6	428700	NA	(16)(b)1.1	1	005	М	
7	428719	NA	(16)(a)2.2	1	119G	М	
8	428676	NA	(16)(a)2.4	1	133B	М	
9	395637	NA	(5)(a)	1	199E	М	
10	428672	NA	(16)(a)2.2	2	102	М	
11	428673	NA	(16)(a)2.2	2	108	М	
	0						

	L1							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	372198	69A-58.00 6	NA	00	0000	N/A		
2	260798	69A-58.00 4 (2)(a)	N/A	1	0000	N/A		
3	260799	69A-58.00 4 (2)(a)	NA	2	0000	N/A		
	0	•	•	•	•		•	•

	0						
Rov	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	ROOM DESCRIPTION	CODE

	1 433157	NFPA 101, 9.11.1	NA	00	0000	М	509
	2416024	NEDA 45	(12)(a)6	1	0000		000
	2 416034	NFPA 45, 11.2.3.4	(13)(q)6	1	0000	С	899
	3 383152	NA	(7)(c)3	1	0000	М	
	4 415956	69A-58.00 81(11)(d)	(10)(i)4.3	1	0000	С	1205
	5 416030	69A-58.00 83(6)(a)	(13)(p)9	1	144	M	699
	6 415959	NA	(16)(a)2.4	1	146A	М	
	7 432739	NA	(16)(a)2.2	1	164C	М	
	8 416041	NA	(16)(a)2.4	1	185B	М	
	9 416040	NA	(16)(a)2.4	1	185C	М	
1	0 383426	NA	(16)(a)2	1	197A	М	
1	1 399985	NA	(16)(a)2	1	197B	М	
	0						 

1	L1							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	433614	NFPA 101, 9.11.1.A	NA	2	213	М		
2	433592	2 NA	(16)(a)2.4	2	216A	М		
3	393695	5 NA	(16)(a)2	2	216B	М		
4	433611	L NA	(16)(a)2.4	6	0000	М		
5	393699	) NA	(16)(a)2	8	0000	М		
6	433612	2 NA	(16)(a)2.4	8	806A	М		
7	433613	3 NA	(16)(a)2.4	8	811A	М		
8	421118	3 NA	(16)(a)2.4	8	812A	М		
	0							

	8							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	427674	NA	(9)(d)	5	109	М		
	0							

	1							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	435299	NFPA 101, 9.11.1.A	NA	00	0000	М		
2	435176	NA	(2)(f)1	00	0000	С		
	0	•			•	•		

	2							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	436409	NA	(16)(a)3	00	0000	М	Chiller Compound	
2	436410	NA NA	(16)(a)3	00	0000	М	Chiller Compound	
3	436414	NFPA 101, 9.11.1.A	NA	00	0000	М		
4	436477	NA	(5)(a)	00	0000	М		
5	436480	NA	(10)(b)	00	0000	0		
6	436510	NA NA	(2)(a)7	00	0000	0		
7	436489	NA	(9)(d).1	1	004	М		

8	436405	NFPA 101, 9.6.1.3	NA	1	101	М		410
9	436473	NA	(8)(a).5	1	101H	М		
10	419957	NFPA 101, 10.3.1.D	NA	1	109C	М		303
11	436481	69A-58.00 5(2)(a)7.7	(16)(a)6a	1	198	OS		808
	0	204 50 200	0055		2001	T) (DE	2001	0005
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
12	436465	NA	(2)(a)8	2	0000	М		
13	436508	NA	(16)(a)2.4	3	205A	М		
14	436438	NA	(2)(i).1	Р	0000	М		
15	322345	NA	(2)(a)8	P	0000	С		
16	436416	NFPA 101, 15.7.4.3	(12)(a).1	P	9144	0	P-30	1203
17	436441	NA	(16)(b)1.1	P	9801	M	В	
	1							

	16							
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	426930	NA	(2)(f)10b.1	00	0000	С		
2	426931	NFPA 101, 9.11.1.A	NA	00	0000	М		
3	422107	NA	(5)(a)	00	0000	М		
4	427136	69A-58.00 81(11)(d)	(10)(i)4.3	2	105	С		1205

5	394338	NFPA 13, 8.6.4.1.1	NA	2	280	М		599
6	427035	69A-58.00 81(7).3	NA	3	0000	OS		211
7	427059	NFPA 101, 7.1.10.1.A	NA	3	009	os		210
8	427056	69A-58.00 5(2)(a)7.4	(13)(x)4.1	3	103G	OS		302
9	426946	NA	(8)(a).5	3	108	М		
10	427058	NA	(16)(a)3	3	195	М		
11	426934	NA	(16)(a)2.2	3	199A	М		
12	427038	69A-58.00 81(7).3	NA	4	0000	OS		211
Row	Citation	69A-58.008	SREF	BLDG	ROOM	TYPE	ROOM	CODE
	Number		Chapter 5				DESCRIPTION	
13	427070	NA	(3)(a)	4	001B	М		
14	427075	NA	(3)(a)	4	001B	М		
15	427076	NFPA 101, 4.5.8.A	(10) (a)10a.1	4	001B	М		299
16	427040	NFPA 101, 4.5.8.A	(10) (a)10a.1	4	002B	М		299
17	427041	NFPA 101, 4.5.8.A	(10) (a)10a.1	4	002B	М		299
18	426937	NA	(16)(a)2.4	4	104	М		
19	427043	NA	(12)(d)2	4	112	М		
20	427089	NFPA 70, 110.3(B)	(17)(b)	4	392	М		899
21	394400	NA	(2)(a)9	5	0000	М		
22	426970	69A-58.00 81(11)(d)	(10)(i)4.3	5	101A	C		1205
23	427061	69A-58.00 81(11)(d)	(10)(i)4.3	5	107	С		1205
24	427060	69A-58.00 81(11)(d)	(10)(i)4.3	5	108	С		1205
25	427183	69A-58.00 5(2)(a)7.4	(13)(x)4.1	52	101	OS		302

	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
26	410821	L NA	(3)(a)	6	0000	M		
27	427100	NFPA 101, 4.5.8.A	(10) (a)10a.1	6	001B	M		299
28	427122	2 NA	(16)(a)2.4	6	104	М		
29	427123	B NA	(16)(a)2.4	6	104A	М		
30	426963	NFPA 101, 7.1.10.1.A	NA	6	109	os		210
31	427096	69A-58.00 81(11)(d)	(10)(i)4.3	6	202B	С		1205
32	427133	NFPA 101, 7.1.10.1.A	NA	7	0000	os		210
33	427134	69A-58.00 81(8).1	(8)(c)3	7	004	os		209
	8	I .	L	I	1	ı	I	L

2	25							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	426900	NFPA 101, 9.11.1.A	NA	00	0000	М		
2	427010	NA	(5)(a)	5	101	М		

	2							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	423770	69A-58.00 81(11)(d)	(10)(i)4.3	1	107N	С		1205
2	423772	69A-58.00 81(11)(d)	(10)(i)4.3	1	119	С		1205

3	423751	69A-58.00 81(11)(d)	(10)(i)4.3	1	213	С	1205
4	396232	NA	(2)(i)	Р	0000	С	
	0						

4 Row Citation Number SREF Chapter 5 TYPE ROOM DESCRIPTION 69A-58.008 BLDG ROOM CODE NFPA 101, NA 0000 1 429055 00 Μ 9.11.1.A 2 419748 NA (16)(a)3 1 0000 Μ Chiller Compound 3 429180 NΑ (12)(d)2 144 1 М 4 419735 NA (16)(b)1.1 1 192C Μ 0

	4							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	436737	NFPA 101, 9.11.1.A	NA	00	0000	М		
	0					•		

1								
Row Citation Number		69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1 41467	9	NA	(16)(a)	1	187A	С		
n								

	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	428452	NA	(17)(a).1	00	0000	M		
2	428490	NFPA 101, 9.11.1.A	NA	00	0000	M		
3	290306	69A-58.00 5 (2)(a)4	NA	1	0000	С		201
4	395299	69A-58.00 81 (11)(d)	(10)(i)4	1	111	С		1205
5	413869	69A-58.00 81(11)(d)	(10)(i)4.3	1	114	С		1205
6	395327	69A-58.00 81 (11)(d)	(10)(i)4	1	118	С		1205
7	413871	69A-58.00 81(11)(d)	(10)(i)4.3	1	120	С		1205
8	428264	69A-58.00 81(11)(d)	(10)(i)4.3	1	208	С		1205
9	428014	69A-58.00 81(11)(d)	(10)(i)4.3	1	209	С		1205
10	428016	69A-58.00 81(9)(c)	(8)(a).9	1	213	М		210
11	428332	69A-58.00 81(11)(d)	(10)(i)4.3	1	216	С		1205
12	428020	NA	(16)(a)2.2	1	227	М		
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
13	379804	NA	(7)(c)	1	227	М		
14	428314	69A-58.00 81(11)(d)	(10)(i)4.3	1	236	С		1205
15	290307	69A-58.00 5 (2)(a)4	NA	2	0000	С		201
16	427987	NFPA 101, 9.6.1.3	NA	2	104	М		410
17	395313	69A-58.00 81 (11)(d)	(10)(i)4	3	132	С		1205
18	428454	NA	(16)(a)2.2	4	100A	М		

19	428462	69A-58.00 81(11)(d)	(10)(i)4.3	4	104	С		1205
20	428457	NA	(16)(a)2.4	4	105	М		
21	428456	NA	(16)(a)2.4	4	106	М		
22	395366	NA	(16)(a)2	4	121	М		
23	344263	NA	(15)(a)	52	0000	М	Pressbox	
24	413448	NA	(11)(e).1	6	103	М		
	0	-	•		•			

2	24							
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	375158	B NA	(7)(c)3	00	0000	С		
2	417088	8 69A-58.00 81(11)(d)	(10)(i)4.3	1	0000	С		1205
3	417149	) NA	(3)(c)	1	0000	М		
4	436858	B NA	(8)(a).5	1	132A	М		
5	436832	NFPA 101, 13.2.5.4.2	NA	1	191	М		210
6	436822	NFPA 101, 9.11.1	NA	1	198C	М		509
	0	•	<u>'</u>	L	•		•	

6							
Row Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1 420326	NFPA 13, 8.1.1 (1)	NA	1	181	С		520
n l							

	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	260883	69A-58.00 4 (2)(a)	N/A	1	0000	N/A		
2	260892	69A-58.00 4 (2)(a)	N/A	10	0000	N/A		
3	260893	69A-58.00 4 (2)(a)	N/A	11	0000	N/A		
4	260894	69A-58.00 4 (2)(a)	NA	12	0000	N/A		
5	260895	69A-58.00 4 (2)(a)	NA	13	0000	N/A		
6	260896	69A-58.00 4 (2)(a)	NA	14	0000	N/A		
7	260897	69A-58.00 4 (2)(a)	NA	15	0000	N/A		
8	260884	69A-58.00 4 (2)(a)	N/A	2	0000	N/A		
9	260885	69A-58.00 4 (2)(a)	NA	3	0000	N/A		
10	260886	69A-58.00 4 (2)(a)	N/A	4	0000	N/A		
11	260887	69A-58.00 4 (2)(a)	N/A	5	0000	N/A		
12	260888	69A-58.00 4 (2)(a)	NA	6	0000	N/A		
13	260889	69A-58.00 4 (2)(a)	NA	7	0000	N/A		
1	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
14	260890	69A-58.00 4 (2)(a)	NA	8	0000	N/A		
15	260891	69A-58.00 4 (2)(a)	NA	9	0000	N/A		
16	260923	69A-58.00 4 (2)(a)	NA	Р	1160	N/A	P-9	
17	260914	69A-58.00 4 (2)(a)	NA	Р	1161	N/A	P-13	
18	260926	69A-58.00 4 (2)(a)	NA	Р	1162	N/A	P-12	
19	260909	69A-58.00 4 (2)(a)	NA	Р	1163	N/A	P-7	
20	260912	69A-58.00 4 (2)(a)	NA	Р	1164	N/A	P-8	

21	260911	69A-58.00	NA	Р	1165	N/A	P-11	
22	260928	4 (2)(a) 69A-58.00	NA	P	1166	N/A	P-10	
		4 (2)(a)						
23	260924	69A-58.00 4 (2)(a)	N/A	Р	1462	N/A	P-19	
24	260921	69A-58.00 4 (2)(a)	NA	Р	1463	N/A	P-21	
25	260918	69A-58.00 4 (2)(a)	NA	Р	1464	N/A	P-20	
26	260915	69A-58.00 4 (2)(a)	N/A	Р	1518	N/A	P-18	
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
27	263651	69A-58.00 4 (2)(a)	N/A	Р	2392	N/A	P-16	
28	260913	69A-58.00 4 (2)(a)	N/A	Р	2417	N/A	P-17	
29	260907	69A-58.00 4 (2)(a)	NA	Р	3671	N/A	P-27	
30	263264	69A-58.00 4 (2)(a)	NA	Р	4075	N/A	P-22	
31	260906	69A-58.00 4 (2)(a)	NA	Р	4146	N/A	P-26	
32	260925	69A-58.00 4 (2)(a)	N/A	Р	453	N/A	P-1	
33	260917	69A-58.00 4 (2)(a)	NA	Р	454	N/A	P-2	
34	263309	69A-58.00 4(2)(a)	NA	Р	455	N/A	P-3	
35	260908	69A-58.00 4 (2)(a)	NA	Р	4786	N/A	P-23	
36	260927	69A-58.00 4 (2)(a)	N/A	Р	4823	N/A	P-15	
37	260922	69A-58.00 4 (2)(a)	N/A	Р	490	N/A	P-4	
38	263307	69A-58.00 4 (2)(a)	NA	Р	494	N/A	P-6	
39	260916	69A-58.00 4 (2)(a)	N/A	Р	495	N/A	P-5	
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
40	260904	69A-58.00 4 (2)(a)	NA	Р	5474	N/A	P-25	

41	260903	69A-58.00 4 (2)(a)	NA	Р	587	N/A	P-24	
(	o							

	0								
	Citation Number		69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	387517	7 N	IA	(2)(i)	00	0000	С		
2	427537	7 N	IA	(16)(a)3	1	199C	М		
3	410359	9 N	IA	(8)(a).1	1	199D	М		
4	427530		9A-58.00 1(11)(d)	(10)(i)4.3	1	202	С		1205
5	427531		9A-58.00 1(11)(d)	(10)(i)4.3	1	203	С		1205
6	427529		9A-58.00 1(11)(d)	(10)(i)4.3	1	206	С		1205
7	427528		9A-58.00 1(11)(d)	(10)(i)4.3	1	213	С		1205
8	8 427543		IA	(12)(d)2	Р	9869	М	P-5	
	0	,				•	•		

	8							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	431724	NA	(12)(d)2	1	149	М		
2	431727	NA	(12)(d)2	1	156	М		
3	431733	NFPA 101, 9.11.1.A	NA	1	160C	М		
	0			•		•		

;	3						
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	ROOM DESCRIPTION	CODE

1	348219	69A-58.00 81 (11)(d)	(10)(i)4	00	0000	С		1205
2	436089	NFPA 101, 10.3.1.A	NA	1	003	0	1-104	199
3	436164	NFPA 101, 10.3.1.D	NA	1	020B	М		303
4	436173	NA	(1)(e)8.b	1	031	0		
5	436186	NFPA 1, 11.1.4.2	(17)(b)1e.3	5	003	0	5-503	804
6	348335	NA	(2)(i)	Р	0000	С		
7	390641	NA	(10)(h)	P	3566	M	P-2	
8	436219	NFPA 101, 10.3.1.A	NA	Р	9372	0	P-C7	199
	0	ı	ı			L	ı	ı

г

\_

	8							
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	419882	NA	(16)(a)2.4	10	103A	М		
2	419652	NA	(16)(a)2.4	12	102B	М		
3	419653	NA	(16)(a)2.4	12	102D	М		
4	435452	NA	(16)(a)2.2	12	105A	М		
5	435448	NA	(16)(a)2.2	12	106	М		
6	419654	NA	(16)(a)2.4	12	107A	М		
7	419655	NA	(16)(a)2.4	12	107B	М		
8	435439	NA	(16)(a)2.2	12	110B	М		
9	435441	NA	(16)(a)2.2	12	110D	М		
10	435389	69A-58.00 81(16)(a).1	(16)(a)2	3	101B	М		999
11	419853	NA	(16)(a)2.4	3	103	М		
12	419866	NA	(16)(a)2.4	6	101A	М		
13	419877	NA	(16)(a)2.4	6	105A	М		

14	419876	NA	(16)(a)2.4	6	106A	М		
15	435431	NA	(16)(a)2.2	6	107A	М		
16	435432	NA	(16)(a)2.2	6	107B	М		
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
17	419873	NA	(16)(a)2.4	6	108A	М		
18	419872	NA	(16)(a)2.4	6	108B	М		
19	419870	NA	(16)(a)2.4	7	101A	М		
20	419871	NA	(16)(a)2.4	7	101B	М		
21	419868	NA	(16)(a)2.4	7	102A	М		
22	419869	NA	(16)(a)2.4	7	102B	М		
23	435406	NA	(16)(a)2.2	9	104A	М		
	0	•	•					•

2	23							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	431931	NA	(7)(c)3	00	0000	М		
2	421157	NA	(7)(c)3	1	0000	М		
3	421160	NFPA 13, 8.1.1 (1)	NA	1	190	С		520
4	421177	NA	(7)(c)3	2	0000	М		
5	431924	NA	(16)(a)3	9	0000	М	Chiller Enclosure	
6	431927	NA	(16)(a)3	9	190	М		
	0							

	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1		NFPA 101, 9.11.1.A	NA	00	0000	М		
2		NFPA 13, 8.1.1 (1)	NA	1	192B	С		520
3	396707	NA	(2)(i)	Р	0000	М		

	3								
Row	Citation Number		69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	424748	B	NA	(2)(a)9	00	9599	М		
2	424423	3	69A-58.00 81(11)(d)	(10)(i)4.3	1	0000	С		1205
3	424762	1	69A-58.00 81(11)(d)	(10)(i)4.3	50	110	С		1205
4	424772	2	69A-58.00 81(11)(d)	(10)(i)4.3	50	204	С		1205
5	424778	8	69A-58.00 81(11)(d)	(10)(i)4.3	50	205	С		1205
6	42477	7	69A-58.00 81(11)(d)	(10)(i)4.3	50	206	С		1205
	0								

	6							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1		NFPA 101, 9.11.1	NA	00	0000	М		509

	1								
Row	Citation Number		69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	417034	4	NFPA 101, 10.3.1.D	NA	4	102	М		303
2	433231	1	NA	(16)(b)1.1	4	193	М		
3	433234	4	NA	(16)(a)2.4	5	103	М		
4	433223	3	NA	(16)(a)2.4	5	106A	М		
5	433230	)	NA	(16)(b)10	5	190	М		
6	433191	1	NA	(16)(b)1.1	5	190	М		
7	401822	2	NA	(16)(a)2	6	101	М		
	0								

	7							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	426198	NFPA 101, 9.11.1.A	NA	00	0000	М		
2	409938	3 NA	(2)(i).1	00	9599	С		
3	426242	2 NA	(16)(a)2.2	4	105	М		
4	409968	B NA	(16)(a)2.2	5	180	М		
	0			•	•	'		

Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1		NFPA 101, 9.11.1.A	NA	00	0000	М		

	1								
	Citation Number		69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	381156	õ	NA	(13)(n)	00	0000	М		
2	429678	3	NA	(3)(c)	00	9599	М		
3	381296	5	NA	(16)(a)2	1	101B	М		
4	354220	)	NA	(8)(d)4	17	8087	М		
5	235237	7	NA	(14)(b)3a	Р	0000	С		
	0								

5							
Row Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1 363511	NA	(2)(a)8	00	0000	С		
2 376555	NA	(2)(a)8	00	0000	С		
0			•	•	•	_	

2	2						
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	ROOM DESCRIPTION	CODE

1	393318	69A-58.00 81 (11)(d)	(10)(i)4	00	0000	С		1205
2	422754	NA	(11)(e)	1	123	М		
3	422659	NA	(16)(a)2.4	1	205A	М		
4	422665	NA	(16)(a)2.2	1	280	М		
5	422661	NA	(16)(a)2.2	2	171	М		
6	393321	69A-58.00 81 (11)(d)	(10)(i)4	3	114	С		1205
7	422763	NA	(16)(a)2.2	3	180	М		
8	422795	NA	(2)(f)5.1	5	0000	М		
9	410673	NA	(8)(a).2	5	104	М		
10	410674	NFPA 70, 110.3(B)	(17)(b)	5	104	М		899
11	422778	NA	(8)(a).1	6	101	М		
12	422783	69A-58.00 81(8).3	NA	6	102	MS		209
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
13	393281	NA	(2)(i)	P	0000	M		
14	422765	NA	(9)(a).4	Р	9708	М	P-1	
	ı	NA	(9)(d).1	Р	9708	М	P-1	+

1	L4						
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	ROOM DESCRIPTION	CODE

1	435695	NFPA 101, 9.11.1.A	NA	00	0000	М		
2	435726	NFPA 70, 406.6	(17)(b).3	10	105	М		807
3	435706	NA	(16)(a)2.4	11	101A	М		
4	435707	NA	(16)(a)2.4	11	104C	М		
5	435713	NA	(16)(a)2.4	13	101A	М		
6	435714	NA	(8)(a).1	13	102	М		
7	435680	NA	(16)(a)2.4	3	112A	M		
8	435681	NA	(16)(a)2.4	3	112B	М		
9	435673	NA	(16)(a)2.4	3	114A	М		
10	435694	NA	(9)(a)	3	211	М		
11	435676	NA	(16)(a)2.4	3	213C	М		
12	435677	NA	(16)(a)2.4	3	216B	М		
13	435679	NA	(16)(a)2.4	3	216C	М		
14	418104	NA	(16)(a)3	4	190	М		
15	435700	NA	(16)(a)2.4	5	105C	М		
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
16	435701	NA	(16)(a)2.4	6	103C	М		
17	435730	NA	(16)(a)2.4	7	105C	М		
18	435708	NA	(16)(a)2.4	9	104	М		
19	435709	NA	(16)(a)2.4	9	105	М		
20	418143	NA	(16)(a)2.2	9	180	М		
	0	_1			I	ı	L	1

	20						
ı	Row Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	ROOM DESCRIPTION	CODE

1 424953	NFPA 101, 9.11.1.A	NA	00	0000	М	
0						

	1						,	
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	357579	69A-58.00 5 (2)(a)7	(13)(x)4	00	0000	CS		302
2	399233	NA	(1)(d)	00	0000	М		1399
3	399463	NA	(16)(b)1	13	190	М		
4	399464	NA	(16)(a)3	13	190	М		
5	424098	69A-58.00 81(9)(c)	(8)(a).9	15	204	MS		210

	3							
Row	Citation Number	69A-58.00	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	429930	) NA	(16)(a)2.4	1	157	М		
2	429931	l NA	(16)(a)2.4	1	158	М		
3	429927	' NA	(16)(a)2.2	1	184	М		
4	340457	' NA	(5)(a)	2	001	М	P.E. Pavillion	
5	429932	2 NA	(16)(a)2.4	3	106	М		
6	405910	) NA	(7)(c)3	4	0000	М		
	'n	•	•	•	•	•	•	

	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	241942	NA	(2)(i)	00	0000	С		
2	434711	NA	(3)(c)	00	0000	М		
3	434704	NFPA 1, 13.4.8	NA	10	002	М		513
4	434707	NA	(16)(a)2.4	3	319A	М		
5	434731	NA	(16)(a)2.4	4	402B	М		
6	434725	NA	(8)(a).1	7	705	М		
	0							

	6							
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	430565	NA	(12)(d)2	00	0000	М		
2	414513	NFPA 70, 700.16	NA	1	0000	С		299
3	430602	NFPA 101, 10.3.1.A	NA	1	0000	0		199
4	430753	NA	(16)(a)2.2	1	103B	М		
5	430754	NA	(16)(a)2.2	1	103C	М		
6	430582	69A-58.00 81(11)(d)	(10)(i)4.3	1	114	С		1205
7	384025	NA	(16)(a)2	1	122A	М		
8	430806	NA	(16)(a)2.2	1	159A	М		
9	414549	NA	(16)(a)2.4	1	159C	М		
10	430793	NA	(16)(a)2.2	1	169A	М		
11	430742	69A-58.00 81(7).3	NA	1	180	OS		211
12	430743	69A-58.00 81(7).3	NA	1	180	М		211

13	430802	NA	(16)(a)2.2	1	183	М		
14	430791	NA	(16)(a)2.2	1	184	М		
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
15	430600	NA	(16)(a)3	4	191	М		
16	430594	NA	(16)(a)2.2	5	180	М		
	1							

15 Row Citation 69A-58.008 SREF BLDG ROOM TYPE ROOM CODE Chapter 5 DESCRIPTION Number 1 430023 NA (2)(d)10 00 9698 Μ 2 430454 NA (16)(a)2.2 1 145 Μ 3 430455 NA 1 147 (16)(a)2.2 Μ 4 414137 162 69A-58.00 (10)(i)4.3 1 С 1205 81(11)(d) 5 430358 NA (16)(a)3 10 108A Μ 6 430359 184 NA (16)(a)2.2 10 Μ 7 399096 194 NΑ (16)(a)3 10 Μ 8 430394 Chiller Yard NA (5)(a) 11 0000 9 340273 NA (5)(a) 13 0000 С 10 414166 0000 NA (9)(d) 13 С 11 430019 NA (16)(a)2.2 182 М 12 430543 NFPA 101, (10) (a)10a.1 5 004 Μ 299 4.5.8.A 13 413942 69A-58.00 202 1205 (10)(i)4.3 5 С 81(11)(d) 14 413953 NA 6 003 (9)(a).4 Μ

Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
15	399028	NA	(16)(a)3	6	192	M		
16	430520	NA	(16)(a)2.2	7	114B	M		
17	430563	NA	(16)(a)2.2	7	206	М		
18	430384	NA	(16)(a)2.2	9	113B	М		
19	430386	NA	(16)(a)2.2	9	114B	М		
20	430009	NFPA 1, 13.4.8	NA	9	192	М		513
21	430513	NA	(12)(d)2	Р	9856	М	P-14	
	0	•						

21 Row Citation 69A-58.008 SREF BLDG ROOM TYPE ROOM CODE Number Chapter 5 DESCRIPTION 1 433025 NFPA 70, NA 115 802 1 Μ 408.4 2 433023 NA (16)(a)2.2 119 Μ 3 433022 NA 1 121 (16)(a)2.2 Μ 4 433021 123A NA (16)(a)2.4 1 Μ 5 433008 NA 213 (16)(a)2.4 Μ 6 433009 NA (16)(a)2.4 2 214 Μ 7 417128 NΑ 2 233 (9)(d)7 Μ 8 433015 3 301A NA Μ (16)(a)2.4 9 433014 NA 3 303A (16)(a)2.4 Μ 10 433010 NA 3 308 (16)(a)2.4 Μ 11 433011 NA (16)(a)2.4 3 309 Μ 12 433001 NA 191 (16)(a)2.2 6 Μ 0

1	2							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1		NFPA 101, 9.11.1.A	NA	00	0000	М		
2	437161	NA	(8)(a).5	6	182	М		
3	437162	NA	(8)(a).5	6	183	М		
	0	•	•		•	•	•	<u>.                                    </u>

	3								
	Citation Number		69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	400368		69A-58.00 81 (11)(d)	(10)(i)4	00	0000	С		1205
2	416170	0	NA	(16)(a)2.4	1	109	М		
3	41617	1	NA	(16)(a)2.4	1	109A	М		
4	432772	2	NA	(16)(a)2.4	2	207B	М		
5	432773	3	NA	(16)(a)2.4	2	207C	М		
6	416024	4	NA	(16)(a)2.2	4	204	М		
	0								

	6							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1		69A-58.00 81(17)(a)	NA	12	191	М		799
2		69A-58.00 81(20).2	NA	12	192	М		205

	3 426604	NA	(16)(a)3	6	199	М	
l							
ſ	0						

	3			1	<b></b>	1-,	I===:	
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	360759	NFPA 1, 10.19.7	(13)(x)4	00	0000	CS		302
2	424910	NA	(13)(n)	00	0000	М		
3	394847	NA	(2)(i)	1	0000	M		
4	425358	NA	(2)(i).1	1	0000	M		
5	425361	NFPA 101, 4.5.8.A	(10) (a)10a.1	1	0000	M		299
6	425369	69A-58.00 81(11)(d)	(10)(i)4.3	1	0000	С		1205
7	425200	69A-58.00 81(8).3	NA	1	011	MS		209
8	425385	NA	(11)(e)	10	194	М		
9	394660	NA	(16)(a)	12A	101	С		
10	425293	NA	(8)(a).5	13	190	М		
	425418	NA	(8)(a).1	14	0000	М		
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
12	424945	NFPA 70, 300.31	(17)(b).5	14	0000	M		809
13	424913	NA	(9)(a)	14	009	М		
14	425421	NA	(12)(b).1	14	117	М		

15	425426	NA	(11)(e)	14	183	М		
16	424915	NA	(8)(a).5	14	207	М		
17	425318	69A-58.00 81(20).2	NA	16	102	М		205
18	425317	NFPA 101, 7.9.2.4	NA	16	103	М		206
19	409170	NA	(9)(a).4	18	003	М		
20	409164	NA	(16)(a)3	18	190	M		
21	379162	NA	(8)(d)	2	006	M		
22	424964	NA	(8)(d)	2	006	M		
23	425016	NA	(9)(a)	2	104	М		
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
24	425034	NA	(9)(a).4	2	110	М		
25	425030	NA	(9)(a)	2	110C	М		
26	409652	69A-58.00 81(11)(d)	(10)(i)4.3	2	205	С		1205
27	424988	69A-58.00 81(11)(d)	(10)(i)4.3	2	210	С		1205
28	424974	NFPA 101, 7.10.5.2.1	(10)(i)6	2	214	М		202
29	394651	NFPA 13, 8.1.1 (1)	NA	2	318A	С		520
30	425294	NA	(9)(d)	3	001	М		
31	394612	NA	(16)(b)1	5	180	М		
32	425388	69A-58.00 81(11)(d)	(10)(i)4.3	6	0000	С		1205
33	394658	NFPA 13, 8.1.1 (1)	NA	6	001A	С		520

34	409647	69A-58.00 81(11)(d)	(10)(i)4.3	6	206	С		1205
35	424949	69A-58.00 81(8).3	NA	6	301	MS		209
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
36	425386	69A-58.00 81(11)(d)	(10)(i)4.3	8	0000	С		1205
37	394659	NA	(2)(i)	Р	0000	С		
	3							

34 69A-58.008 TYPE ROOM Row Citation SREF BLDG ROOM CODE DESCRIPTION Number Chapter 5 1 428372 NΑ (2)(f)3 00 0000 С 0000 2 428374 NΑ (10)(b) 00 Μ 3 428379 NA (16)(b)1.1 1 0000 Μ 4 428388 NFPA 101, 1 0000 299 (10)(a)8.1 Μ 4.5.8.B 5 428394 69A-58.00 1 192 MS 808 (16)(a)6a 5(2)(a)7.7 6 411950 1 210 NΑ (12)(d)2 M 7 428424 NA (16)(b)1.1 3 0000 Μ 8 428425 NA (16)(b)1.1 3 0000 Μ 9 428420 NA (16)(b)1.1 4 0000 M 10 428413 NA (8)(a).5 4 101 Μ 11 412217 NFPA 101, NA 4 101F 303 Μ 10.3.1.D Row Citation 69A-58.008 SREF BLDG ROOM TYPE ROOM CODE DESCRIPTION Number Chapter 5

							Total Total
							Total
	I	1					l
Row Citation	69A-58.008	SPEE	BLDG	IROOM	TTVDE	IROOM	CODE
Row Citation Number	33/1 30.000	SREF Chapter 5	BLDG	T.COIVI		ROOM DESCRIPTION	
1396180	) NA	(16)(a)3	5	192	М		
2 410212	NFPA 13, 8.1.1 (1)	NA	5	192	С		520
0				_			

	2							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	436638	NA	(8)(a).5	10	101C	М		

2	403768	NA	(5)(a)	11	0000	М	
3	436619	NA	(1)(e)3.1	11	0000	М	
4	436680	NA	(16)(a)2.4	5	0000	М	
5	436692	NA	(16)(a)2.4	5	0000	М	
	0						

5 Row Citation 69A-58.008 SREF BLDG ROOM TYPE ROOM CODE DESCRIPTION Number Chapter 5 1 335480 0000 С NA (14)(b)3a 00 2 436285 NA (16)(a)2.4 109C 2 Μ 3 405508 NΑ (16)(a)2 2 130C M 2 4 436301 NA (16)(a)2.4 134C Μ 5 405521 NA (5)(a) 3 112 Μ 6 411149 3 115 NA (16)(a)2.2 Μ 7 405519 NA (16)(a)2 4 0000 Μ 8 411113 NA 106A (16)(a)2.4 4 M 9 411132 109 NA (16)(a)3 4 Μ 10 436322 NFPA 101, (10)(i)6 4 118 Μ 202 7.10.5.2.1 11 436323 69A-58.00 NA Р 6332 V-8 204 Μ 81(20).1 0

11						
Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	ROOM DESCRIPTION	CODE

1	433588	NA	(16)(a)3	1	190	М	
2	416616	NA	(16)(a)2.2	2	127B	М	
3	391477	NA	(16)(a)2	2	180	М	
4	433574	NA	(16)(a)3	2	191	М	
5	433577	NA	(3)(c)	2	9599	М	
6	433543	NA	(16)(a)2.2	5	180	М	
7	433585	NA	(16)(a)2.2	6	101C	М	
	0						

	7							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	431964	NFPA 101, 9.11.1	NA	00	0000	М		509
	0							

1 Row Citation Number SREF Chapter 5 TYPE ROOM DESCRIPTION 69A-58.008 BLDG ROOM CODE (10)(i)4 1 388134 69A-58.00 00 0000 С 1205 81 (11)(d) 2 412993 (10)(b) 00 0000 С NA (8)(a) 3 3 388284 NA 307 Μ

3

307F

853C

Μ

Μ

(8)(a)

(9)(c)

4 399145

5 412971

NA

NA

6 235058	NA	(14)(b)3a	Р	0000	С	
0						

	6							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	433108	NA	(3)(c)	00	0000	М		
2	433109	NA	(2)(a)5	00	0000	М		
3	417905	NA	(16)(a)3	1	113	М		
4	417813	NA	(8)(a).5	2	208	М		
5	417919	NA	(16)(a)2.4	7	0000	М		
6	433092	NA	(8)(a).1	9	901	М		
7	417816	NA	(2)(i).1	Р	0000	С		
	0	ı	1	L	l		1	1

		7							
R		Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
	1	422326	NFPA 101, 13.2.11.1(	NA	5	202	М		299
1			1)	ı	•		•		
		0							

	1							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	l	NFPA 101, 9.11.1	NA	00	0000	M		509

2	417552	NFPA 13, 8.6.3.3	NA	1	162F	С		599
3	256742	69A-58.00 4 (2)(a)	NA	Р	6034	N/A	V-5	
4	256741	69A-58.00 4 (2)(a)	NA	Р	6035	N/A	V-4	
5	256740	69A-58.00 4 (2)(a)	NA	Р	6036	N/A	V-3	
6	256739	69A-58.00 4 (2)(a)	NA	Р	9773	N/A	V-2	
7	256745	69A-58.00 4 (2)(a)	NA	Р	9775	N/A	V-1	
	0	•			•			

	2							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	435296	NFPA 101, 9.11.1	NA	00	0000	М		509
2	435375	NA	(16)(a)2.2	1	105A	М		
3	435804	NA	(2)(k)	2	101	С	Dirt Area Between Pavilion and Basketball Courts	

;	3							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	433833	NFPA 101, 9.11.1.A	NA	00	0000	M		

		Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
-	1	391744	69A-58.00 81 (11)(d)	(10)(i)4	00	0000	С		1205
ŀ	2	434043	NA	(9)(d).1	5	109	М		
ľ		0	•						

	2							
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	434134	NA	(12)(d)2	1	200	М		
2	434137	NA	(12)(d)2	1	206	М		
3	434121	NA	(12)(d)2	1	230	М		
4	434123	NA	(12)(d)2	1	231	М		
5	434122	NA	(12)(d)2	1	233	М		
	0	•		•	•	•		

	5							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	434292	NA	(16)(a)2.2	5	509B	М		
2	420739	NA	(2)(i).1	Р	0000	С		

2 422412	NA	Α (	(7)(c)3	avilio	0000	М	
0			_				

		2							
		Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
	1	410391	69A-58.00 81(11)(d)	(10)(i)4.3	1	125	С		1205
	2	424687	69A-58.00 81(11)(d)	(10)(i)4.3	1	128A	С		1205
	3	410103	69A-58.00 81(11)(d)	(10)(i)4.3	1	138	С		1205
Ī		0		•	•		•	•	

;	3								
	Citation Number		69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	432222		NFPA 101, 9.11.1	NA	00	0000	М		509
2	262129	9	NA	NA	4	0000	N/A		
	0				•	•	•		•

	1							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	432565	NA	(16)(a)2.4	2	104F	М		
2	432554	NA	(16)(a)2.4	5	201A	М		
3	432553	NA	(16)(a)2.4	5	202B	М		
4	432552	NA	(16)(a)2.4	5	204B	М		
5	432555	NA	(16)(a)2.4	5	206A	М		
6	432550	NA	(16)(a)2.4	5	211A	М		

7	432549	NA	(16)(a)2.4	5	214B	М	
8	432559	NA	(16)(a)2.4	5	215	М	
9	432560	NA	(16)(a)2.4	5	216	М	
10	432530	NA	(16)(a)2.4	6	103B	М	
11	432529	NA	(16)(a)2.4	6	104B	М	
12	358160	NA	(2)(i)	Р	0000	С	
	0		1				

1	2								
	Citation Number		69A-58.008	SREF Chapter 5	BLDG	ROOM	ı	ROOM DESCRIPTION	CODE
1	427358	3	NA	NA	00	0000	N/A		
2	427360		NFPA 101, 9.11.1.A	NA	00	0000	М		
	0								

1 Row Citation 69A-58.008 SREF BLDG ROOM TYPE ROOM CODE DESCRIPTION Number Chapter 5 1 247236 NA (14)(b)3a 00 0000 С 2 415828 NA (2)(a)8 00 0000 М NFPA 101, 3 428761 NA 00 0000 М 9.11.1.A (7)(c)3 4 428791 NA 1 0000 Μ 5 428818 (12)(d)2 168 NA 1 Μ 6 366034 NA (7)(c)32 0000 С Gymnasium

7	428841	NFPA 101, 4.6.12.1.A	(9)(a).2	2	202	М	304
8	415770	NA	(16)(a)3	3	190	М	
	0						

8 Row Citation 69A-58.008 SREF BLDG ROOM TYPE ROOM CODE Chapter 5 DESCRIPTION Number 1 355943 00 0000 С NΑ (2)(a)8 2 356214 69A-58.00 00 0000 С 1205 (10)(i)4 81 (11)(d) 3 430028 0000 NA (2)(i).1 00 Μ 4 369688 0000 NA (13)(n) 00 Μ 5 430144 0000 NA (10)(b) 1 Μ 6 430172 NA (16)(a)2.4 220A Μ 7 430173 NA (16)(a)2.4 1 221A Μ 8 430111 NΑ (16)(a)3 10 080 M 9 369685 080 С NA (8)(a) 10 10 430035 NΑ (16)(a)3 10 080 Μ 11 430183 NA (7)(c) 2 0000 М 12 430043 151 NA (8)(a).5 M Row Citation 69A-58.008 **SREF** BLDG ROOM TYPE ROOM CODE DESCRIPTION Chapter 5 Number 13 413374 NFPA 101, (9)(a).2 0000 Μ 304 4.6.12.1.A 14 356195 NFPA 101, (13)(a) 4 116 С 299 7.2.1.3.1

15	430075	NA	(16)(a)2.4	6	112	М		
16	369594	NA	(8)(a)	6	181	С		
17	430064	NA	(16)(a)3	6	181	М		
18	430065	NA	(16)(a)3	6	181	М		
19	430103	NA	(16)(a)2.4	7	160	М		
20	430104	NA	(16)(a)2.4	7	161	М		
21	356051	NA	(8)(a)	7	180	С		
22	430070	NA	(16)(a)3	7	182	М		
23	430120	NA	(9)(c)	8	162	М		
24	430129	NFPA 101, 4.5.8.A	(10) (a)10a.1	8	197	М		299
25	430148	NA	(16)(b)1.1	8	207	М		
26	430149	NA	(16)(b)1.1	8	207	М		
Dow	Citation	69A-58.008	SREF	BI DG	ROOM	TYPE	ROOM	CODE
ROW	Number	09A-30.000	Chapter 5	BLDG	ROOM	ITTE	DESCRIPTION	CODE
27	430154	69A-58.00 5(2)(a)7.7	(16)(a)6a	8	281	MS		808
28	430271	NA	(16)(a)3	8	282	М		
20	430223	NA	(16)(b)1.1	9	160	М		

	28							
Ro	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
	1 432703	NA	(16)(a)2.4	3	0000	М		
	2 432623	NA	(16)(a)3	5	120	М		
	3 432678	NA	(16)(a)2.2	6	105	М		
	4 432613	NA	(16)(a)2.4	9	117A	М		_

	5 432653	NA	(16)(a)2.4	Р	9871	М	
ſ	0						

	5							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	1	ROOM DESCRIPTION	CODE
1	433634	NFPA 101, 9.11.1	NA	00	0000	М		509
2		69A-58.00 81 (11)(d)	(10)(i)4	1	0000	С		1205

		2								
R		Citation Number		69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
	1	42985		NFPA 101, 9.11.1.A	NA	00	0000	М		
	2	41649 <sup>-</sup>		69A-58.00 81(14)(a)	NA	2	0000	CS		299
	3	429850	0	NA	(12)(d)2	3	213	М		
	4	41646	5	NA	(16)(a)2.4	6	105F	М		
		1				•				

3 Row Citation Number SREF Chapter 5 TYPE ROOM DESCRIPTION 69A-58.008 BLDG ROOM CODE 1 416842 NFPA 101, NA 10 101 Μ 9.7.5.A 2 434578 NA 102 303 NFPA 101, 5 Μ 10.3.1.D

3 434600	NA	(16)(a)2.2	7	0000	М	
0						

3 TYPE ROOM Row Citation 69A-58.008 SREF BLDG ROOM CODE Number DESCRIPTION Chapter 5 172 С 1 430982 69A-58.00 1205 (10)(i)4.3 1 81(11)(d) NA 2 430980 NFPA 101, 1 173 Μ 303 10.3.1.D 3 410555 NA 11 307 (16)(a)2.2 Μ 4 431154 NFPA 101, NA 12 193 Μ 509 9.11.1 5 411348 NFPA 45, 0000 (13)(q)6 2 899 M 11.2.3.4 6 339151 NA (10)(b) 2 209 С 7 411302 NA 2 280 (8)(a).5 Μ 8 430988 69A-58.00 3 346 210 (8)(a).9 Μ 81(9)(c) 9 431040 347 (12)(d)2 3 Μ 10 410753 NFPA 101, (8)(a) 5 0000 299 M 4.5.8.H 11 430890 5 503 NΑ (8)(a).5 Μ 12 411256 NA 5 541 М (8)(a).5 13 411343 69A-58.00 807 (8)(a).9 MS 210 81(9)(c) 69A-58.008 Citation SREF BLDG ROOM TYPE ROOM CODE Row DESCRIPTION Number Chapter 5

							Total Total
			_		,		
Row Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1 425721	NFPA 101, 9.11.1	NA	00	0000	М		509
2 425642	69A-58.00 81(17)(a)	NA	4	203	M		799
0		I		1	1		l

2						
Row Citation	69A-58.008	SREF Chapter 5	BLDG	ROOM	ROOM DESCRIPTION	CODE

	1 430		NFPA 101, 9.11.1.A	NA	00	0000	М	
	2 430	0476	NA	(7)(c)3	5	0000	М	
	0		l					

	2								
	Citation Number		69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	422573	3	69A-58.00 81(11)(d)	(10)(i)4.3	1	0000	0		1205
2	422574	4	NFPA 70, 110.3(B)	(17)(b)	1	0000	0		899
3	42257	5	NA	(9)(a)	1	0000	0		
4	422576	<u> </u>	69A-58.00 81(11)(d)	(10)(i)4.3	1	0000	0		1205
5	422578	3	NA	(9)(a)	1	0000	0		
6	422579	9	NFPA 101, 9.11.1.A	NA	1	0000	0		
7	422580	)	NFPA 17, 11.3.1	(13)(p)10.9	1	0000	0		515
8	422603	3	NFPA 101, 9.6.1.3	NA	1	0000	0		410
	0		ı	•				1	

	8							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	425609	69A-58.00 4(2)(a)	NA	00	0	0		1299
2	409008	NA	(2)(d)10	00	0000	М		

3	342185	NFPA 101, 13.4.8.6.8	(13)(n)	00	0000	С	Home Football Bleachers	
4	377014	69A-58.00 81 (11)(d)	(10)(i)4	00	0000	С		1205
5	425578	NA	(16)(a)2.4	1	013B	М		
6	366306	NFPA 13, 8.1.1 (1)	NA	1	102	С		520
7	366158	NFPA 13, 8.1.1 (1)	NA	1	107	С		520
8	425584	NA	(16)(b)1.1	1	129A	М		
9	425711	NA	(16)(a)3	1	192	М		
10	425692	NA	(16)(a)3	1	194	М		
11	425876	NA	(16)(a)2.4	10	103	М	Baseball Field	
12	425877	NA	(16)(a)2.4	10	104	М	Baseball Field	
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
13	425882	NA	(16)(a)2.4	11	103	М	Softball Field	
14	425883	NA	(16)(a)2.4	11	104	М	Softball Field	
15	425813	NA	(16)(a)2.4	2	131A	М		
16	425812	NA	(16)(a)2.4	2	132A	М		
17	342008	NA	(16)(a)2	2	134	М		
18	425586	NA	(16)(a)2.2	2	157	М		
19	425780	NFPA 25, 4.1.3	NA	2	181	0		599
20	425583	NA	(16)(a)3	2	193	М		
21	425824	NFPA 101, 7.1.10.1.A	NA	3	003	OS		210
22	425823	NFPA 101, 7.1.10.1.A	NA	3	108	os		210
23	425826	NFPA 101, 7.1.10.1.A	NA	3	115	os		210

24	425820	69A-58.00 5(2)(a)7.6	(13)(x)4.4	3	190	0		302
25	425821	NA	(16)(a)3	3	190	М		
26	425601	NA	(16)(a)2.4	4	0000	М		
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
27	425787	NA	(8)(a).5	4	104	М		
28	393263	NA	(16)(a)2	4	108D	М		
29	409048	NA	(8)(a).2	4	109	М		
30	425784	NA	(17)(a).1	4	180	0		
31	425588	69A-58.00 5(2)(a)7.9	(17)(b)2c	4	193	os		808
32	425590	NFPA 101, 7.1.10.1.A	NA	5	002	OS		210
33	425589	NFPA 70, 110.26.A	(17)(b)2d	5	101B	0		801
34	425598	NA	(16)(a)2.4	5	103	М		
35	425595	NA	(16)(a)3	5	190	М		
36	393444	NA	(7)(c)	50	0000	С		
37	278009	69A-58.00	NA	50	0000	C	Pressbox	299
38	425635	81 (15)(a) NA	(8)(a).5	6	005	M		
Row	Citation	69A-58.008	SREF	BLDG	ROOM	TYPE	ROOM	CODE
	Number		Chapter 5				DESCRIPTION	
39	425655	NA	(8)(a).5	6	009	М		
40	425662	NFPA 70, 110.26.A	(17)(b)2d	6	102B	0		801
41	425628	NA	(8)(a).5	6	107	М		

42	425650	NA	(16)(0)2.4	6	112	М		
42	425050	INA	(16)(a)2.4		112	IVI		
43	425648	NA	(10)(f)	6	112A	М		
44	425621	NA	(10)(b)	7	106	0		
45	425615	NA	(10)(b)	7	114	0		
46	425899	NA	(13)(q)1.1	8	114A	М		
47	425902	69A-58.00 5(2)(a)7.7	(16)(a)6a	8	190	os		808
48	425904	69A-58.00 5(2)(a)7.9	(17)(b)2c	8	291	os		808
49	425660	NA	(8)(a).5	9	102	М		
50	352737	NA	(2)(i)	Р	0000	С		
51	425607	NFPA 70, 110.26.A	(17)(b)2d	Р	9414	0	P-326	801
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE

								Total Total
								Ισιαί
		I	I	I	I	I		I
Row	Citation	69A-58.008	SREF	BLDG	ROOM	TYPF	ROOM	CODE
	Citation Number		SREF Chapter 5				ROOM DESCRIPTION	
1	435164	NFPA 101, 9.11.1.A	NA	00	0000	М		
	0	•	•					

	1							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1		NFPA 101, 9.11.1.A	NA	00	0000	М		
2	432107	NA	(5)(a)	00	0000	М		

3	432055	NFPA 101, 4.5.8	(10)(a)10a	1	001B	М	299
4	403849	NA	(9)(d)	2	109D	М	
5	432122	NA	(6)(b)	2	120	М	
6	432207	NA	(16)(a)3	2	194	М	
7	411511	NA	(16)(a)2.4	3	121A	М	
8	411512	NA	(16)(a)2.4	3	121B	М	
	0						

	8							
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	433430	NFPA 101, 9.11.1.A	NA	00	0000	М		
2	420482	NA	(7)(c)3	00	0000	М		
3	433288	69A-58.00 81(11)(d)	(10)(i)4.3	3	108	С		1205
4	402064	69A-58.00 81 (11)(d)	(10)(i)4	3	115	С		120
5	420493	NFPA 101, 7.1.10.1	(2)(d)1.1	3	9699	CS		212
6	433281	NA	(16)(a)2.4	5	101D	М		
7	401779	NA	(2)(i)	Р	0000	М		

	6							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	427919	NA	(5)(a)	00	0000	С	East PE Pavilion	

2	428083	NFPA 101, 9.11.1	NA	00	0000	М	509
3	428113	NA	(16)(a)3	12	190	М	
4	428062	69A-58.00 81(16)(a)	(13)(0)	2	101B	М	999
5	427924	NA NA	(16)(a)2.2	4	104	М	
6	427923	NA	(16)(a)2.2	4	104A	М	
7	427925	NA	(16)(a)2.2	4	105	М	
8	427922	NA	(16)(a)2.2	4	105A	М	
	0	<u>'</u>	-		•		•

	8							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	434504	NFPA 101, 9.11.1.A	NA	00	0000	М		
	0			•	•	•		

	1							
Rov	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
-	426725	NFPA 101, 9.11.1.A	NA	00	0000	М		
2	2 412850	) NA	(1)(f)	00	0000	С	Storage Trailers at Bldgs 8 and 12	
3	3 426722	2 NA	(9)(a).4	50	0000	С		
	0	•	•	•	•	•		

	3							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	422025	NA	(10)(b)	1	0000	М		
2	422043	NFPA 101, 4.5.8.D	(10)(c).1	1	292	С		304

	2								
	Citation Number		69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	235721	-	NA	(16)(a)	1	181	С		
2	335838	3	NA	(4)	2	0000	С		
3	335809	)	NA	(2)(i)	Р	0000	С		
	0								

	3							
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	418364	NA NA	(16)(a)3	00	0000	М		
2	418434	NFPA 101, 13.2.2.2.4 (2)	NA	1	120	М		210
3	434868	B NA	(16)(b)9	1	128A	М		
4	418394	NFPA 70, 300.31	(17)(b).5	1	129	М		809
5	434869	) NA	(12)(d)2	1	139	М		
6	434881	. NA	(12)(d)2	1	146	М		

7	434883	NA	(8)(a).8	1	149A	М		
8	418393	NFPA 70, 300.31	(17)(b).5	1	159	М		809
9	434892	NFPA 101, 10.3.1.D	NA	1	160	М		303
10	434890	NFPA 101, 4.6.12.1.A	(9)(a).2	1	160N	М		304
11	434891	NA	(17)(a)1.1	1	161	М		
12	418388	NFPA 70, 300.31	(17)(b).5	1	161C	М		809
13	434854	NA	(12)(d)2	1	173	М		
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
14	434851	NA	(12)(d)2	1	174	М		
15	434846	NA	(12)(d)2	1	180	М		
16	434859	NA	(12)(d)2	1	187	М		
17	434841	NA	(8)(a).1	1	194B	М		
	0	•	•	ı			•	

	17								
	Citation Number		69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	435043	3	NA	(12)(d)2	1	132	М		
2	435023	3	NA	(12)(d)2	1	212	М		
	0		•		•	•	•		

:	2							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	403703	69A-58.00 6	NA	00	0000	N/A	Entire Campus	105
(	0							

		0								
		Citation Number		69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
•	1	388617		NFPA 13, 8.1.1 (1)	NA	3	193	С		520
Ī	2	427256	<u> </u>	NA	(16)(a)2.2	5	104	М		
•	3	388638		NFPA 13, 8.1.1 (1)	NA	5	108	С		520
•	4	427189		NFPA 1, 13.4.8	NA	5	192	М		513
Ī		0		•	•	•	•		•	

Citation Number	69A-58.008	SREF					
		Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
418687	NA	(2)(a)9	00	0000	С		
418712	NA	(2)(i).1	00	0000	С		
336127	NA	(7)(c)3	1	0000	С	Covered Area in Courtyard Adjacent to 1- 197A	
418729	NFPA 13, 8.1.1 (1)	NA	1	102B	С		520
435219	NFPA 1, 11.5.3.1	NA	1	159	OS		1202
435188	NFPA 101, 9.11.1.A	NA	1	198	М		
	418712 336127 418729 435219	418712 NA  336127 NA  418729 NFPA 13, 8.1.1 (1)  435219 NFPA 1, 11.5.3.1  435188 NFPA 101, 9.11.1.A	418712 NA (2)(i).1 336127 NA (7)(c)3 418729 NFPA 13, 8.1.1 (1) NA 435219 NFPA 1, 11.5.3.1 NA 435188 NFPA 101, 9.11.1.A	418712 NA (2)(i).1 00  336127 NA (7)(c)3 1  418729 NFPA 13, NA 1 8.1.1 (1)  435219 NFPA 1, 11.5.3.1  435188 NFPA 101, 9.11.1.A	418712 NA (2)(i).1 00 0000 336127 NA (7)(c)3 1 0000 418729 NFPA 13, 8.1.1 (1) NA 1 102B 435219 NFPA 1, 11.5.3.1 NA 1 159 435188 NFPA 101, 9.11.1.A NA 1 198	418712 NA (2)(i).1 00 0000 C  336127 NA (7)(c)3 1 0000 C  418729 NFPA 13, 8.1.1 (1)  435219 NFPA 1, 11.5.3.1 NA 1 159 OS  435188 NFPA 101, 9.11.1.A NA 1 198 M	418712 NA (2)(i).1 00 0000 C  336127 NA (7)(c)3 1 0000 C Covered Area in Courtyard Adjacent to 1-197A  418729 NFPA 13, 8.1.1 (1)  435219 NFPA 1, 11.5.3.1 NA 1 159 OS  435188 NFPA 101, 9.11.1.A NA 1 198 M

	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	l	69A-58.00 81 (11)(d)	(10)(i)4	00	000	С		1205
2	305006	NA	(2)(a)8	Р	0000	С		

	2							
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	359054	69A-58.00 81 (11)(d)	(10)(i)4	00	0000	С		1205
2	434614	NFPA 70, 408.4	NA	00	0000	М		802
3	434677	NA	(16)(a)3	1	0000	М		
4	434679	NA	(10)(b)	1	0000	М		
5	434690	NA	(16)(a)2.4	1	111	М		
6	434544	NFPA 101, 10.3.5	(12)(a).3	1	118	0		199
7	434545	NFPA 101, 10.3.5	(12)(a).3	1	139	0		199
8	434546	NFPA 70, 400.3	(17)(b)1e.2	1	139	0		803
9	418361	NA	(8)(a).1	12	101	М		
10	367932	69A-58.00 81(9)(a)	NA	2	103B	CS		299
11	390809	NA	(5)(a)	2	110	М		
12	434554	69A-58.00 81(9)(a).1	NA	2	123	OS		299
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE

13	359049	NFPA 70, 110.3 (B)	(17)(b)	2	130	М		899
14	434685	NA	(16)(b)1.1	2	132	М		
15	434621	NA	(16)(a)2.4	3	102C	М		
16	434627	NA	(10)(b)	3	104	М		
17	434615	NA	(1)(f)	4	0000	0		
18	434659	NA	(14)(b)4a	4	0000	М		
19	434661	NA	(10)b	4	0000	М		
20	358949	NFPA 101, 15.2.5.4	NA	4	101	CS		299
21	224820	NA	(13)(q)1	4	101	С		
22	224823	NA	(13)(q)1	4	102	С		
23	358950	NFPA 101, 15.2.5.4	NA	4	103	CS		299
24	358952	NFPA 101, 15.2.5.4	NA	4	104	CS		299
25	224826	NA	(13)(q)1	4	104	С		
26	434654	NFPA 70, 300.31	(17)(b).5	4	115	М		809
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
27	434694	69A-58.00 81(20).2	NA	4	119	M		205
28	434616	NA	(1)(f)	5	0000	0		
29	256467	NA	(13)(q)1	5	101	С		
30	358955	NFPA 101, 15.2.5.4	NA	5	101	CS		299
31	358990	NFPA 664, 8.2.2.1.4	(13)(q)7	5	102	С		699
32	224837	NA	(13)(q)1	5	102	С		
33	434639	NA	(13)(q)5	5	102	0		
34	359077	NFPA 101, 15.2.5.4	NA	5	102	CS		299

35	434637	NA	(8)(d)	5	105	М		
36	434641	NFPA 101, 7.1.10.1.A	NA	5	106	os		210
37	434665	NA	(8)(a).5	5	108	М		
38	434697	NA	(1)(f)	6	0000	0		
39	434645	NA	(7)(c)3	6	0000	М		
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
40	358958	NFPA 101, 15.2.5.4	NA	6	102	CS		299
41	359076	NFPA 101, 15.2.5.4	NA	6	103	CS		299
42	434647	NA	(16)(a)2.4	6	108	М		
	10		_1	<u> </u>	1		<u> </u>	

3	32							
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	437019	NFPA 101, 9.11.1.A	NA	00	0000	М		
2	437023	NFPA 101, 7.1.10.1.A	NA	1	007	OS		210
3	437020	NFPA 101, 9.6.1.3	NA	1	101	М		410
4	437029	NA NA	(16)(a)2.4	1	125	М		
5	437030	NA NA	(16)(a)2.4	1	126	М		
6	437039	NFPA 101, 7.1.10.1.A	NA	1	129	OS		210
7	437041	. NA	(16)(a)3	10	0000	М		
8	437060	NA	(9)(a)	2	106A	М		

9	437064	NA	(8)(a).5	2	114A	М		
10	437061	69A-58.00 5(2)(a)7.7	(16)(a)6a	2	191	os		808
11	437143	69A-58.00 81(8).3	NA	8	006	MS		209
12	437093	NFPA 13, 8.6.4.1.1.1	NA	8	123A	М		599
13	437131	69A-58.00 5(2)(a)7.9	(17)(b)2c	8	291	os		808
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
14	437026	NA	(8)(a).5	9	192	М		
	5	•	1				<u>'</u>	ı

	9							
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	350886	6 NA	(2)(i)	00	0000	С		
2	385245	69A-58.00 81 (11)(d)	(10)(i)4	00	0000	С		1205
3	436521	. NA	(16)(a)2.2	2	113A	М		
4	436515	5 NA	(16)(a)2.2	2	118A	М		
5	436398	3 NA	(16)(a)3	2	196	М	2nd Floor Mechanical Room	
6	436399	) NA	(16)(a)2.2	2	209A	М		
7	436402	NA	(8)(a).5	2	213A	М		
8	436400	) NA	(16)(a)2.2	2	216A	М		
9	410140	) NA	(16)(a)2.2	3	180	М		
10	436363	B NA	(16)(a)3	4	190	М		
11	436358	69A-58.00 81(16)(a).1	(16)(a)2	5	118B	М		999

12	436359	NA	(3)(a)	6	0000	М		
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
								Total
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
			Chapter 5				DESCRIPTION	
1	436805	69A-58.00 6	NA	00	0000	N/A		199
2	274996	69A-58.00 4 (2)(a)	N/A	1	0000	N/A		
3	275006	69A-58.00 4 (2)(a)	N/A	10	0000	N/A		
4	275007	69A-58.00 4 (2)(a)	N/A	11	0000	N/A		

5	274997	69A-58.00 4 (2)(a)	N/A	2	0000	N/A		
6	274998	69A-58.00 4 (2)(a)	N/A	3	0000	N/A		
7	274999	69A-58.00 4 (2)(a)	N/A	4	0000	N/A		
8	275000	69A-58.00 4 (2)(a)	N/A	5	0000	N/A		
9	275001	69A-58.00 4 (2)(a)	N/A	6	0000	N/A		
10	275002	69A-58.00 4 (2)(a)	N/A	7	0000	N/A		
11	275003	69A-58.00 4 (2)(a)	N/A	8	0000	N/A		
12	275005	69A-58.00 4 (2)(a)	N/A	9	0000	N/A		
13	275009	69A-58.00 4 (2)(a)	N/A	98	0000	N/A		
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
14	275010	69A-58.00 4 (2)(a)	N/A	99	0000	N/A		
	0			•	•	•	•	•

	0							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	368752	69A-58.00 81 (11)(d)	(10)(i)4	00	0000	С		1205
2	387995	NA	(3)(a)	00	9599	С		
3	387996	NA	(3)(a)	00	9599	С		
4	418825	NA	(16)(a)2.2	1	122	М		
5	418947	NA	(16)(a)2.2	2	220	М		
6	418951	NA	(9)(d)	3	106	С		
7	387642	NA	(16)(a)2	3	106F	М		

	8	418903	NA	(16)(b)1.1	3	110	М	
	9	418842	NA	(16)(a)2.2	6	212A	М	
Γ		0						

	9							
	Citation Number	69A-58.	008 SREF Chapte		ROOM	TYPE	ROOM DESCRIPTION	CODE
1	43725	NFPA 10 10.3.1.D		1	124D	М		303
2	43724	NFPA 10 9.11.1.A		1	130	М		
3	437258	8.1.1 (1)		2	102	М		520
4	404922	NFPA 70 408.4	), NA	2	190	М		802
	0		-					

	4							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	313050	NA	(2)(a)8	Р	0000	С	Portables	

	1							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	426847	NFPA 101, 9.11.1.A	NA	00	0000	М		
2	427386	NA	(7)(c)3	1	0000	М		
3	418533	NA	(16)(a)2.2	1	123C	М		

4	427445	NA	(16)(a)2.4	1	123K	М		
5	418573	NA	(16)(a)2.2	1	212	М		
6	426853	NA	(7)(c)3	2	0000	М		
7	426854	NA	(7)(c)3	2	0000	М		
8	426861	NA	(7)(c)3	2	0000	М		
9	419260	NFPA 13, 8.1.1 (1)	NA	2	192	С		520
10	427473	NA	(1)(f)	2	216	0		
11	418487	NFPA 13, 8.1.1 (1)	NA	3	102P	С		520
12	426863	NA	(16)(a)2.4	4	105B	М		
13	426864	NA	(16)(a)2.4	4	105C	М		
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE

								Total Total
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	435269	NA	(12)(d)2		107	М		
		NA	(12)(d)2		116	М		
		NA	(12)(d)2	2	121	М		
	0							

3							
Row Cita Nu	ation mber	69A-58.008	SREF Chapter 5	BLDG	ROOM	ROOM DESCRIPTION	CODE

1	404806	NA	(6)(b)	00	0000	М	Pavilion	
2		NFPA 101, 9.11.1.A	NA	00	0000	М		
3	432171	NA	(16)(a)3	6	106	М		

ſ		3							
		Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
ĺ	1	377120	NA	(14)(b)3a	Р	0000	С		
•		I	1	1	1	I	1		i I
		0							

Row Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1 435087	NFPA 101, 9.11.1.A	NA	00	0000	M		
2 435093	NA	(2)(d)10	00	9599	М		
3 435094	NA	(3)(c)	00	9599	M		
4 404434	69A-58.00 81 (11)(d)	(10)(i)4	50	0000	С		1205
5 422064	NA	(2)(a)8	50	8088	М		
6 422054	NA	(9)(a)	9	902	М		
7 422056	NA	(9)(a)	9	903	М		

	7							
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	319897	69A-58.00 81 (11)(d)	(10)(i)4	00	0000	С		120
2	396618	NFPA 101, 7.1.10.1	NA	00	0000	OS		21
3	396682	2 NA	(13)(n)	00	0000	М		
4	425921	NFPA 101, 9.11.1.A	NA	00	0000	M		
5	410760	) NA	(12)(d)2	1	130	M		
6	425990	NFPA 13, 6.2.7.2	NA	10	106	М		599
7	381025	5 NA	(9)(d)	10	106	М		
8	425985	5 NA	(16)(a)3	2	195	М		
9	426095	5 NA	(7)(c)	3	102	С		
10	426157	' NA	(17)(a).1	7	104	М	Lecture Hall	
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
11	426123	B NA	(12)(d)2	8	162	М		
12	396653	NA NA	(9)(a)	Р	0000	М		
13	426104	NFPA 101, 4.5.8.H	(8)(a)	Р	9219	М	P-5	299
	1	1			1		1	1

	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	413497	NA	(13)(n)	00	0000	M		
2	428752	NA	(10)(a)3b	00	0000	M	Exterior Stage and Ramp	
3	330072	NA	(2)(i)	00	0000	С		
4	379342	NA	(8)(a)	10	195	M		
5	394372	NA	(1)(f)	2	113H	0		
6	428749	NA	(9)(a).4	3	109	M		
7	413495	69A-58.00 81(9)(b)	NA	6	211	0		102
8	428871	NFPA 101, 4.5.8.D	(10)(c).1	9	107M	0		304

	8							
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	325833	B NA	(2)(i)	00	0000	С		
2	404947	' NA	(16)(a)2	1	181	М		
3	433070	) NA	(16)(a)2.4	3	101A	М		
4	433078	B NA	(16)(a)2.4	3	102A	М		
5	433069	) NA	(16)(a)2.4	3	103A	М		
6	433077	' NA	(16)(a)2.4	3	104A	М		
7	404973	NA NA	(16)(a)2	4	102C	М		

	8	433244	NA	(3)(c)	5	107	М	
	9	420074	NFPA 101, 7.10.1	(10)(i)4	8	106	М	299
_		l	1	ı		1		' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '
		0						

ſ		9								
		W Citation Number		69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
ľ	1	1 199270		NA	(14)(b)3a	00	9500	С		
	2	2 414711		NA	(9)(c)	Р	0000	М		
Γ		0		•						

	2							
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	415987	NA	(10)(b)	00	0000	М		
2	416004	NA	(2)(i).1	00	0000	М		
3	435622	NFPA 101, 9.11.1.A	NA	00	0000	М		
4	435582	NA	(9)(d)	1	0000	М		
5	435571	NA	(8)(a).1	1	190	М		
6	435586	NFPA 101, 10.3.1.D	NA	2	107	М		303
7	416151	NFPA 101, 4.5.8.I	NA	3	0000	М		411
8	435606	NFPA 101, 4.5.8.A	(10) (a)10a.1	3	004	М		299
9	416133	69A-58.00 81(11)(d)	(10)(i)4.3	3	102	С		1205

10	416134	69A-58.00 81(11)(d)	(10)(i)4.3	3	105	С		1205
11	435603	NA	(10)(i)5	3	111D	М		
12	416150	69A-58.00 81(11)(d)	(10)(i)4.3	3	112	С		1205
-	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
13	416415	69A-58.00 81(11)(d)	(10)(i)4.3	3	205	С		1205
14	416461	NA	(2)(i).1	Р	9266	М	P-3	
	0			-				

1	L4								
	Row Citation Number		69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	1 435477		NFPA 101, 9.11.1.A	NA	00	0000	М		
2	2 435490		NA	(12)(c)	1	211	М		
3	380085	5	NA	(5)(a)	2	104	М		
	0								

Row Citation Number         69A-58.008         SREF Chapter 5         BLDG ROOM         TYPE ROOM DESCRIPTION         CODE DESCRIPTION           1 414622         69A-58.00 81(11)(d)         (10)(i)4.3         00 0000         C         1205           2 414278         NA         (2)(i).1         P 0000         C		3						
81(11)(d)	Rov	1	69A-58.008	_	BLDG	ROOM		CODE
2 414278 NA (2)(i).1 P 0000 C	:	1 414622		(10)(i)4.3	00	0000	С	1205
		2 414278	NA NA	(2)(i).1	Р	0000	С	

	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	343428	69A-58.00 81 (11)(d)	(10)(i)4	00	0000	С		1205
2	427818	NFPA 101, 9.11.1.A	NA	00	0000	M		
3	427910	NA	(7)(c)3.1	11	0000	M		
4	428069	NFPA 13, 6.2.7.2	NA	11	106	М		599
5	412140	NA	(7)(c)3.1	13	0000	М	Pressbox	
6	385277	NA	(1)(f)	2	112	0		
7	385088	NA	(1)(f)	3	102D	0		
8	343514	NA	(1)(f)	4	109	0		
9	428136	NA	(16)(a)3	8	120	M		
	0	1	I	ı	1			

	9								
	Ow Citation Number		69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	1 362263		NA	(7)(c)3	1	0000	С		
2	2 423420		69A-58.00 81(11)(d)	(10)(i)4.3	1	164	С		1205
	0		•	•	•	•	•	•	

l	2						
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	ROOM DESCRIPTION	CODE

1		NFPA 101, 9.11.1	NA	00	0000	М	509
2	409946	NA	(5)(a)	6	0000	М	
	0						

	2								
	Citation Number	69A-	58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	346171	L NA		(2)(i)	00	0000	С		
2	434405	5 NFPA 9.11.1		NA	00	0000	М		509
3	434538	3 NA		(3)(c)	00	9599	М	Sidewalk South of P-23	
4	434441	L 69A-5 81(16)		(16)(a)2	1	125B	М		999
5	346103	3 NA		(2)(i)	Р	0000	С		
•	•	'		1	•	•	'		

	5								
	Citation Number		69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	435759		69A-58.00 81(11)(d)	(10)(i)4.3	1	134	С		1205
2	43573		69A-58.00 81(11)(d)	(10)(i)4.3	1	142A	С		1205
3	435743		69A-58.00 81(11)(d)	(10)(i)4.3	1	142H	С		1205
4	421246	-	69A-58.00 81(11)(d)	(10)(i)4.3	1	149	С		1205
5	435658		69A-58.00 81(11)(d)	(10)(i)4.3	1	210	С		1205
	<u> </u>			•	•	•	•	•	•

	5							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	425125	NFPA 70, 110.3(B)	(17)(b)	1	122	М		899
2	425178	NA	(16)(a)2.4	2	0000	М		
3	425177	69A-58.00 5(2)(a)7.7	(16)(a)6a	2	190	CS		808
4	425167	NFPA 70, 300.31	(17)(b).5	6	619	М		809
5	425126	69A-58.00 5(2)(a)7.7	(16)(a)6a	7	190	OS		808
6	409275			7	703	М		
7	373748	NA	(2)(a)8	Р	0000	С		

	5							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	43541	NFPA 101, 9.11.1.A	NA	00	0000	М		
2	435435	69A-58.00 81(11)(d)	(10)(i)4.3	00	0000	С		1205
3	435482	l NA	(8)(a).5	1	004	М		
4	435474	1 NA	(8)(a).5	1	007	М		
5	435517	7 NA	(8)(a).5	1	016	М		
6	435444	NFPA 70, 110.3(B)	(17)(b)	1	191	М		899
7	435413	3 NA	(17)(a).1	4	100	0		

	7								
	Citation Number		69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	285117		A-58.00 2)(a)	NA	Р	278	N/A	P-4	
2	285119		A-58.00 2)(a)	NA	Р	317	N/A	P-2	
3	392422		A-58.00 2)(a)	NA	Р	459	N/A	P-3	
4	285121		A-58.00 2)(a)	NA	Р	536	N/A	P-8	
5	285118		A-58.00 2)(a)	NA	Р	6	N/A	P-2B	
6	285122		A-58.00 2)(a)	NA	Р	7005	N/A	P-7	
7	270895		A.58.00 2)(a)	N/A	Р	736	N/A	P-1	
8	285124		A-58.00 2)(a)	NA	Р	9254	N/A	P-5	
9	285125		A-58.00 2)(a)	NA	Р	9255	N/A	P-6	
	0	I		1	1	1	1	1	1

	0								
	Citation Number		69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	422375	5	NA	(7)(c)	00	0000	С		
2	406804		NFPA 101, 4.5.8.B	(10)(a)8.1	Р	9523	М		299
	0				•			•	

2							
Row C	Citation Iumber	69A-58.008	SREF Chapter 5	BLDG	ROOM	ROOM DESCRIPTION	CODE

1 42226	NFPA 70, 408.4	NA	2	101	М	802
2 42227	NFPA 70, 408.4	NA	2	102	М	802
0						

	2							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	421738	B NA	(5)(c)	00	0000	М		
2	421753	B NA	(9)(d)	2	104	М		
3	373954	69A-58.00 81 (11)(d)	(10)(i)4	4	0000	С		1205
4	387919	) NA	(16)(a)2	4	101E	М		
5	373887	7 69A-58.00 81 (11)(d)	(10)(i)4	5	0000	С		1205
6	421715	5 NA	(2)(d)10	6	8088	М		
7	373892	69A-58.00 81 (11)(d)	(10)(i)4	7	0000	С		1205
	0	1	1	•	•	•	'	1

	7								
	Citation Number		69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	427933		69A-58.00 4(2)(a)	NA	00	0	0		1299
2	427934	1	NA	(2)(f)1	00	0000	0		
3	427935	5	NA	(2)(a)5	00	0000	М		
4	427936	ô	NA	(2)(a)5	00	0000	М		
5	360105	5	NA	(2)(i)	00	0000	С		

6	391665	NA	(7)(c)3	00	0000	М		
7	427940	NA	(5)(a)	00	0000	М	West Pavilion	
8	428217	NA	(16)(a)2.4	1	008	M		
9	428219	NA	(17)(a)	1	009	М		
10	427939	NA	(7)(c)	12	0000	М		
11	428223	69A-58.00 5(2)(a)7.7	(16)(a)6a	12	007	os		808
12	428225	NA	(8)(a).5	12	007	М		
13	428190	NA	(9)(a).4	3	001	М		
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
14	428235	NA	(9)(c)	6	004A	М		
15	428265	NA	(9)(c)	8	002A	М		
16	428256	NA	(9)(c)	8	004C	M		
17	428294	NA	(8)(a).5	9	008	М		
18	428189	NA	(16)(b)1.1	Р	0000	М		
19	411765	NA	(9)(d)	P	31	М	P-3	
20	427947	NA	(6)(b)	Р	3543	M	P-2	
	1				<u> </u>		l	1

	19							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	423547	NA	(16)(a)2.2	2	206	М		
2	423555	NA	(11)(e)	2	304	М		
	0	•				•		

	2							
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	436553	NFPA 101, 9.6.1.3	NA	1	101A	М		410
2	436569	NA	(16)(a)2.4	2	202A	М		
3	436567	NA	(16)(a)2.4	2	207A	М		
4	436561	NA	(16)(a)2.4	3	306	М		
5	436588	NA	(16)(a)2.4	4	407A	М		
6	436603	NA	(16)(a)2.4	7	701	М		
7	436606	NA	(16)(a)2.4	7	703	М		
8	436615	NA	(16)(a)2.4	7	705A	М		
9	436614	NA	(16)(a)2.4	7	706A	М		
10	436599	NA	(16)(a)2.4	7	707A	М		
11	436597	NA	(16)(a)2.4	7	708A	М		
12	436545	NA	(9)(a)	Р	3570	М	P-6	
13	254924	69A-58.00 4 (2)(a)	NA	Р	4788	N/A	P-9	
14	436549	NA	(9)(a)	Р	5006	М	P-8	
15	436550	69A-58.00 5(2)(b)1.1	NA	Р	5006	М	P-8	410
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE

								Total Total
Row	Citation	69A-58.008	SREF	BI DG	ROOM	TVDE	ROOM	CODE
Now	Number	337 351033	Chapter 5	BEBG	T.COM		DESCRIPTION	CODE
1	350718	NA	(2)(i)	00	0000	С		
2	391609	NA	(7)(c)3	00	0000	М		
3	391612	69A-58.00 81 (11)(d)	(10)(i)4	1	0000	С		1205
4	436697	NA	(16)(a)2.2	1	0000	С		
	0	1	<u> </u>	l		<u> </u>		

Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	424897	NA	(16)(a)2.4	11	105	М		
2	424898	NA	(16)(a)2.4	11	109	М		
3	425088	NA	(16)(a)2.4	2	108A	М		
4	425066	NA	(16)(a)2.4	3	117B	М	3-104	
5	424848	NFPA 70, 110.3(B)	(17)(b)	7	111	М		899
6	424907	NA	(16)(a)2.4	8	112A	М		
7	424908	NA	(16)(a)2.4	8	113A	М		
8	374081	NA	(2)(a)8	Р	0000	С		
9	424883	NA	(16)(a)2.4	Р	6459	М	C-13	
	0	•	1	I			'	

	9							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	421580	) NA	(7)(c)	00	0000	С		
2	435965	NFPA 101, 9.6.1.3	NA	1	101	M		410
3	435974	1 NA	(16)(a)2.2	2	112B	М		
4	421612	NFPA 101, 4.5.8.D	(10)(c).1	3	190	С		304
	0	<u> </u>	•	•	•	•	•	

	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	343729	NA	(3)(c)	00	0000	С	Tennis and Basketball Courts	
2	343955	NFPA 101, 13.4.8.6.8		00	0000	С	Home Football Bleachers	1399
3	356775	NA	(8)(d)	00	0000	С		
4	370319	69A-58.00 81 (11)(d)	(10)(i)4	00	0000	С		1205
5	424029	NFPA 101, 9.11.1	NA	00	0000	M		509
6	424037	NA	(16)(a)2.4	1	016A	М		
7	424184	NFPA 101, 9.6.1.3	NA	1	101	M		410
8	424036	NA	(16)(a)2.4	1	110C	М		
9	408204	NA	(12)(d)2	1	148	М		
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
10	424034	69A-58.00 81(1)(e)	NA	1	154B	M		299
11	393165	NA	(5)(a)	11	0000	С		
12	424224	NA	(16)(a)2.4	2	002A	M		
13	424205	NA	(16)(a)2.2	2	126	М		
14	424207	NA	(13)(q)1.1	2	149	М		
15	424200	NA	(16)(a)3	2	194	М		

16	424284	I NA	(8)(a).5	3	001B	М		
17	424279	) NA	(16)(b)1.1	3	104	М		
18	424278	NFPA 45, 8.2.2	(16)(a)5	3	106	М		999
19	424309	) NA	(16)(a)2.4	4	0000	М		
20	424315	5 NA	(16)(a)3	4	0000	М		
21	424052	2 NA	(16)(b)1.1	5	003B	М		
22	424297	7 NA	(16)(a)2.4	5	103E	М		
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
23	424259	) NA	(10)(b)	5	108	М		
24	424054	69A-58.00 81(17)(a)	NA	5	193	М		799
25	424028	69A-58.00 81(17)(a)	NA	6	193	М		799
26	424151	l NA	(16)(a)2.4	7	0000	М		
27	424152	NFPA 1, 13.6.1.2.A	NA	7	103	MS		506
28	332615	5 NA	(2)(a)8	Р	0000	С		
	1		1	1			•	

2	27							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	422240	NFPA 101, 9.6.1.3	NA	1	0000	М		410
2	422243	NFPA 70, 408.4	NA	1	003	М		802
	0					•		

	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	341973	NA	(1)(f)	00	9599	0		
2	372070	NA	(15)(a)	12	170	М		
3	400963	NA	(13)(x)8a	12	203C	0		
4	425270	NA	(16)(a)2.2	5	106	М		
5	425261	NA	(16)(a)2.2	7	181	М		
6	415415	NA	(16)(b)1.1	8	194	М		
	0				<u> </u>			

	6								
	Citation Number	6	9A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	372419		-58.00 11)(d)	(10)(i)4	00	0000	С		1205
2	384380	) NA		(3)(c)	00	0000	М		
3	428492	NA		(2)(f)3	00	0000	С		
4	428564	1 NA		(17)(a)1.1	1	108A	М		
5	428547	7 NA		(16)(a)2.2	1	197A	М		
6	428576	6 NA		(16)(a)2.2	1	293	М		
7	428562	NA		(16)(a)2.2	2	104	М		
8	428559	) NA		(16)(a)2.4	2	105A	М		
9	359090	) NA		(2)(a)8	Р	0000	С		

10	359091	NA	(14)(b)3a	Р	0000	С		
11	428508	NA	(12)(d)2	Р	9343	М	P-403	
	0							

	1	L1								
		Citation Number		69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
	1	407058		69A-58.00 81(11)(d)	(10)(i)4.3	00	0000	С		1205
	2	2 378776		69A-58.00 5 (2)(a)7	(16)(a)6a	3	191	os		808
İ		1		•			•	•		

	1							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	405814	NA	(3)(c)	00	0000	М		
2	437014	69A-58.00 81(17)(c)	NA	1	107A	MS		405
3	436988	69A-58.00 81(17)(c)	NA	1	108A	MS		405
4	437000	69A-58.00 81(17)(c)	NA	2	112	MS		405
5	436999	NA	(16)(a)2.2	2	243	М		
6	421006	NA	(8)(a).5	4	408	М		
7	436979	NA	(16)(a)2.2	8	806	М		
8	436978	NA	(16)(a)2.2	8	807	М		
	3				1		l	

ļ	5						
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	ROOM DESCRIPTION	CODE

1	361500	NA	(7)(c)3	00	0000	С		
2	435884	NA	(7)(c)	00	0000	M	Metal Bldg. North Campus	
3	435885	NA	(1)(e)3.1	00	0000	М		
4	331035	NFPA 45, 11.2.3.4	(13)(q)6a	1	0000	С		899
5	436053	69A-58.00 81(11)(d)	(10)(i)4.3	1	0000	0		1205
6	436134	NFPA 13, 8.1.1 (1)	NA	1	0000	С		520
7	436144	NFPA 101, 9.6.1.3	NA	1	101	M		410
8	435867	NA	(16)(b)1.1	1	137	М		
9	436148	NA	(1)(e)3.1	1	140	0		
10	436057	69A-58.00 81(11)(d)	(10)(i)4.3	1	157	С		1205
11	436058	69A-58.00 81(11)(d)	(10)(i)4.3	1	158	С		1205
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
12	436059	69A-58.00 81(11)(d)	(10)(i)4.3	1	160	С		1205
13	436025	NA	(8)(a).5	1	161	М		
14	436056	69A-58.00 81(11)(d)	(10)(i)4.3	1	162	С		1205
15	436004	NFPA 101, 7.1.10.1.A	NA	1	163	OS		210
16	436008	69A-58.00 81(11)(d)	(10)(i)4.3	1	169	С		1205
17	436012	69A-58.00 81(11)(d)	(10)(i)4.3	1	171	С		1205
18	436052	69A-58.00 81(11)(d)	(10)(i)4.3	1	174	С		1205

19	436075	NA	(16)(a)2.4	1	179A	М		
20	436140	NFPA 101, 10.3.5	(12)(a).3	1	180	0		199
21	436076	NA	(16)(a)2.4	1	181A	М		
22	435861	69A-58.00 81(11)(d)	(10)(i)4.3	1	192	С		1205
23	435878	NA	(16)(a)2.4	1	197F	М		
24	436054	NA	(13)(x)2b	1	197H	М		
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
25	436143	NFPA 70, 300.31	(17)(b).5	1	198G	М		809
26	435856	NA	(1)(e)8j	1	199	0		
27	436039	69A-58.00 5(2)(a)7.9	(17)(b)2c	1	199B	os		808
28	435871	NFPA 101, 9.11.1	NA	1	199C	М		509
29	435857	69A-58.00 5(2)(a)7.7	(16)(a)6a	1	199G	os		808
30	435853	NA	(8)(a).5	2	191	М		
31	435862	NA	(16)(a)2.4	2	202D	М		
32	436068	NA	(8)(a).1	2	203A	М		
33	435863	NA	(16)(a)2.4	2	203D	М		
34	217097	NA	(14)(b)3a	Р	0000	С		
35	390038	NA	(6)(b)	Р	123	М	P-3	
36	374569	NA	(6)(b)	Р	152	М	P-6	
37	402485	NA	(10)(h)	Р	152	М	P-6	
38	254675	69A-58.00 4 (2)(a)	N/A	Р	1860	N/A	P-12	
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
39	435888	NA	(9)(a)	Р	2376	М	P-10	
40	402466	NA	(10)(h)	Р	293	М	P-9	

41	361360	NA	(10)(h)	Р	293	М	P-9	
42	374576	NA	(6)(b)	Р	293	М	P-9	
43	402484	NA	(6)(b)	Р	313	М	P-7	
44	418781	NA	(7)(c)3.1	Р	313	М	P-7	
45	435889	NFPA 70, 300.31	(17)(b).5	Р	313	М	P-7	809
46	254671	69A-58.00 4 (2)(a)	NA	Р	315	N/A	P-8	
47	418787	NA	(9)(a).4	Р	3755	М	P-1	
48	435892	NA	(6)(b)	Р	4065	М	P-14	
49	435893	NA	(6)(b)	Р	4068	М	P-13	
50	436170	69A-58.00 4(2)(a).1	NA	Р	4248	N/A	P-11	
51	436171	69A-58.00 4(2)(a).1	NA	Р	508	N/A	P-16	
52	374590	NA	(6)(b)	Р	672	М	P-15	
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
53	436172	69A-58.00 4(2)(a).1	NA	Р	724	N/A	P-17	
	3	•	•	•	•	•		

	45							
Row	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	1	NFPA 101, 9.11.1.A	NA	00	0000	М		
2	434970	NA	(2)(d)10	00	9599	М		
3	1	69A-58.00 81(11)(d)	(10)(i)4.3	1	144	С		1205
4		69A-58.00 81(11)(d)	(10)(i)4.3	1	146	С		1205

5		69A-58.00 81 (11)(d)	(10)(i)4	1	228	С	1205
6	434956	NA	(16)(a)2.2	2	180	М	
7	402515	NA	(16)(a)2	3	102A	М	
	0						

	7							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	310929	) NA	(14)(b)3a	00	0000	С		
2	433728	NFPA 101, 9.11.1	NA	00	0000	М		509
3	433804	NFPA 101, 4.5.3.2	(8)(a).6	2	0000	М	2-105, 2-106	210
	0	•		•	•	•		

	3							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	424561	NFPA 101, 9.11.1.A	NA	00	0000	М		
2	379110	NA	(2)(d)10	00	9599	М		
3	424567	NA	(16)(a)2.2	1	107B	М		
4	424566	NA	(16)(a)2.2	1	107C	М		
5	412345	69A-58.00 81(11)(d)	(10)(i)4.3	1	146	С		1205
6	412587	69A-58.00 81(11)(d)	(10)(i)4.3	1	212	С		1205
7	412611	69A-58.00 81(1)(d)	NA	1	212	CS		299
8	424636	NA	(8)(a).1	10	001	М		
9	370753	NA	(16)(a)5	2	210	М		999

10		69A-58.00 5(2)(a)7.9	(17)(b)2c	3	151	OS		808
11	398921	NA	(16)(a)3	3	182	М		
12	412404	NA	(5)(a)	4	101	С		
13	412378	NA	(16)(a)2.4	4	112B	М		
14	412397	NA	(16)(a)2.4	4	160	М		
_	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
15	424656	NA	(8)(a).1	9	103	М		
	2			1	•	•		

1	.3							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM	TYPE	ROOM DESCRIPTION	CODE
1	433433	NA	(16)(a)2.4	1	117A	М		
2	433659	NA	(16)(a)2.2	4	103C	М		
3	433776	NFPA 101, 9.11.1.A	NA	4	104B	М		
4	433654	NA	(16)(a)2.4	4	104D	М		
5	433653	NA	(16)(a)2.4	4	104F	М		
	0	•	•	ı				

	5							
	Citation Number	69A-58.008	SREF Chapter 5	BLDG	ROOM		ROOM DESCRIPTION	CODE
1	389925	NA	(14)(b)3a	Р	0000	С		
2	421784	NA	(2)(i).1	Р	0000	С		
3	421806	NA	(2)(i).1	Р	9760	С	P-11	

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Adjust gate in chain link fencing to latch properly - adjacent to propane tank and basket ball court	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Make necessary repairs to fire pump as indicated on annual inspection report dated 8.8.18	0		6/30/21
Repair exhaust fan in bathroom	2	NC	6/30/19
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair or replace heavily rusted door to hot water heater room	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21

## Total Serious Life Safety Citations Total Non-Serious Safety Citations

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Post evacuation signs indicating primary and secondary evacuation routes in contrasting colors for all classrooms without doors directly to exterior	2	NC	6/30/20
Replace missing window blinds (X2)	0		6/30/21
Provide non-slip impervious floor surface in bathroom	1	NC	6/30/19
Provide non-slip impervious floor surface in bathroom	1	NC	6/30/19

## Total Serious Life Safety Citations Total Non-Serious Safety Citations

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair or replace deteriorated, rotting wood on covered walks throughout campus	2	NC	6/30/19
Modify or improve site drainage at entrance gate to eliminate standing water - see Mr. Williams (custodian)	6	NC	6/30/19

## Total Serious Life Safety Citations Total Non-Serious Safety Citations

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES	T ppiop I	CORDECTIVE
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Provide suitable area for storage of golf carts and recharging golf cart batteries	12	NC	6/30/19
Make repairs as noted on fire sprinkler inspection report	0		6/30/21
Make first floor corridors 1-011 and 1-013 fire rated. Penetrations above ceiling	3	NC	6/30/18
Make third floor corridors 1-30 and 1-31 fire rated. Penetrations above ceiling	3	NC	6/30/18
Make second floor corridors 1-020 and 1-023 fire rated. Penetrations above ceiling	3	NC	6/30/18
Replace rotting fascia at NW exterior door of 1-118	0		6/30/21
Remove storage from mechanical room	1	NC	6/30/18
Post sign indicating primary and secondary evacuation routes in contrasting colors in dance room	1	NC	6/30/24
Prohibit storage and charging golf carts in mechanical room	1	NC	6/30/18
Remove all storage from corridor adjacent to 7-106	1	NC	6/30/18
Remove all storage from corridor adjacent to 7-124	1	NC	6/30/18
Remove stands from corridor adjacent to 7-119	1	NC	6/30/18
Repair ripped and rippled carpeting at west side of auditorium	1	NC	6/30/20
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Remove rust from and refinish rusted bar joists and metal deck	5	NC	6/30/17
Post sign indicating primary and secondary evacuation routes in contrasting colors in classroom	1	NC	6/30/24
Post sign indicating primary and secondary evacuation routes in contrasting colors in classroom	1	NC	6/30/24

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Restripe parking lot	0		6/30/22
Post sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/22

#### Total Serious Life Safety Citations Total Non-Serious Safety Citations

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repair for damaged edge of soffit outside warehouse bay 1-121 at south side of Bldg.	2	NC	6/30/20

Contract with a design professional to determine necessary repairs

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair or replace damaged parking bumpers which have exposed, protruding re-bar creates a tripping hazard. Parking bumpers 123, 134 on SE side of building	0		6/30/21
Repair damaged, spalling concrete on walls of roof	0		6/30/21
Eliminate plants growing in roof drains	0		6/30/21
Repair or replace rusted sinks in women bathroom	1	NC	6/30/20
Repair or replace rusted sinks in men bathroom	2	NC	6/30/19
Repair or replace damaged toilet partitions	0		6/30/21
Repair damaged, spalling concrete above AC ducts south of Bell Tower and on walls of roof	0		6/30/21
Repair deteriorated bottom edge of wall finish on roof above AC duct behind tower bell	1	NC	6/30/20

Repair or replace rusted sinks in women bathroom	1	NC	6/30/20
Fire alarm panel indicates trouble - perform necessary repairs	0	NC	6/30/20
Make necessary repairs as indicated on annual fire alarm inspection report dated January 2017	1	NC	6/30/20
Provide current certification that emergency lighting and generator are operable	0		6/30/21
Repair damaged electrical cord at juice refrigerator in serving line	0		6/30/21
Replace missing countertop laminate at sink area	0		6/30/21
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair or replace rusted sinks in bathroom	2	NC	6/30/19
Repair or replace damaged laminate on stall divider wall	2	NC	6/30/19
Repair or replace rusted sinks in men bathroom	2	NC	6/30/19
Repair water damaged wall finish at 3rd and 4th floor landings, between 1st and 2nd floors and damaged ceiling at 2nd floor	0		6/30/21
Eliminate plants growing in roof drains	0		6/30/21
Repair deteriorated wall finish on roof behind door - Wing-C roof	1	NC	6/30/20
Repair exhaust fan in bathroom	0		6/30/21
Replace broken signs (x2) for womens bathroom, 1 sign at entrance door and 1 in corridor	0		6/30/21
Repair or replace rusted sinks in bathroom	1	NC	6/30/20
Trim trees growing over building	0		6/30/21
Make repairs as indicated on fire alarm inspection report	0		6/30/21
Repair uneven concrete walk east of Chillers	0		6/30/21
Provide current certification that emergency lighting and generator are operable	0		6/30/21
Clean rain gutters	0		6/30/21
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
			6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on annual inspection report dated 3.28.18	0		6/30/21

## Total Serious Life Safety Citations Total Non-Serious Safety Citations

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Refinish and repair rusty areas of exterior stairs for buildings 4,5,6. Replace rusted through members	6	NC	6/30/21
Modify or improve drainage to prevent erosion at sidewalk north of building 9 and fill eroded area	5	NC	6/30/20
Make necessary repairs to fire sprinkler system as indicated on inspection report. Red annual and yellow semi-annual and quarterly tags	0		6/30/21
Replace damaged shields for 3 drinking fountains	0		6/30/21
Repair leaking chiller line at air handler in center of mechanical room	2	NC	6/30/19
Provide dust collection and exhaust system for all equipment being used. Do not use until connected to dust collection system	5	NC	6/30/19
Repair leaking plumbing in hood wash down cabinet	0		6/30/21
Repair or replace dust collector	0		6/30/21
Repair leaking chilled water line	0		6/30/21
Repair roof leaks through ceiling hatch. Coach indicates when it rains water runs out of ceiling hatch	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Modify or improve storm drainage from covered walkway outside of 4-101 and walkway from building 1 to building 4 to prevent storm water from running across sidewalks	5	NC	6/30/20
Remove rust and refinish: stair risers and nosing, supports of center handrail, and metal framing at 2nd floor landing at all stairwells for Bldg. 2 & 4. Also repair damaged stair nosing where applicable. Remove rust. Do not paint over rust	2	NC	6/30/20
Make necessary repairs to fire sprinkler system as indicated on inspection report. Red annual and yellow semi-annual and quarterly tags	0		6/30/21
Remove and prohibit storage on south exit ramp from Auditorium	0		6/30/19
Maintain clear aisle to SE exit from Stage	0		6/30/19
Provide current inspection tag for elevator	0		6/30/21
Repair ventilation fan in custodial closet	0		6/30/21
Adjust door to exterior to latch properly	0		6/30/21
Repair air conditioning. Will not run	0		6/30/21
Adjust door to exterior to latch properly	0		6/30/21
Repair exhaust fans in bathrooms 4-241A and B	0		6/30/21
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair air conditioning system to ensure it operates as designed in communications room or provide split system Excessive heat is causing network equipment to malfunction and school is keeping fire door open	2	NC	6/30/19
Trane refrigerant monitor indicates TROUBLE. Repair trouble	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on inspection report. Red annual and yellow semi-annual and quarterly tags	0		6/30/21
Remove and replace moldy insulation on leaking chilled water line	0		6/30/21
Re-insulate chilled water pump impeller housing	0		6/30/21
Modify or improve site drainage at covered walkway side of portable classrooms	7	NC	6/30/19

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Remove rust, prime and paint rusted areas on steel support beams and columns in courtyard between buildings 1 and 2 and rusted gates on exits from courtyard	5	NC	6/30/17
Replace missing evacuation route map showing primary and secondary routes in contrasting colors	0	NC	6/30/20
Replace missing Emergency Evacuation Map indicating primary and secondary evacuation routes in contrasting colors	0	NC	6/30/20
Replace missing evacuation map	1	NC	6/30/20
Replace missing evacuation map	1	NC	6/30/20
Replace missing evacuation route map indicating primary and secondary evacuation routes in contrasting colors	0	NC	6/30/20
Replace missing emergency evacuation map indicating primary and secondary routes in contrasting colors	0	NC	6/30/20
Replace missing evacuation map	1	NC	6/30/20
Eliminate termite infestation in bookcase	0	NC	6/30/21
Post sign indicating primary and secondary evacuation routes in contrasting colors. Office	1	NC	6/30/20
converted to small classroom			

converted to small classroom

Serious Life Safety Citations 0 Non-Serious Safety Citations 10	DEFICIENCY DESCRIPTION AND CORRECT	VE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Non-Serious Safety Citations 10	Serious Life Safety Citations	0			
	Non-Serious Safety Citations				

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair broken metal tension wire for cover to shade structure in playfield east of Bldg. 2	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Modify or improve storm drainage from covered walkway from building 16 to building 8 to prevent storm drainage from running across walkway	5	NC	6/30/20
Replace broken GFCI outlet	0		6/30/21
Joslyn electronic systems box has 3 lights on it. One is illuminated red. Repair	0		6/30/21
Reinsulate chilled water lines to eliminate condensate leak	0		6/30/21
Replace 2 missing riser covers for stairs	0		6/30/21
Repair door at bottom of stairs to open and close properly	0		6/30/21
Repair or replace damaged door. Split on hinge side Caused by blocking open door on hinge side	0		6/30/21
Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	1	NC	6/30/20
Remove and prohibit hanging curtains from ceiling	0		6/30/19
Replace missing slats for window blinds	0		6/30/21
Post sign indicating primary and secondary evacuation routes in contrasting colors	1	NC	6/30/20
Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	1	NC	6/30/20
Post sign indicating primary and secondary evacuation routes in contrasting colors	1	NC	6/30/20
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Post sign indicating primary and secondary evacuation routes in contrasting colors	1	NC	6/30/20
Post sign indicating primary and secondary evacuation routes in contrasting colors	1	NC	6/30/20
Post sign indicating correct primary and secondary evacuation routes in contrasting colors	1	NC	6/30/20
Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	1	NC	6/30/20
Remove storage from mechanical room, floor machine	0		6/30/19
Get oversize plates for GFI outlet and light sensor to cover openings around them	0		6/30/21

Repair hanging soffit at windows	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Provide placard to cover lugs on Tork time clock	0		6/30/21
Secure weather strip to door frame at entry	0		6/30/21
Label all circuits on electrical panel H4A	0		6/30/21
Room converted to classroom and door swing is wrong for both doors. Select a more appropriate room for a classroom in building. Rooms 5-107, 5-114, 5-116 or 5-118	0		6/30/19
Repair exhaust fan in bathroom	0		6/30/21
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair purge fan	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Determine cause of water damaged ceiling tiles and replace tiles	0		6/30/21
Repair leaking plumbing behind water heater	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Maintain playground equipment in safe condition. Replace missing roof covering over equipment. See Coach	3	NC	6/30/18
Make repairs as noted on fire sprinkler inspection report, red annual inspection tag dated May 2018	0		6/30/21
Repair leaky gutters and downspouts throughout campus	2	NC	6/30/19

Indicate primary and secondary evacuation routes on all evacuation maps	6	NC	6/30/18
Replace missing hardware on exterior door at 1-153	0		6/30/21
Repair ventilation fan	0		6/30/21
Repair broken back check device on door	0		6/30/21
Repair exhaust fan at kiln	0		6/30/21
Repair ventilation fan	0		6/30/21
Repair ventilation fan	1	NC	6/30/20
Adjust door to lock properly	0		6/30/21
Repair ventilation fan in bathroom	0		6/30/21
Replace missing window blinds	0		6/30/21
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE

ixon-Serious Sarety Citations 13	Serious Life Safety Citations	0		
	Non-Serious Safety Citations	13		

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Sloped ground at east property line is eroding onto the basketball courts. Stabilize the bank to eliminate erosion and clean sand off of basketball courts	5	NC	6/30/18
Provide dated flame resistance label on main stage curtain	0		
Repair opening in supply duct at air handler	0		6/30/21

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on inspection report. Red annual and yellow quarterly and semi-annual tags	0		6/30/21
Repair rusted column on PE pavilion (column is rusted through next to concrete floor)	1	NC	6/30/19

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair damaged ventilator unit	2	NC	6/30/19

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on annual inspection report dated 4.21.2018	0		6/30/21
Repair exhaust fan in bathroom	1	NC	6/30/20
Provide emergency lighting in testing room	0		6/30/21
Repair exhaust fan in bathroom	1	NC	6/30/20
Repair exhaust fan in bathroom	1	NC	6/30/20
Repair exhaust fan in bathroom	1	NC	6/30/20
Repair exhaust fan in bathroom	1	NC	6/30/20
Repair exhaust fan in bathroom	1	NC	6/30/20
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	1	NC	6/30/20
Repair exhaust fan in bathroom	1	NC	6/30/20
Repair ventilation fan in custodial room	0		6/30/21

Provide vent line for dryer	2	NC	6/30/19
Repair deteriorated and peeling paint of east exterior wall finish at Bldg. 3	0		6/30/21
Repair light in exit sign at 2nd floor covered walkway adjacent to both stairwells (X2)	0		6/30/21
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Serious Life Safety Citations 0 Non-Serious Safety Citations 15			

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Modify or improve drainage in interior courtyard to eliminate standing water. When water evaporates it leaves algae that is very slick. 2 slip and fall accidents to date.	3	NC	6/30/19

Refinish rusty areas of air conditioning duct adjacent to 1-016	0	6/30/21
corridor		

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make repairs as indicated on annual fire sprinkler inspection report dated July 2018	0		6/30/21
Remove rust from and refinish rusted cooling tower plumbing. Pay attention to where pipes exit building	3	NC	6/30/18
Repair runner lights on aisle floor in Auditorium	3	NC	6/30/18
Make repairs as noted on fire pump inspection report dated July 2017	0		6/30/21
Obtain a building permit to provide suitable electrical wiring for all 300 plus computer stations in	1	NC	6/30/21

media center to eliminate piggy backed surge protectors and excessive extension cords

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
No access was available to 1-211, 6-101A, 6-101B and 12-170 (chair lift in building 12). Please provide access to these rooms during the report review meeting	0		6/30/19
Make necessary repairs to fire sprinkler system as indicated on inspection report. Red annual and yellow semi-annual and quarterly tags	0		6/30/21
Post sign indicating primary and secondary evacuation routes in contrasting colors in all classrooms without doors directly to exterior	0		6/30/22
Repair or replace deteriorated guardrail cap for 2nd floor balcony at interior courtyard. Concrete has spalled off and rebar is exposed. Particularly bad at building 2	0		6/30/21
Repair leaking rain gutters throughout facility	0		6/30/21
Repair 1 trouble indicated on fire alarm panel	0		6/30/21

Repair trouble indicated on fire alarm panel	0		6/30/21
Repair roof leaks. Roof metal is rusted through	0		6/30/21
Safety cable all lights and speakers on catwalk	0		6/30/19
Remove and prohibit storage in exit corridor	0		6/30/19
Repair trouble indicated on fire alarm panel	0		6/30/21
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Remove and prohibit storage under stairs	0		6/30/19
Repair motor for OAF 12-2 on AHU 12-2	0		6/30/21
Repair DX unit, blowing out warm air	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	1	NC	6/30/20
Repair rusted and leaky chilled water pipe near ceiling and reinsulate it, standing water on floor	1	NC	6/30/20
Remove storage from electrical room	0		6/30/19
Repair exhaust fan in bathroom	0		6/30/21
Repair A-C condensate leak	0		6/30/21
Replace broken and missing handrail for stairs at 5-134. 2nd run inside handrail	0		6/30/21
Repair emergency escape window to open	0		6/30/21
Clean A-C vent	0		6/30/19
Repair emergency escape window to open properly	0		6/30/21
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Replace missing slats for window blinds	0		6/30/21
Replace missing slats for window blinds  Remove storage from mechanical room	0		6/30/21

Repair leaking air handler	0		6/30/21
Repair damaged hard ceiling in corridor in Girls Locker room	0		6/30/21
Reinstall damper motors for outside air dampers in Gym	0		6/30/21
Replace light tubes in light fixture	0		6/30/19
Repair or replace rusted and leaking chilled water piping (standing water on floor from leak) Reinsulate chilled water line	1	NC	6/30/20
Provide window blinds for window by door to exterior	0		6/30/21
Raise heat detector to bottom of deck above	0		6/30/21
Make necessary repairs to fire pump - red tag dated 8-8-17	1	NC	6/30/20
Modify or improve storm drainage to go away from portables and not underneath portables	5	NC	6/30/23

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair uneven areas of basketball court to eliminate tripping hazards, most noticeable at sidewalk entrance to court	0		6/30/21
Replace missing motor guard cover for P-1	0		6/30/21
Replace rusty support brace for electrical unit adjacent to 2-194	0		6/30/21
Replace missing nosing on upper run of stairs	0		6/30/21
Fill cracks in exterior wall above 2nd floor doors	0		6/30/21
Replace missing carpet square piece in aisle between cubicles	1	NC	6/30/20
Replace missing floor tiles at AC unit	0		6/30/21

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Provide covered walkway to portables P-12, P-14, and P-16	6	NC	6/30/21
Repair damaged rain gutters in courtyard between buildings 5 and 7	2	NC	6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on annual inspection report dated 9.26.18	0		6/30/21

<sup>-</sup> Piping and check valves are due for interior inspection

#### Total Serious Life Safety Citations Total Non-Serious Safety Citations

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Insulate impeller housing for chilled water pump in Chiller Compound	1	NC	6/30/20

#### Total Serious Life Safety Citations Total Non-Serious Safety Citations

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair exhaust fan in bathroom	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE

Stabilize soil banks at track to prevent sand from running onto track	0		6/30/21
Communication closet very hot and door has to be propped open. Repair A-C unit in ceiling	0		6/30/21
Provide mechanical ventilation or verify range is vented to exterior and close return vent from range into room	5	NC	6/30/19
Provide drainage at intermediate landing to eliminate standing water	7	NC	6/30/19
Prohibit charging batteries in corridor	0		6/30/19
Eliminate non 15A cord amp extension cord used to charge batteries	0		6/30/19
Modify bottom step of bleachers so rise is the same as other steps. 7 inch difference	14	NC	6/30/19
Missing floor tile at floor drain and broken floor tile. Replace broken and missing tiles or grout these areas	0		6/30/21
Remove and prohibit storage in west exit corridor	0		6/30/19
Remove chain and padlock from gate with panic bar at bottom of stairs	0		6/30/19

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on inspection report. Red annual and yellow semi-annual and quarterly tags	0		6/30/21
Repair outside air intake motor	0		6/30/21
Eliminate Iguanas living under portable	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair lights in parking lot to work properly. Only one bulb is working	0		6/30/21

Make necessary repairs to fire sprinkler system as indicated on annual inspection report dated 9.26.18	0		6/30/21
Provide automatic fire sprinkler coverage for closet in room	2	NC	6/30/21
Provide automatic fire sprinkler coverage for room. No label on door, no fire sprinkler heads, heat detector at ceiling and plan indicates 1 hour walls	2	NC	6/30/21
Provide automatic fire sprinkler coverage for room. 20 minute door, heat detector at ceiling, no fire sprinkler head and plan indicates 1 hour walls	2	NC	6/30/21
Adjust door to walk-in cooler to latch properly	2	NC	6/30/19

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair damaged masonry bench at north end of bus loop	0		6/30/21
Anchor or remove 2 shipping containers at track	2	NC	6/30/19
Repair exhaust fan in bathroom	2	NC	6/30/19
Repair exhaust fan in bathroom	2	NC	6/30/19
Replace missing thumb latch to on bathroom stall door	1	NC	6/30/19
Repair exhaust fan in bathroom	2	NC	6/30/19
Repair exhaust fan in bathroom	2	NC	6/30/19
Repair ventilation fans for all cook ranges in culinary lab	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Post sign indicating primary and secondary evacuation routes in contrasting colors	1	NC	6/30/22
Repair inoperable purge fan	2	NC	6/30/19
Repair exhaust fan in boys bathroom	0		6/30/21
Repair exhaust fan in girls bathroom	0		6/30/21
Repair ventilation fan in custodial room inside 1-158C	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair ventilation fan in custodial room inside 1-149C	0		6/30/21
Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	1	NC	6/30/22
Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	1	NC	6/30/22
Post sign indicating primary and secondary evacuation routes in contrasting colors	2	NC	6/30/22
Make necessary repairs to fire sprinkler system as indicated on inspection report 10.19.18	0		6/30/21
Repair exhaust fan in bathroom	2	NC	6/30/19
Repair exhaust fan in bathroom	2	NC	6/30/19

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Replace worn exterior signage indicating property address	0		6/30/21

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Modify all emergency lighting so that no room may be left in darkness if single bulb fails	23	NC	6/30/19
Repair exhaust fan in boys bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	2	NC	6/30/19
Repair exhaust fan in bathroom	2	NC	6/30/19
Repair exhaust fan in bathroom	0		6/30/21

Repair exhaust fan in bathroom	1	NC	6/30/20

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21

## Total Serious Life Safety Citations Total Non-Serious Safety Citations

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Modify or improve drainage to eliminate standing water in NW parking lot	12	NC	6/30/20
Modify handrails along stairs to be continuously graspable - East and West stairs (X2)	24	NC	6/30/23
No violations observed. Building secured and not in use.			
Post signs indicating primary and secondary evacuation routes in contrasting colors for classrooms on 1st and 2nd floor in Bldg. 2	1	NC	6/30/19
Provide handrails on each side of stairs (X2)	12	NC	6/30/19
No violations observed. Building is secured and not in use.			

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Provide correct sign indicating primary and secondary evacuation routes in contrasting colors - current sign is upside down	0		6/30/20
Replace missing evacuation map sign indicating primary and secondary evacuation routes in	0		6/30/20

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on inspection report. Red annual and yellow quarterly tags	0		6/30/21
Repair exhaust fans in bathrooms 1-128B through 1-135B and 1- 139B through 1-143-B and 1-137A	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair broken window blinds	0		6/30/21
Repair broken window blinds	1	NC	6/30/20
Modify or improve storm drainage from portables. Water currently goes under units. Drains are	5	NC	6/30/19

missing caps, drain pipe is broken and pipes are full of rocks and dirt

#### Total Serious Life Safety Citations Total Non-Serious Safety Citations

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on inspection report (annual report dated 12-21-17)	0	NC	6/30/21
Modify evacuation route maps in all classromms to show both primary and secondary evacuation	5	NC	6/30/18

routes (current maps show only a primary route, a secondary route should also be shown in a different color)

	DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
1				

Modify or improve storm drainage from covered walk at main entry and bus loop to prevent storm drainage from running across sidewalks	5	NC	6/30/19
Modify or improve site drainage to eliminate standing water on basketball court	5	NC	6/30/19
Eliminate poison ivy growing in shrubs at parent pick-up	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Secure spout to low drinking fountain at bathrooms in Cafeteria	0		6/30/21
Repair exhaust fan	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Remove rust and prime steel frame under chillers. Coil support frame work extremely rusted and cannot be repaired	2	NC	6/30/19
Repair exhaust fan in flammable storage room	0		6/30/21
Repair exhaust fan	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Campus is secure and no longer in use. Buildings need to be inspected before future use, including fire alarm system	0		
No violations observed - Building not in use			
No violations observed - Building not in use			

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE

Make repairs as noted on fire sprinkler inspection report, red annual inspection tag dated October 2018	0		6/30/21
Provide emergency disconnect valve for water in all science rooms (1-131, 1-134, 1-146, 1-158, 1-162, 1-182 and 1-190)	1	NC	6/30/22
Repair leaking rain gutters and downspouts	3	NC	6/30/18
Post signs indicating primary and secondary evacuation routes in contrasting colors for all student occupied spaces in Building 1	1	NC	6/30/23
Repair exhaust fan above cooking range to vent to the exterior - fan blows back into room. The exhaust duct is visible above the range	1	NC	6/30/20
Repair exhaust fan in bathroom	1	NC	6/30/20
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	1	NC	6/30/20
Repair exhaust fan in bathroom	1	NC	6/30/20
Repair exhaust fan in bathroom	3	NC	6/30/18
Repair exhaust fan in bathhroom	2	NC	6/30/19

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on annual inspection report 10.26.18	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	2	NC	6/30/19
Repair exhaust fan in all individual bathrooms in Bldg. 6	0		6/30/21
Repair exhaust fan in bathrooms 8-801A, 8-802A, 8-813A and 8-815A	2	NC	6/30/19
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	1	NC	6/30/20

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Replace missing and grout cracked floor tile	0		6/30/21

### Total Serious Life Safety Citations Total Non-Serious Safety Citations

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on inspection report. Red annual and yellow quarterly and semi-annual tags	0		6/30/21
Restripe parking lot	0		6/30/22

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair pump 2 in chiller cpompound	0		6/30/21
Metal pump stand for pump 2 in Chiller Compound holds water Drill hole in stand to drain water. Stand badly rusted. Refinish stand	0		6/30/21
Make necessary repairs to fire sprinkler system as indicated on inspection report. Red annual and yellow quarterly tags	0		6/30/21
Remove rust from and refinish rusted column to truss connections for fabric roofed play area	0		6/30/21
Old tires south of portables hold water. This provides a breeding area for mosquitos. Remove tires from site or drill holes in tires so that they do not hold water	0		6/30/19
Remove old damaged picnic tables at NW campus	0		6/30/19
Replace missing piece of base tile at entry	0		6/30/21

Repair trouble indicated on fire alarm panel	0		6/30/21
Key from key box unlocks secure testing materials storage room. Change lock	0		6/30/21
Provide dated flame resistance certification for stage curtain (last date on certification was April 27, 2012)	1	NC	6/30/20
Remove storage from mechanical room. Chalk marker and hoses	0		6/30/19
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Fill drop off at edge of concrete walk south side of building 2	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Area drains for P-A through P-L are filled with dirt and water coming out of downspouts is undermining rear landings. Repair drains	0		6/30/21
Modify or improve site drainage to take rain water away from portables. Currently rain water goes under units and is undermining landings and foundations	8	NC	6/30/19
Remove and prohibit excessive flammable decorations on walls.  20 percent of the walls can be covered with paper	0		6/30/19
Secure faucet to sink in bathroom	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Existing parking is not adequate. Provide more parking spaces.	0	NC	6/30/23
Make necessary repairs to fire sprinkler system as indicated on inspection report. Red annual and yellow semi-annual and quarterly tags	0		6/30/21
Repair or replace rusted goal posts at football field. Rust has been painted over. Remove rust, prime and refinish goal posts or replace them if they are to damaged	1	NC	6/30/21
Post sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/22

Relocate sprinkler head to under side of roof deck and provide correct head	2	NC	6/30/19
Remove chain and padlock from gate with panic bar south of 3- 199A	0		6/30/19
Remove and prohibit storage in exit corridor from Varsity Locker Room	0		6/30/19
Prohibit storage of gasoline or gas powered equipment	0		6/30/19
Replace missing door handle on inside of door	0		6/30/21
Insulate chilled water line at pump	0		6/30/21
Repair exhaust fan in electrical room	0		6/30/21
Remove chain and padlock from gate with panic bar north of building 4	0		6/30/19
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Cover exposed welded wire mesh at 2nd floor landing of stairs	0		6/30/21
Eliminate standing water on stair landings	0		6/30/21
Remove rust from, patch, prime and refinish rusting areas of stairs	0		6/30/21
Eliminate standing water on stair landings	0		6/30/21
Remove rust from, prime and refinish rusting areas of stairs	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair broken window blinds	0		6/30/21
Repair or replace surge suppressors for electrical panels H43 section 1 and EQH43	0		6/30/21
Properly grade and sod landscape area to prevent sand accumulation along sidewalk at NE corner of Bldg. 5. Roof drains empties on ground and erodes soil	2	NC	6/30/19
Post sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/22
Post sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/22
Post sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/22
Prohibit storage of gasoline and propane. Store in flammable storage cabinet. Storage room at	0		6/30/19

#### baseball field

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair large horizontal gap in concrete retaining wall under patio on west side of Building 6. Fill gap between wall and patio deck to prevent water intrusion	1	NC	6/30/20
Remove rust from, patch, prime and refinish rusted areas on stairs	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Relocate desks to maintain clear aisle to exit	0		6/30/19
Post sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/22
Remove and prohibit tables and chairs at west exit to exterior from Auditorium	0		6/30/19
Prohibit hold open devices on fire doors at north end of corridor	0		6/30/19

## Total Serious Life Safety Citations Total Non-Serious Safety Citations

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on inspection report (Annual Inspection tag dated 9-18-18)	0		6/30/21
Remove peeling paint from under PE Pavilion roof and repair cause of paint peeling (large paint chips falling on PE Pavilion floor causing slipping hazard)	0		6/30/21

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Post sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/20
Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/20

Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/20
Modify or improve storm drainage from portables to stop drainage from going under units and eroding	2	NC	6/30/20
sand onto play court			

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on inspection report (annual inspection dated 2-18-18, red tags on risers)	0		6/30/21
Re-insulate impeller housing for chilled water pump in Chiller Compound	1	NC	6/30/20
Repair broken window blinds	0		6/30/21
Re-insulate hot water pipes	1	NC	6/30/20

#### Total Serious Life Safety Citations Total Non-Serious Safety Citations

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on inspection report	0		6/30/21

#### Total Serious Life Safety Citations Total Non-Serious Safety Citations

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Provide exhaust fan in custodial closet	1	NC	6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES	PRIOR	CORRECTIVE
	CITED PREV.	FY STAT	ACTION DATE
Replace burned out light bulbs in light fixtures along all covered walkways and in stairwells through out campus	0		6/30/21
Make necessary repairs to fire sprinkler system as indicated on annual inspection report dated 5.25.18	0		6/30/21
Replace missing call buttons for Emergency Areas of Rescue Assistance at each end of 2nd floor corridor	10	NC	6/30/18
Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	2	NC	6/30/23
Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	1	NC	6/30/23
Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	2	NC	6/30/23
Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	1	NC	6/30/23
Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/22
Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/22
Repair emergency escape window to open and close properly	0		6/30/21
Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/22
Repair ventilation fan in custodial room	0		6/30/21
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair or replace roof access hatch to prevent leaks (latch does not seal properly)	3	NC	6/30/18
Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/22
Replace missing call buttons for Emergency Areas of Rescue Assistance at each end of 2nd floor corridor	10	NC	6/30/18
Repair problems with fire alarm system - Troubles indicated on panel	0		6/30/21
Post sign indicating primary and secondary evacuation routes in contrasting colors	2	NC	6/30/23
Repair ventilation fan in custodial room adjacent to boys and girls group bathrooms	0		6/30/21

Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/22
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan	2	NC	6/30/19
Repair elevator at pressbox	6	NC	6/30/16
Provide current inspection certificate for boiler, certificate expired in 2015. 650,000 BTU	1	NC	6/30/20

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair rusty, damaged rain gutters and downspouts throughout campus	4	NC	6/30/23
Post signs indicating primary and secondary evacuation routes in contrasting colors for all student occupied spaces throughout building	1	NC	6/30/21
Repair uneven concrete walkway around tree in center of interior courtyard	1	NC	6/30/20
Repair loose door handle and inoperable lock	0		6/30/21
Provide lock with means of egress on gate for cage area	0		6/30/21
Make repairs as noted on fire sprinkler inspection report. Provide current annual inspection tag	0		6/30/21

### Total Serious Life Safety Citations Total Non-Serious Safety Citations

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Provide automatic fire sprinkler coverage for room. Sprinkler head not visible	1	NC	6/30/20

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			

No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			
No violations observed (not in use)			
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
No violations observed (not in use)			

No violations observed (not in use)		

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Modify or improve site drainage to eliminate standing water on play courts	3	NC	6/30/19
Repair leaking air conditioning system to ensure it operates as designed	0		6/30/21
Repair or replace heavily rusted door frame	1	NC	6/30/20
Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/22
Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/22
Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/22
Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/22
Repair or replace broken window blinds	0		6/30/21

## Total Serious Life Safety Citations Total Non-Serious Safety Citations

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair broken window blinds	0		6/30/21
Repair broken window blinds	0		6/30/21
Make necessary repairs to fire sprinkler system as indicated on inspection report dated 10-16-18	0		6/30/21

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE

Indicate primary and secondary routes in contrasting colors on all evacuation maps	6	NC	6/30/25
Remove and prohibit flammable curtains and window coverings	0		6/30/19
Provide current dated flame resistance label on stage curtain	0		6/30/21
Prohibit use of bleach	0		6/30/19
Prohibit plugging surge protector into surge protector at student computers	0		6/30/19
Modify or improve storm drainage to take water away from portables. Currently storm water is going under units	6	NC	6/30/19
Eliminate termites and repair termite damage	3	NC	6/30/18
Remove and prohibit flammable curtains and window coverings	0		6/30/19

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair exhaust fan in bathroom	1	NC	6/30/20
Repair exhaust fan in bathroom	1	NC	6/30/20
Repair exhaust fan in bathroom	1	NC	6/30/20
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	1	NC	6/30/20
Repair exhaust fan in bathroom	1	NC	6/30/20
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan at kiln to allow fan to be controlled by school staff as needed	0		6/30/21
Repair exhaust fan in bathroom	1	NC	6/30/20
Repair exhaust fan in bathroom	1	NC	6/30/20
Repair exhaust fan in bathroom	1	NC	6/30/20

Repair exhaust fan in bathroom	1	NC	6/30/20
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair exhaust fan in bathroom	1	NC	6/30/20
Repair exhaust fan in bathroom	1	NC	6/30/20
Repair exhaust fan in bathroom	1	NC	6/30/20
Repair exhaust fan in bathroom	1	NC	6/30/20
Repair exhaust fan in bathroom	1	NC	6/30/20
Repair exhaust fan in bathroom	1	NC	6/30/20
Repair exhaust fan in bathroom	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair damaged rain gutters in courtyard at the corner of Building 6 and 7 and remove mold from column caused by leaking gutter	0		6/30/21
Repair leaking rain gutter at downspout at entry to building	1	NC	6/30/20
Fire sprinkler head not visible in closet. Provide fire sprinkler head in closet	1	NC	6/30/24
Repair leaking rain gutter at downspout north of 2-102	1	NC	6/30/20
Replace missing insulation on water pump in chiller enclosure	0		6/30/21
Replace missing insulation on valve on chilled water supply line on AHU10-1	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on annual inspection report dated 6.26.18	0		6/30/21
Provide automatic fire sprinkler coverage for room or provide 2 hour rated fire walls to underside of roof deck	2	NC	6/30/20
Modify or improve storm drainage at M-1 through M-6 to prevent storm drainage from going under portables	2	NC	6/30/19

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Stabilize soil and provide ground cover to prevent continuous erosion of dirt and sand in area between sidewalks on north side of buildings 9 and 10, adjacent to building 14. Sidewalk is covered with dirt and sand creating a slippery surface	0		6/30/21
Replace missing signs indicating primary and secondary evacuation routes in contrasting colors in rooms 1-112, 1-113, 1-114, 1-115, 1-122, 1-124, 1-130, 1-131, 1-202, 1-210, 1-216, 1-217, 1-218, 1-224, 1-225, 1-228, 1-229, 1-230, 1-232, 1-234, 1-236,	0		6/30/24
Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/24
Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/24
Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/24
Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/24

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make repairs as noted on fire sprinkler inspection report, semi annual inspection tag dated August	0		6/30/21
2010			

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Provide dated flame resistance certification on stage curtain (date on last certification is 6-5-11)	1	NC	6/30/20
Repair leaking plumbing on top of tank at valve and union	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Set mixing valve so that water temperature at showers is maximum 110 degrees	0		6/30/21
Repair leaking plumbing above hot water storage tanks	0		6/30/21
Repair exhaust fan in flammable storage room	2	NC	6/30/19

### Total Serious Life Safety Citations Total Non-Serious Safety Citations

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on inspection report. Red annual and yellow quarterly and semi-annual tags	0		6/30/21
Modify or improve site drainage at walkway between Building 4 and portable classroom units (area gets flooded when it rains because water has no where to drain)	1	NC	6/30/20
Outside air intake in Gym is one quarter open and actuator motor is damaged. Repair motor	0		6/30/21
Repair exhaust fan inside flammable storage room	1	NC	6/30/20

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler systems as indicated on Annual inspection report dated 8-31-18	0		6/30/21
(building 3 and 5)			

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair bleachers as instructed in the Bleacher Structural Inspection Report. Contact Patrick Joyce if questions occur.	3	NC	6/30/18
Repair uneven areas of concrete at benches in sitting area west of 13-101	0		6/30/21
Repair exhaust fan in bathroom	3	NC	6/30/18
Replace broken glass in atrium dome outside 17-100	5	NC	6/30/17
Provide covered walkway to portables	16	NC	6/30/18

### Total Serious Life Safety Citations Total Non-Serious Safety Citations

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Modify or improve drainage in west parking lot to eliminate standing water in 2 locations at north end of parking lot	5	NC	6/30/19
Modify or improve drainage to eliminate standing water on asphalt at bus loop	4	NC	6/30/19

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE

Post secondary evacuation route for evacuation maps in 1-201, 1-203, 1-205, 1-207, 2-201, 2-203, 2-205, 2-206, 2-207, 2-209, 3-111, 3-113 and 3-116.	2	NC	6/30/17
Replace missing grille filter for exhaust fans above cook range (X3)	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in custodial room	0		6/30/21
Repair exhaust fan in elevator machine room	0		6/30/21
Post sign indicating primary and secondary evacuation routes in contrasting colors.	2	NC	6/30/17
Repair exhaust fan in custodial room	0		6/30/21
Make manhole cover level with concrete in courtyard adjacent to SW cover of Bldg. 5	0		6/30/21
Adjust door of walk in freezer to close and latch properly	1	NC	6/30/20
Replace missing latches for doors of electrical panels 5KP1 and 5KP2 located adjacent to 5-104B	1	NC	6/30/20
Repair damaged weather strip on exit doors in gym lobby adjacent to girls bathroom 6-101D. Weather strip adjacent to latch hardware is bent	0		6/30/21
Adjust SW exit doors to lobby to latch properly	0		6/30/20
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED	PRIOR FY STAT	CORRECTIVE ACTION DATE
	PREV.		
Yard drains for portables are filled with dirt and debris. Water comes out of downspouts and goes under portables and is wicked up into concrete wall. Disconnect downspouts from yard drains and provide splash blocks and down spout extensions to get water away from portables	2	NC	6/30/19
Repair deteriorated wall finish adjacent to east exit	0		6/30/21
Repair broken vinyl base along wall adjacent to bathroom door	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE

Make necessary repairs to fire sprinkler system as indicated on annual inspection report dated 11.28.18	0		6/30/21
Provide insulated cover for exposed electrical outlet under serving area (X2)	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair damaged laminate on inside face of classroom door	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Determine cause of water damaged ceiling tiles and replace tiles	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair leaking air handler	1	NC	6/30/20
Repair exhaust fan in bathroom	0		6/30/21
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in Custodial closet	1	NC	6/30/20

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES	PRIOR	CORRECTIVE
	CITED	FY STAT	ACTION DATE
	PREV.		

Make necessary repairs to fire sprinkler system as indicated on	0	6/30/21
inspection report (systems have red		
annual and yellow quarterly tags)		

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Provide suitable area for storage of flammables. No flammable storage room on campus.	5	NC	6/30/19
Re-stripe and re-mark SW parking lot	2	NC	6/30/19
Remove rust from and refinish rusting chilled water plumbing	2	NC	6/30/19
Repair or replace badly rusted guardrail at top of cooling tower	2	NC	6/30/19
Immediately repair emergency escape window to open properly - missing hardware. Window does not	0		6/30/20
open	1	1 1	

### Total Serious Life Safety Citations Total Non-Serious Safety Citations

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair exhaust fan in girls bathroom	0		6/30/21
Repair exhaust fan in boys bathroom	0		6/30/21
Repair ventilation fan in custodial room	0		6/30/21
Remove rust and repaint roof, trusses and columns at P.E. Pavilion	5	NC	6/30/17
Repair exhaust fan in girls bathroom	0		6/30/21
Replace broken and missing roof tiles above 4-171	2	NC	6/30/19

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Modify or improve site drainage to eliminate standing water on play court adjacent to pavillion	13	NC	6/30/20
Repair uneven concrete walks in interior courtyard between Bldg. 6 and east exit gate to bus loop	0		6/30/21
Provide current inspection report for fire pump and make any necessary repairs if needed. Last inspection date was 10.16.17	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair or replace rusted door to play area	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair or replace broken and missing window blinds in the following rooms 1-141, 1-147, 1-151, 1-153, 1-155, 1-157, 1-160, 1-161, 1-167, 1-168	0		6/30/21
Modify all emergency lighting so that no room may be left in darkness if single bulb fails	1	NC	6/30/23
After installation of new blinds remove and prohibit flammable curtains and window coverings over windows and exterior doors in classrooms	0		6/30/19
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/22
Repair exhaust fan in bathroom	3	NC	6/30/18
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in girls bathroom	1	NC	6/30/20
Repair exhaust fan in bathroom	0		6/30/21
Once new lock is installed on gate at cage area remove chain and padlock gate for cage area	0		6/30/19
Provide handle with lock on gate for cage area to allow egress from inside cage	0		6/30/21

Repair ventilation fan	0		6/30/21
Repair ventilation fan	0		6/30/21
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair leaking air conditioning system to ensure it operates as designed	0		6/30/21
Repair ventilation fan	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES	PRIOR	CORRECTIVE
	CITED PREV.	FY STAT	ACTION DATE
Repair leaning, damaged chain link fencing at staff parking lot east of bus loop	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Post sign indicating primary and secondary evacuation routes in contrasting colors	1	NC	6/30/19
Replace missing cover for AC vent in ceiling	0		6/30/21
Repair ventilation fan	0		6/30/21
Remove corrosion from top of Air handler on AHU 10-1	2	NC	6/30/19
Repair or replace rusty areas of chillers including bolts and fence top rail on water tower units	0		6/30/21
Replace badly rusted anchor bolts and nuts that hold greenhouse to block wall. Use stainless steel connectors	6	NC	6/30/20
Improve green house floor drainage to eliminate standing water	1	NC	6/30/20
Repair ventilation fan	0		6/30/21
Replace missing nosing on lower run of stairs	0		6/30/21
Post sign indicating primary and secondary evacuation routes in contrasting colors	1	NC	6/30/19
Patch crack at top of stairwell wall - 2nd floor	1	NC	6/30/20

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair or replace corroded ductwork on air handler unit	2	NC	6/30/19
Repair exhaust fan in bathroom	0		6/30/21
Repair purge fan	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Make repairs as noted on fire pump inspection report, red annual tag dated November 2017	0		6/30/21
Repair broken window blinds	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Label all circuits on electrical panel G	0		6/30/21
Repair exhaust fan	0		6/30/21
Replace missing fan grate	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Provide non-slip surface for ramp	1	NC	6/30/20
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on inspection report. Red annual tag and yellow quarterly and semi-annual tags	0		
Replace rusted door handle	0		6/30/21
Replace rusted door handle	0		6/30/21

### Total Serious Life Safety Citations Total Non-Serious Safety Citations

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Post sign indicating primary and secondary evacuation routes in contrasting colors in all classrooms without doors directly to the exterior. Many maps have identical primary and secondary routes	2	NC	6/30/20
Repair exhaust fan in bathroom	1	NC	6/30/20
Repair exhaust fan in bathroom	1	NC	6/30/20
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair purge fan	1	NC	6/30/20

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Provide current state inspection tag for boiler, expired June 2017	0		6/30/21
Provide current certification that all student occupied spaces have emergency lights and all are operable, certificate dated July 2017	0		6/30/21

Repair leaking air conditioning system to ensure it operates as	0	6/30/21
designed		

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES	PRIOR	CORRECTIVE
	CITED PREV.	FY STAT	ACTION DATE
Provide suitable area for storage of flammables and gas powered equipment	4	NC	6/30/18
Repair bleachers as instructed in the Bleacher Structural Inspection Report. Contact Patrick Joyce if questions occur.	0		6/30/21
Provide swale to drain to eliminate need to use sand bags at door to 1-125 to prevent water intrusion into room	2	NC	6/30/19
Modify or improve site drainage to eliminate sand running across sidewalk along west side of media center	0		6/30/21
Repair damaged metal nosing at exterior stairs located west of media center corridor 1-003	0		6/30/21
Post sign indicating primary and secondary evacuation routes in contrasting colors for all 2nd floor classrooms	0		6/30/20
Adjust fire door to open latch properly - north end of 2nd floor corridor	0		6/30/20
Repair or replace rusted hot water heater	0		6/30/21
Provide ventilation fan in pool equipment room - north end. All metal is rusting. Install fan outside of room to force air into room	2	NC	6/30/19
Adjust exterior mechanical room door hardware to work properly - atch hardware sticks	0		6/30/21
Replace damaged weather strip and repair rusted frame for door glazing - auditorium lobby east exit door	0		6/30/21
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Provide cover on exposed electrical junction boxes for auditorium spotlights at front catwalk above auditorium (X3)	0		6/30/21
Determine cause of water damaged ceiling tiles and replace tiles outside control booth 14-218	0		6/30/21
Repair broken auditorium seat C8 - 3rd row at north end	0		6/30/21

Repair or replace rusted hot water heater	0		6/30/21
Secure loose cylinder lock on staff bathroom door	0		6/30/21
Provide certification that all student occupied spaces have emergency lights and all are operable through out campus	0		6/30/21
Make necessary repair to emergency generator - panel indicates low oil level	0		6/30/21
Repair deteriorated wall finish at second floor window	1	NC	6/30/20
Repair rusty duct for air conditioning system to ensure it operates as designed - above hot water heater	1	NC	6/30/20
Replace broken glass in window on second floor stair landing and replace rusted out glass stops outside of window	3	NC	6/30/18
Replace cracked wire glass in stairwell window - 3rd floor landing	0		6/30/21
Determine cause of water damaged ceiling tiles and replace tiles above serving area	0		6/30/21
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Determine cause and repair water leak along wall adjacent to back sink - see teacher	0		6/30/21
Determine cause of water damaged ceiling tiles and replace tiles	0		6/30/21
Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	1	NC	6/30/24
Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/20
Repair damaged illuminated exit sign in 2nd floor corridor adjacent to 2-207	0		6/30/21
Provide automatic fire sprinkler coverage for room. Room has heat detector. Walls not marked to indicate fire rating, door label missing, door louver has fusible link and no closer on door	2	NC	6/30/24
Repair uneven and cracked flooring in 1st floor corridor	0		6/30/21
Repair or replace leaking water heater	2	NC	6/30/19
Post sign indicating primary and secondary evacuation routes in contrasting colors in all 1st floor classrooms	0		6/30/20
Provide automatic fire sprinkler coverage for room. Has heat detector	2	NC	6/30/24

Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	1	NC	6/30/24
Repair south door to open and close properly - hard to open	0		6/30/20
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Post sign indicating primary and secondary evacuation routes in contrasting colors for all classrooms in Bldg.	0		6/30/20
Modify or improve drainage at portables. Storm water ends up under portables	2	NC	6/30/24

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Restripe parking lot and bus loop	0		
Pressure clean play court	0		6/30/21
Repair leaking toilet supply lines in rooms 1-120A, 1-127A, 1-129, 1-134B, 1-135 (handicapped toilet and toilet next to it), 1-201A, 1-203A, 1-203B, 1-204C, 1-208B, 1-214, 1-215 and 1-220C	0		6/30/21
Secure handrails along ramp for exterior Stage	0		6/30/21
Remove storage from mechanical room	0		6/30/21
Repair broken window blinds	1	NC	6/30/20
Repair leaking toilet supply lines in rooms 3-101A, 3-103A, 3-104A, 3-106A, 3-107A, 3-107B, 3-108A and 3-111A	0		6/30/21
Repair leaking drinking fountain on south exterior wall of building	0		6/30/21
Repair leaking toilet supply lines for toilets in rooms 4-101B, 4-101C, 4-102, 4-103A, 4-104, 4-105A, 4-108A and 4-110A	0		6/30/21
Adjust north door to exterior to latch properly	0		6/30/21
Provide new flame resistance label on CCTV curtain (date on current certificate is May 2, 2012)	1	NC	6/30/20
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE

Serious Life Safety Citations Non-Serious Safety Citations	1		
Non-Serious Safety Citations	10		

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Refinish or replace rusty areas of duct on AHU	2	NC	6/30/19
Fire sprinkler head is too low. Raise head to be closer to ceiling	1	NC	6/30/20

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair sticky latch on door. Door cannot be locked	0		6/30/21

Remove rust, prime and paint steel framing at PE pavilion	2	NC	6/30/19
Pigeons are nesting in roof structure of covered play area. Eliminate pigeons	0		6/30/21
Repair exhaust fan in bathrooms 5-111A and 5-112A	0		6/30/21
Repair exhaust fan in bathroom2 5-101A and 5-102A	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Provide covered walkway to portable entrance doors, walkway stops between some portables and doesn't cover all entrance doors	7	NC	6/30/20
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	2	NC	6/30/19
Replace missing grille on exhaust fan in bathroom	0		6/30/21
Remove rust from and refinish rusty pump stands	2	NC	6/30/19
Repair ventilation fan in flammable storage room	1	NC	6/30/20
Repair exhaust fans in bathrooms 4-148A and 4-148B	2	NC	6/30/19
Repair exhaust fan in bathroom	1	NC	6/30/20
Refinish or repair rusty areas of air handler and ductwork to ensure system operates as designed	1	NC	6/30/20
Repair light in exit sign in serving area (X2)	0		6/30/21
Repair emergency lighting above front door	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE

Repair leaking air conditioning system to ensure it operates as designed	0		6/30/21
Repair ventilation fan in bathroom	1	NC	6/30/20
Repair exhaust fan in custodial room	3	NC	6/30/18
Refinish rusty areas of air conditioning duct at ceiling to ensure system operates as designed	0		6/30/21
Repair damaged concrete walk at exterior door adjacent to 2-180	0		6/30/21
Repair ventilation fan	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make repairs as noted on fire sprinkler inspection report, red annual inspection tag dated December	0		6/30/21
2017	1	'	'

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Post signs indicating primary and secondary evacuation routes in contrasting colors in student occupied areas	3	NC	6/30/19
Drain grate at doors to exterior through out campus are slick.  Abrasive finish has worn off. Refinish or replace grates to provide slip resistant finish.  Female Coach indicated several students have slipped and fallen on the grates	1	NC	6/30/22
Repair or replace heavily damaged kitchen exterior door and frame - Rusted door frame and gap at bottom of door	3	NC	6/30/18
Repair or replace damaged, rusted door frame	2	NC	6/30/19
Repair damaged walls at base to provide impervious finish	1	NC	6/30/20

Provide covered walkway to portables	16	NC	6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair uneven pavers in courtyard	0		6/30/21
Provide cover on sunken gutter or raise grate to be even with ground located on the north side of Building 6 to prevent tripping hazard	0		6/30/21
Replace belt guard for outside air intake motor	1	NC	6/30/20
Repair or replace rusted through door frame	1	NC	6/30/20
Repair exhaust fan for bathrooms 7-709B, 7-710B, 7-713B and 7-716B	1	NC	6/30/20
Repair or replace badly rusted door on generator room	0		6/30/21
Modify or improve storm drainage at portables to prevent water from going under portables	1	NC	6/30/21

### Total Serious Life Safety Citations Total Non-Serious Safety Citations

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Replace missing guardrail section at loft	0		6/30/21

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Provide current inspection tag for fire sprinkler system and make any necessary repairs if indicated on report (red Annual tag and yellow quarterly tags attached, no signatures on rear of tags)	0		6/30/21

Relocate sprinkler heads to be minimum 4 inches away from walls. Head at 1-162G	1	NC	6/30/20
No violations observed (Currently used by 21 CCLC offices)			
No violations observed (Currently used by 21 CCLC offices)			
No violations observed (Currently used by 21 CCLC offices)			
No violations observed (Currently used by 21 CCLC offices)			
No violations observed (Currently used by 21 CCLC offices)			

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make repairs as noted on fire sprinkler inspection report, red annual inspection tag dated November 2018	0		6/30/21
Repair extremely noise ventilation fan	0		6/30/21
Provide ground cover system which will resist extremely high foot traffic, for dirt area between	0		6/30/24

basketball courts and PE Pavilion. Dirt is being tracked onto concrete play area under pavilion which creates a very slippery surface. Dirt area is currently covered by area rugs placed by school staff

#### Total Serious Life Safety Citations Total Non-Serious Safety Citations

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on annual inspection report dated July	0		6/30/20
2018			

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Post sign indicating primary and secondary evacuation routes in contrasting colors in all classrooms in Buildings 3,4 and 5	3	NC	6/30/19
Replace broken base tile in girl's restroom	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair broken window blinds	0		6/30/21
Repair broken window blinds	0		6/30/21
Repair broken window blinds	0		6/30/21
Repair broken window blinds	0		6/30/21
Repair broken window blinds	0		6/30/21

#### Total Serious Life Safety Citations Total Non-Serious Safety Citations

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair ventilation fan in girl's restroom	0		6/30/21
Modify or improve drainage at portables 1 through 6 to prevent storm water from going under portables.	1	NC	6/30/22

#### Regrade soil and grout gap between portables and foundations

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Modify or improve site drainage to eliminate standing water at north side of bus repair canopy	3	NC	6/30/21

Repair or replace damaged rain gutter on east and west sides of	0	6/30/21	
driver's pavilion			

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	1	NC	6/30/22
Post sign indicating primary and secondary evacuation routes in contrasting colors. Instructional space in media center	0		6/30/20
Post sign indicating primary and secondary evacuation routes in contrasting colors	1	NC	6/30/22

### Total Serious Life Safety Citations Total Non-Serious Safety Citations

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make repairs as noted on fire sprinkler inspection report, yellow semi annual tag dated July 2018	0		6/30/21
Bldg. is boarded and not in use			

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21

Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Modify or improve storm drainage to prevent rain water from going under all portable units	5	NC	6/30/18

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
School is not occupied at this time. All utilities, fire alarm system, and fire sprinkler systems are all in service. Campus is being converted for future use as Technical Education Facility. Buildings must be inspected before future occupancy.	0		
Make necessary repairs to fire sprinkler system as indicated on inspection report (annual tag 9-28-18)	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Provide covered walkway to and between all portable units	12	NC	6/30/20
Fill at south side of sidewalk between buildings 1 and 3	1	NC	6/30/20
Make necessary repairs to fire sprinkler system as indicated on inspection report (annual report dated 5-20-18, red tag on risers)	0		6/30/21
Repair or replace damaged rain gutters in courtyard	0		6/30/21
Repair broken window blinds	0		6/30/21
Repair rusted and leaking rain gutters and downspouts on north and south sides of gymnasium building	4	NC	6/30/17

Repair damaged ceiling in boy's locker room	0		6/30/21
Replace missing belt guard for outside air intake motor	1	NC	6/30/20

Modify or improve drainage under visitors bleachers at Football Fy STAT ACTION DATE FY STAT Field to eliminate standing water  Show primary and secondary evacuation routes on new evacuation maps and provide map in every student occupied space  Cut channels through sod so storm water can get to catch basins  O 6/30/21  Make necessary repairs to bleachers as indicated on report by Pat Joyce. Notify Pat when repairs are done  Fill void in walkway where sand trap was removed. At entry to corridor 1-290  Repair exhaust fan in bathroom  O 6/30/21  Repair exhaust fan in bathroom  O 6/30/21  Display for refrigerant monitor is not working and a bare wire is hanging out of the cabinet. Repair display and land wire  Repair or replace rusty, damaged doors  Remove rust from, prime and refinish badly rusting stands for cooling tower pumps  Repair roof leaks at roof drain at 2-270  O 6/30/21  DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION  DEFIC	DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES	PRIOR	CORRECTIVE
Field to eliminate standing water  Show primary and secondary evacuation routes on new evacuation maps and provide map in every student occupied space  Cut channels through sod so storm water can get to catch basins  O  6/30/21  Make necessary repairs to bleachers as indicated on report by Pat Joyce. Notify Pat when repairs are done  Fill void in walkway where sand trap was removed. At entry to corridor 1-290  Repair exhaust fan in bathroom  O  6/30/21  Repair exhaust fan in bathroom  O  6/30/21  Display for refrigerant monitor is not working and a bare wire is hanging out of the cabinet. Repair display and land wire  Repair or replace rusty, damaged doors  Remove rust from, prime and refinish badly rusting stands for cooling tower pumps  Repair roof leaks at roof drain at 2-270  O  6/30/21  DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION  TIMES CITED FY STAT ACTION DATE  PREV.  PRIOR CORRECTIVE ACTION O  CORRECTIVE ACTION DATE  Repair leak above ceiling at east end of corridor between gym and locker rooms (water running through cracks in concrete lid is forming stalactites)	DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	CITED		
maps and provide map in every student occupied space  Cut channels through sod so storm water can get to catch basins  0 6/30/21  Make necessary repairs to bleachers as indicated on report by Pat Joyce. Notify Pat when repairs are done  Fill void in walkway where sand trap was removed. At entry to corridor 1-290  Repair exhaust fan in bathroom  0 6/30/21  Repair exhaust fan in bathroom  0 6/30/21  Display for refrigerant monitor is not working and a bare wire is hanging out of the cabinet. Repair display and land wire  Repair or replace rusty, damaged doors  4 NC 6/30/19  Remove rust from, prime and refinish badly rusting stands for cooling tower pumps  Repair roof leaks at roof drain at 2-270  0 6/30/21  Repair or replace rusted door transom  0 6/30/21  DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION  TIMES CITED PRIOR CORRECTIVE ACTION  DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION  Repair leak above ceiling at east end of corridor between gym and locker rooms (water running through cracks in concrete lid is forming stalactites)		5	NC	6/30/18
Make necessary repairs to bleachers as indicated on report by Pat Joyce. Notify Pat when repairs are done  Fill void in walkway where sand trap was removed. At entry to corridor 1-290  Repair exhaust fan in bathroom  0 6/30/21  Repair exhaust fan in bathroom  0 6/30/21  Repair exhaust fan in bathroom  0 6/30/21  Display for refrigerant monitor is not working and a bare wire is hanging out of the cabinet. Repair display and land wire  Repair or replace rusty, damaged doors  4 NC 6/30/19  Remove rust from, prime and refinish badly rusting stands for cooling tower pumps  Repair roof leaks at roof drain at 2-270  0 6/30/21  Repair or replace rusted door transom  0 6/30/21  Repair or replace rusted door transom  0 6/30/21  Repair or replace rusted door transom  1 NC 6/30/20  Repair leak above ceiling at east end of corridor between gym and locker rooms (water running through cracks in concrete lid is forming stalactites)		5	NC	6/30/18
Joyce. Notify Pat when repairs are done  Fill void in walkway where sand trap was removed. At entry to corridor 1-290  Repair exhaust fan in bathroom  0 6/30/21  Repair exhaust fan in bathroom  0 6/30/21  Display for refrigerant monitor is not working and a bare wire is hanging out of the cabinet. Repair display and land wire  0 6/30/21  Repair or replace rusty, damaged doors  4 NC 6/30/19  Remove rust from, prime and refinish badly rusting stands for cooling tower pumps  Repair roof leaks at roof drain at 2-270  0 6/30/21  Repair or replace rusted door transom  0 6/30/21  DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION  TIMES CITED PREV.  PRIOR CORRECTIVE ACTION DATE  Repair leak above ceiling at east end of corridor between gym and locker rooms (water running through cracks in concrete lid is forming stalactites)	Cut channels through sod so storm water can get to catch basins	0		6/30/21
Repair exhaust fan in bathroom  Repair or refrigerant monitor is not working and a bare wire is hanging out of the cabinet. Repair display and land wire  Repair or replace rusty, damaged doors  Remove rust from, prime and refinish badly rusting stands for cooling tower pumps  Repair roof leaks at roof drain at 2-270  Repair or replace rusted door transom  Repair or replace rusted door transom  Repair or replace rusted door transom  Repair leak above ceiling at east end of corridor between gym and locker rooms (water running through cracks in concrete lid is forming stalactites)		4	NC	6/30/17
Repair exhaust fan in bathroom  0 6/30/21  Display for refrigerant monitor is not working and a bare wire is hanging out of the cabinet. Repair display and land wire  0 6/30/21  Repair or replace rusty, damaged doors  4 NC 6/30/19  Remove rust from, prime and refinish badly rusting stands for cooling tower pumps  Repair roof leaks at roof drain at 2-270  0 6/30/21  Repair or replace rusted door transom  0 6/30/21  DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION  TIMES CITED PREV.  PRIOR CORRECTIVE ACTION DATE PREV.  Repair leak above ceiling at east end of corridor between gym and locker rooms (water running through cracks in concrete lid is forming stalactites)		0		6/30/21
Display for refrigerant monitor is not working and a bare wire is hanging out of the cabinet. Repair display and land wire  Repair or replace rusty, damaged doors  Remove rust from, prime and refinish badly rusting stands for cooling tower pumps  Repair roof leaks at roof drain at 2-270  Repair or replace rusted door transom  DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION  TIMES CITED FY STAT ACTION DATE  Repair leak above ceiling at east end of corridor between gym and locker rooms (water running through cracks in concrete lid is forming stalactites)	Repair exhaust fan in bathroom	0		6/30/21
hanging out of the cabinet. Repair display and land wire  Repair or replace rusty, damaged doors  Remove rust from, prime and refinish badly rusting stands for cooling tower pumps  Repair roof leaks at roof drain at 2-270  O 6/30/21  Repair or replace rusted door transom  DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION  TIMES CITED PREV.  PRIOR FY STAT ACTION DATE  Repair leak above ceiling at east end of corridor between gym and locker rooms (water running through cracks in concrete lid is forming stalactites)	Repair exhaust fan in bathroom	0		6/30/21
Remove rust from, prime and refinish badly rusting stands for cooling tower pumps  Repair roof leaks at roof drain at 2-270  Repair or replace rusted door transom  DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION  TIMES CITED PREV.  PRIOR CORRECTIVE ACTION DATE  Repair leak above ceiling at east end of corridor between gym and locker rooms (water running through cracks in concrete lid is forming stalactites)		0		6/30/21
Repair roof leaks at roof drain at 2-270 0 6/30/21  Repair or replace rusted door transom 0 6/30/21  DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION TIMES CITED PREV. PRIOR FY STAT ACTION DATE  Repair leak above ceiling at east end of corridor between gym and locker rooms (water running through cracks in concrete lid is forming stalactites)	Repair or replace rusty, damaged doors	4	NC	6/30/19
Repair or replace rusted door transom  DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION  TIMES CITED PREV.  Repair leak above ceiling at east end of corridor between gym and locker rooms (water running through cracks in concrete lid is forming stalactites)  PRIOR CORRECTIVE ACTION  TIMES CITED PREV.  PRIOR FY STAT ACTION DATE  1 NC 6/30/20		0		6/30/21
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION  TIMES CITED FY STAT ACTION DATE  Repair leak above ceiling at east end of corridor between gym and locker rooms (water running through cracks in concrete lid is forming stalactites)	Repair roof leaks at roof drain at 2-270	0		6/30/21
Repair leak above ceiling at east end of corridor between gym and locker rooms (water running through cracks in concrete lid is forming stalactites)  CITED PREV.  FY STAT ACTION DATE  1 NC 6/30/20	Repair or replace rusted door transom	0		6/30/21
Repair leak above ceiling at east end of corridor between gym and locker rooms (water running through cracks in concrete lid is forming stalactites)  CITED PREV.  FY STAT ACTION DATE  1 NC 6/30/20	DESIGNAV DESCRIPTION AND CORRECTIVE ACTION	TIMES	DDIOD	000000011/5
between gym and locker rooms (water running through cracks in concrete lid is forming stalactites)	DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	CITED		
	between gym and locker rooms (water running through cracks in	1	NC	6/30/20
		5	NC	6/30/18

Repair exhaust fans in bathrooms 6-112 A and B	0		6/30/21
Repair or replace rusty, damaged door	4	NC	6/30/19
Repair leaking air handler	0		6/30/21
Reinsulate chilled water lines to prevent condensate leaks	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair or replace rusted door, frame and louver	5	NC	6/30/19
Reinsulate chilled water lines to prevent condensate leaks	0		6/30/21
Replace missing ceramic wall tiles at urinals	0		6/30/21
Cover exposed rebar at riser 6 of second run of stairs. Inside of stairs	0		6/30/21
Repair gas outlet at Teachers station. No flow	0		6/30/21
Repair sink 4, no water	0		6/30/21
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Remove scaffold stored in mechanical room	0		6/30/20
Repair leaking air handler	0		6/30/21
Repair leaking drain for high urinal	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair exhaust fan in bathrooms 3-123A and 3-124A	0		6/30/21
Repair leaking air handler	0		6/30/21
Repair purge fan switch. Button will not depress	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21

Repair exhaust fan in Boys bathroom	0	6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make repairs as noted on fire sprinkler inspection report, red annual inspection tag dated September 2018	0		6/30/21
Post sign indicating primary and secondary evacuation routes in contrasting colors. All	3	NC	6/30/18

evacuation maps show the complete building with evacuation routes from all rooms

#### Total Serious Life Safety Citations Total Non-Serious Safety Citations

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on inspection report (annual inspection dated 2-28-18, no inspection tags were attached on risers)	0		6/30/21
Eliminate dead end corridor, east exit corridor from Media Center. Approximately 36 feet	1	NC	6/30/22
Repair broken window blinds	0		6/30/21
Repair exhaust fan in bathroom	1	NC	6/30/20

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on inspection report. Red annual, semi-annual and quarterly tags	1	NC	6/30/20
Provide dated flame resistance label on stage curtain (date on certificate is 4-23-12)	0		6/30/21

Repair ventilation fans in all restrooms in Building 7	0	6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/22
Provide dated flame resistance label on CCTV curtain	0		6/30/21
Repair purge fan in science lab	1	NC	6/30/20
Make repairs as noted on fire sprinkler inspection report, yellow quarterly tag dated August 2018	0		6/30/21
Replace missing emergency disconnect valves for water for all science rooms: 2-109, 2-111, 2-207, 2-209 and 2-211 Valves shall be completely shut-off with a quarter turn	1	NC	6/30/20
Modify slope of floor to provide adequate floor drainage	6	NC	6/30/19
Adjust door to latch properly	1		6/30/20
Repair emergency escape window to open properly	0		6/30/21
Replace missing window blinds	0		6/30/21
Repair exit door in arts courtyard to open and close properly - door rubs on frame	1	NC	6/30/20
Adjust door to 5-500 latch properly	0		6/30/21
Adjust both doors to latch properly	1	NC	6/30/20
Repair emergency escape window to open properly - window did not open	1	NC	6/30/19
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE

Serious Life Safety Citations Non-Serious Safety Citations	1		
Non-Serious Safety Citations	12		

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Provide current inspection tag for fire sprinkler system and make any necessary repairs if indicated on report - last report was dated 4.21.2017	0		6/30/21
Provide current state inspection tag for steamer in culinary lab FL130181	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE

Make necessary repairs to fire sprinkler system as indicated on Annual inspection report dated 12-29-17	0	6/30/21
Repair leaky and moldy downspouts on exterior walls of Building 5, locations are at 5-196, 5-198,	0	6/30/21
5-126D, and 5-110		

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Post sign indicating primary and secondary evacuation routes in contrasting colors. Classroom F	0		6/30/19
Secure data outlet box to wall. Classroom A	0		6/30/19
Determine cause of water damaged ceiling tiles and replace tiles. Classroom B	0		6/30/19
Post sign indicating primary and secondary evacuation routes in contrasting colors. Classroom E	0		6/30/19
Determine cause of water damaged ceiling tiles and replace tiles. Classroom E office	0		6/30/19
Make necessary repairs to fire sprinkler system as indicated on inspection report. Fire sprinkler riser room	0		6/30/19
Make repairs as indicated on inspection report for Kitchen hood fire suppression system. Kitchen	0		6/30/19
Make repairs to fire alarm system as indicated on fire alarm inspection report	0		6/30/19

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
No access was available to portable P-9415. Please provide access to the portable during the report review meeting. Key will not go into lock	0		6/30/19
Replace missing top rail on perimeter fencing along driveway next to Softball concessions building	1	NC	6/30/20

Modify home football bleachers to meet code requirements: Vertical openings between guardrails and footboards or seat boards shall be provided with intermediate construction so that a 4 inch diameter sphere cannot pass through the opening. See inspection report by Patrick Joyce		NC	6/30/20
Provide signs indicating primary and secondary evacuation routes in all classrooms	4	NC	6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Provide automatic fire sprinkler coverage for closets in conference room	4	NC	6/30/21
Provide automatic fire sprinkler coverage for vault	4	NC	6/30/21
Repair leaking flush valve on 6th toilet	0		6/30/21
Connect damper actuators to dampers	0		6/30/21
Connect damper actuators to dampers	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair inoperable fume hood	6	NC	6/30/17
Repair exhaust fan for fume hood	0		6/30/21
Remove and prohibit storage blocking access to fire sprinkler riser	0		6/30/19
Connect damper actuators to dampers on air handlers	0		6/30/21
Remove and prohibit storage on ramp and in exit corridor	0		6/30/19
Remove and prohibit storage at both Stage exits	0		6/30/19
Remove and prohibit storage at south exit from Stage	0		6/30/19

Prohibit charging golf cart batteries in room	0		6/30/19
Repair leaking Magic Air unit suspended from ceiling	0		6/30/21
Repair exhaust fan in bathrooms 4-116A and 4-117A	0		6/30/21
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Replace missing cover plate on panic bar on door to exterior	0		6/30/21
Repair ventilation fan in flammable storage room	2	NC	6/30/19
Repair Art Patio door to close properly	1	NC	6/30/20
Replace tubes in light fixture	0		6/30/19
Remove storage from electrical room	0		6/30/19
Remove and prohibit storage in exit corridor	0		6/30/19
Provide clear access to electrical panel	0		6/30/19
Repair exhaust fan in bathrooms 5-103B and C	0		6/30/21
Connect damper actuators to dampers	0		6/30/21
Pressbox roof membrane has extreme deflection at some areas. Determine reason for roof deck soft spots on pressbox roof. Make repairs in accordance with structural engineer recommendations. STAY OFF OF ROOF UNTIL REPAIRS ARE COMPLETED	2	NC	6/30/20
Provide stairs to football field pressbox	11	NC	6/30/20
Repair panic hardware on west door to exterior from corridor. Down rod will not retract	0		6/30/21
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Replace missing hold open magnet on door at west end of corridor	0		6/30/21
Provide clear access to electrical panels	0		6/30/19
Replace missing steel cover plate on panic hardware on west door	0	1	6/30/21

Repair exhaust fan in bathrooms 6-112A and B	0		6/30/21
Replace broken seat for last toilet	0		6/30/21
Large cord covers and cords run across aisles causing a tripping hazard. Find a better way to run cords and cables from sound and lighting controls in Auditorium	0		6/30/19
Provide light bulb in open socket for lights at make-up mirror	0		6/30/19
Adjust flow of emergency eye wash	0		6/30/21
Remove storage from mechanical room	0		6/30/19
Remove storage from electrical room	0		6/30/19
Secure door handle to door	0		6/30/21
Modify or improve drainage to take rain water away from portables, not under portables	5	NC	6/30/21
Provide clear access to electrical panel	0		6/30/19
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE

Serious Life Safety Citations	7		
Non-Serious Safety Citations	44		
1			

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on annual inspection report 1.16.19	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on annual inspection report dated 5.29.18	0		6/30/21
Repair or replace bent aluminum column at bus loop covered walkway between Bldgs. 1 and 3	0		6/30/21

Repair broken section of graspable handrail at top of stairwell	0		6/30/21
Secure loose floor tiles where crack is - facing 2-109B	2	NC	6/30/19
Repair damaged bleacher seat located at center of west bleachers 1st row	0		6/30/21
Repair water leak in chiller room under P-2A	0		6/30/21
Repair exhaust fan in bathroom	1	NC	6/30/20
Repair exhaust fan in bathroom	1	NC	6/30/20

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on annual inspection report dated 6.12.18	0		6/30/21
Clean gutters and covered walks between buildings 1 and 2. Trim branches growing over covered walk north of building 2	1	NC	6/30/20
Replace missing sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/20
Post sign indicating primary and secondary evacuation routes in contrasting colors	2	NC	6/30/17
Provide panic hardware on north and south gates for kindergarten play area west of building 3 to allow egress access at all times	1	NC	6/30/20
Repair exhaust fan in girls bathroom	0		6/30/21
Modify or improve storm drainage from portables. Storm water dumps at bottom of walls and goes under units	2	NC	6/30/19

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make repairs to rusty, damaged areas of PE pavilion at east campus	0		6/30/24

Make repairs as noted on fire sprinkler inspection reports for east and west campus, red annual inspection tags dated March 2018	0	6/30/21
Refinish rusty section of duct of AHU SF 10 1 for air conditioning system to ensure it operates as designed	0	6/30/21
Repair inoperable wall damper in kiln room	0	6/30/21
Repair ventilation fan	0	6/30/21
Repair ventilation fan	0	6/30/21
Repair ventilation fan	0	6/30/21
Repair ventilation fan	0	6/30/21

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on annual inspection report dated 4.23.18	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on annual inspection report dated 7.31.2018	0		6/30/21
Coordinate with Building Code Services to obtain building permits for 4 storage trailers, 2 at bldg. 8 and 2 at bldg. 12. Placement of 2 trailers at bldg. 12 is acceptable. Remove or relocate 2 trailers at bldg. 8, new location on campus needs to be approved by Building Code Services prior to relocation of trailers. Storage trailers need hurricane tie down straps. Trailers are all within 60 feet of occupied buildings and need heat detectors	1	NC	6/30/21
Repair deteriorated finish on exterior walls of Building - Band between 1st and 2nd floor is pitted	0		6/30/22

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Remove pink mold from exterior wall of 1-110 to 1-114	1	NC	6/30/20
Plans indicate 2 hour walls. No label on door and penetration through enclosure wall. Seal	1	NC	6/30/20

penetration in enclosure wall, provide 90 minute door or provide fire sprinkler in room

#### Total Serious Life Safety Citations Total Non-Serious Safety Citations

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Provide ventilation for custodial closet	21	NC	6/30/18
Repair or replace rusted metal lathe and rusted corner bead on exterior walls of building 2, including chiller compound	7	NC	6/30/18
Modify or improve roof drainage from concrete portables to take rain water away from units	7	NC	6/30/25

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair chilled water pipe support in chiller compound. Support anchors on base plate missing	1	NC	6/30/20
Provide panic hardware on exit door to corridor 1-100A	1	NC	6/30/20
Repair drinking fountain in teachers planning room	0		6/30/21
Provide cover on open Neptronic damper actuator box on AHU-12	1	NC	6/30/20
Repair broken window blinds	0		6/30/21
Repair broken window blinds	0		6/30/21

Attach closer on restroom door	0		6/30/21
Provide cover on open Neptronic damper actuator box on AHU-11	1	NC	6/30/20
Provide dated flame resistance certification on stage curtain (current certificate is dated April 25, 2012	0		6/30/21
Replace damaged metal ceiling in covered play area behind stage	0		6/30/21
Replace missing canister on recessed light fixture in ceiling in front of stage	0		6/30/21
Provide cover on open Neptronic damper actuator box on air handler	1	NC	6/30/20
Repair broken window blinds	0		6/30/21
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair broken window blinds	0		6/30/21
Repair broken window blinds	0		6/30/21
Repair broken window blinds	0		6/30/21
Repair or replace rusted door	0		6/30/21

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair broken window blinds	0		6/30/21
Repair broken window blinds	0		6/30/21

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Campus is secure and no longer in use Buildings will need to be inspected before future use.	0		

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Provide automatic fire sprinkler coverage for room. Plans indicate 1 hour wall. No fire sprinkler head visible. Room has heat detector	3	NC	6/30/22
Repair ventilation fan	0		6/30/21
Provide automatic fire sprinkler coverage for storage mezzanine at rear of stage. Blocked by ductwork	3	NC	6/30/20
Deficiencies noted on Fire Pump inspection report dated October 2018, make necessary repairs	0		6/30/21

#### Total Serious Life Safety Citations Total Non-Serious Safety Citations

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Grade soil to prevent erosion and fill eroded areas on bank east of east parking lot	1	NC	6/30/20
Modify or improve site drainage to eliminate standing water at pedestrian entry to north parking lot. After rain 2-3 inches of water standing on sidewalk	1	NC	6/30/20
Repair damaged, leaking rain gutter adjacent to 1-197A to prevent further damage to surrounding area. Repair all gutters in interior courtyard. Many holes rusted through gutters. During hard rain water flows into school	7	NC	6/30/17
Provide automatic fire sprinkler coverage for closet	1	NC	6/30/25
Remove and prohibit use of space heater	0		
Make necessary repairs to fire sprinkler system as indicated on inspection report	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Post signs indicating primary and secondary evacuation routes in contrasting colors throughout campus	2	NC	6/30/19
Modify or improve roof drainage from portables to drain away from units and fill undermined landings and sidewalks	9	NC	6/30/19

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Post sign indicating evacuation routes in all classrooms without doors directly to exterior	5	NC	6/30/18
Revise panel schedules for buildings 3,4,5, and 6.	0		6/30/21
Repair or replace supports for chillers in chiller compound at 1-137. Remaining supports are beginning to crush coils	0		6/30/21
Repair intercom and bell. Cannot be heard in 1-111 and 1-103	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Remove and prohibit combustible (residential) furniture. Couch has no evidence of flame proofing	0		6/30/19
Remove and prohibit combustible (residential) furniture. Couch has no evidence of flame proofing	0		6/30/19
Eliminate extension cord or replace with minimum 15A cord. Used for lamps at couch. Use a protected surge strip	0		6/30/19
Repair or replace rotted wooden door on south side of room	1	NC	6/30/20
Provide secondary egress	4	NC	6/30/18
Repair or replace rusty outside air intake ductwork and rusted through roof cap	3	NC	6/30/18
Provide secondary egress. Secondary egress to 2-124C is locked and blocked	0		6/30/19
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE

Close open damper motor unit 2, exposed wires	5	NC	6/30/17
Repair gas plumbing in Kitchen. Gas shuts of intermittently	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Install defibrillator and test it	0		6/30/21
Contact Building Department, obtain permit and schedule inspection for new work	0		6/30/19
Provide hurricane anchors for Tiny House north of building 4 if it is to remain on site	0		6/30/21
Replace cover for cleanout in grassed area south of 4-103	0		6/30/21
Provide 2 exit doors from space. Garage doors are down and not an exit	5	NC	6/30/18
Provide floor drain for emergency eye wash/shower	16	NC	6/30/20
Provide floor drain for emergency eye wash/shower	16	NC	6/30/20
Provide 2 exit doors from space. Garage doors are down and not an exit	5	NC	6/30/18
Provide 2 exit doors from space. Garage doors are down and not an exit	5	NC	6/30/18
Provide floor drain for emergency eye wash/shower	16	NC	6/30/20
Provide cover on thermostat	0		6/30/21
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Provide certification that all student occupied spaces have emergency lights and all are operable. Last certification 6-24-17	0		6/30/21
Contact Building Department obtain permit and schedule inspection for new work	0		6/30/19
Provide floor drain at emergency eye wash/shower	12	NC	6/30/20
Provide 2 exit doors from space. Garage door is down and not an exit	5	NC	6/30/18
	<b></b>	NC	6/30/19
Provide dust collection and exhaust system	5		
Provide dust collection and exhaust system  Provide floor drain for emergency eye wash/shower	16	NC	6/30/20
-			6/30/20 6/30/19

Replace broken glass for emergency escape window	0		6/30/21
Remove and prohibit storage in exit corridor	0		6/30/19
Adjust door to latch properly, sticky latch	0		6/30/21
Contact Building Department, obtain permit and call for inspection of new work	0		6/30/19
Secure hanging rain gutter on west side of building	0		6/30/21
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Provide 2 exit doors from space. Garage door is shut and not an exit. Used as Karate school 2015 and 2016. Sheet metal shop 2019	5	NC	6/30/18
Provide 2 exit doors from space. Garage door is shut and not an exit	5	NC	6/30/18
Repair exhaust fan in bathroom	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on inspection report. Red annual, yellow quarterly tags and green semi-annual tags	0		6/30/21
Remove and prohibit storage in exit corridor	0		6/30/19
Repair trouble indicated on fire alarm panel	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Maintain clear aisle to west exit from Stage. Cords on floor across exit path and tables and chairs at bottom of stairs	0		6/30/19
Reinsulate impeller housing on chilled water pump in Chiller Compound	0		6/30/21
Determine cause of water damaged and moldy hard ceiling and refinish ceiling	0		6/30/21

Adjust door to latch properly. Sticky latch and bathroom door cannot be locked	0		6/30/21
Remove storage from mechanical room. Cabinets and mats	0		6/30/19
Adjust west door at top of stairs to latch properly. Put spacer behind latch	0		6/30/21
Adjust fire sprinkler head so deflector projects a minimum 1 inch below escutcheon	0		6/30/21
Remove storage from electrical room	0		6/30/19
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair or replace badly rusted door frame. Closer has pulled off of frame	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Modify or improve drainage from play courts to eliminate standing water on courts	6	NC	6/30/19
Post sign indicating primary and secondary evacuation routes in contrasting colors for buildings 2 and 5	3	NC	6/30/18
Repair ventilation fan	0		6/30/21
Repair ventilation fan	0		6/30/21
Refinish rusty areas of duct adjacent to Fire Sprinkler Riser to ensure air conditioning system operates as designed	0		6/30/21
Repair ventilation fan	0		6/30/21
Repair lock button to operate properly	0		6/30/21
Repair ventilation fan	0		6/30/21
Repair exhaust fan in custodial room	1	NC	6/30/20
Refinish rusty areas of duct adjacent to door to ensure that air conditioning system operates as designed	0		6/30/21
Repair exhaust fan at kiln	0		6/30/21

Refinish areas of peeling and missing stucco finish on columns of pavilion	0		6/30/21
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Serious Life Safety Citations 0 Non-Serious Safety Citations 12			

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Campus is secure and no longer in use. Buildings need to be inspected before future use, including fire alarm system	0		
No violations observed. Building not in use			
No violations observed. Building not in use			
No violations observed. Building not in use			

No violations observed. Building not in use			
No violations observed. Building not in use			
No violations observed. Building not in use			
No violations observed. Building not in use			
No violations observed. Building not in use			
No violations observed. Building not in use			
No violations observed. Building not in use			
No violations observed. Building not in use			
No violations observed. Building not in use			6/30/18
	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
No violations observed. Building not in use			

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Provide Emergency Evacuation maps with both primary and secondary evacuation routes in contrasting colors throughout campus, except for Building 6 which has current maps	4	NC	6/30/18
Provide engineers evaluation of cracked retaining wall along side of canal and repair according to engineers recommendation - east of Bldg. 3	3	NC	6/30/19
Repair leaning light pole - east of Bldg. 3	3	NC	6/30/19
Repair exhaust fan	1	NC	6/30/20
Repair exhaust fan	1	NC	6/30/20
Repair damaged flooring in Kitchen. Floor finish coming off	1	NC	6/30/20
Repair exhaust fan in bathroom	3	NC	6/30/18

Insulate hot water pipes	1	NC	6/30/20
Repair exhaust fan	1	NC	6/30/20

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Provide dated flame resistance label on green curtain in CCTV Studio or remove curtain	1		6/30/21
Make necessary repairs to fire sprinkler system as indicated on inspection report. Yellow quarterly and semi-annual tags. No annual tag	1		6/30/21
Heat will go into ceiling space through access hole for roof ladder and fire sprinkler will not initiate. Provide heat trap around opening in ceiling	1		6/30/21
Label all circuits on electrical panel: SBL 1-3	3	NC	6/30/19

#### Total Serious Life Safety Citations Total Non-Serious Safety Citations

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Modify roof drainage from portables. Rain water leader drops water at bottom of exterior wall of portable and is going under units and undermining sidew		NC	6/30/19

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on annual inspection report dated 4.20.2018	0		6/30/21
Repair hole and seal leaks in rain gutter above entrance to main office	0		6/30/21
Repair ventilation fan	1	NC	6/30/20

Repair exhaust fan in bathroom - inside 1-123J	0		6/30/21
Repair inoperable purge fan	1	NC	6/30/20
Repair hole in rain gutter and seal leaks in gutter at gym east entrance vestibule to corridor 2-002	0		6/30/21
Seal leaking rain gutter adjacent to 2-192	0		6/30/21
Seal leak in rain gutter above 2-195	0		6/30/21
Provide automatic fire sprinkler coverage for electrical room without 2 hour fire rated walls	1	NC	6/30/23
Prohibit use of space as a classroom - resource room does not meet code and design requirements for classroom space. You may relocate classroom to 2-210	0		6/30/19
Provide automatic fire sprinkler coverage in recently installed walk in freezer	1	NC	6/30/23
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE

Serious Life Safety Citations Non-Serious Safety Citations	0 13		
Non-Schous Salety Chanons	15		

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair broken window blinds	0		6/30/21
Repair broken window blinds	0		6/30/21
Repair broken window blinds	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE

Repair termite damage to roof framing of Pavilion	2	NC	6/30/19
Make necessary repairs to fire sprinkler system as indicated on inspection report. Red annual and yellow semi-annual and quarterly tags	0		6/30/21
Teacher indicates black dust comes out of A-C outlet and she must clean it up weekly. Repair duct work to eliminate dust	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Provide covered walkway to exits of portables on site 4 years or more. According to school staff P-1 and	3	NC	6/30/22
P-3 are used by students			

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on annual inspection report dated 10.26.18	0		6/30/21
Repair bent chain link fencing at NW end of playfield area due to overgrown tree trunks. Place a section of fencing with secured posts and bottom rail to close gap and prohibit access to and from adjacent lake	0		6/30/21
Repair uneven walkway caused by tree roots along west property fence and adjacent to tree north of bus loop. See PE coach	0		6/30/21
Post signs indicating primary and secondary evacuation routes in contrasting colors	2	NC	6/30/19
Fill eroded area at 50-190	1	NC	6/30/20
Determine cause of damaged ceiling and make necessary repairs	1	NC	6/30/20
Determine cause of damaged ceiling and make necessary repairs	1	NC	6/30/20

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Provide evacuation maps that indicate both primary and secondary evacuation routes for all classrooms and assembly spaces	8	NC	6/30/23
Prohibit keeping gates between buildings 4 and 5, 7 and 8 locked while campus is occupied to eliminate dead end corridors and allow egress at all times	2	NC	6/30/17
Repair bleachers, home and visitor at football stadium, as instructed in the Bleacher Structural Inspection Report. Contact Patrick Joyce if questions occur and for reinspection when repairs complete	2	NC	6/30/19
Make necessary repairs to fire sprinkler system as indicated on inspection report, Annual inspection completed on 7-27-18 with deficiencies listed on report, Building 8-195 and 10-192	0		6/30/21
Repair window blinds. Missing slats	1	NC	6/30/20
Replace missing escutcheons on fire sprinkler heads in ceiling of auditorium (X7)	0		6/30/21
Repair or replace rippled carpeting between upper and lower seating areas	3	NC	6/30/18
Repair water leaking from A/C unit, (standing water on floor)	0		6/30/21
Repair or replace damaged canvas cover in covered playground courtyard behind preschool	0		6/30/22
Replace burned out bulbs in light fixtures in ceiling of lecture hall (lift will be needed to replace approximately 25 bulbs in ceiling over 25 feet high)	0		6/30/21
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair shade on window to open properly	0		6/30/21
Repaint and refinish peeling paint on exterior walls of portables	2	NC	6/30/19
Repair rear door to open properly (door drags on exterior concrete slab	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair bleachers as instructed in the Bleacher Structural Inspection Report. Contact Patrick Joyce if questions occur.	1	NC	6/30/20
Replace missing bottom rail on guardrail on raised platform in interior courtyard at 2 inches above floor	0		6/30/21
Modify or improve site drainage at tennis courts and softball field	7	NC	6/30/19
Repair heavily rusted door frame	3	NC	6/30/18
Remove lightweight partition walls forming storage space (X2) from piano lab (structures do not meet code and design requirements, contact FMC for assistance if needed)	2	NC	6/30/17
Repair damaged areas of walls	0		6/30/21
Limit occupancy to maximum 5 students - designed after Oct. 18, 1994 or facilitate a project through M&PO to change door to swing in direction of egress	1	NC	6/30/18
Prohibit making holes in walls for data cords, remove data cords from holes in walls. Create work	0		6/30/19

m holes in walls. Create work | | | | order requesting maintenance zone team to properly fill holes in walls

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Modify covered walkway drainage at bus loop to prevent storm water from running across sidewalk	7	NC	6/30/21
Repair exhaust fan in bathroom	2	NC	6/30/19
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	2	NC	6/30/19

Repair damaged concrete sub flooring adjacent to exit door. Raised concrete appears to be causes by oak tree roots - make necessary repairs to make floor level	0		6/30/21
Provide exit sign with directional arrow adjacent to newly created stage exit at curtain stop. Self	1	NC	6/30/20
illuminated exit sign is acceptable	1	•	'

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Provide covered walk to portables	17	NC	6/30/21
Provide signs in portable bathrooms indicating epoxy paint and when painted	1	NC	6/30/20

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair opening in fabric at low point of astro-turf play field. Tripping hazard	1	NC	6/30/20
Modify or improve site drainage to eliminate standing water on basketball court	1	NC	6/30/20
Make necessary repairs to fire sprinkler system as indicated on inspection report	0		6/30/21
Replace broken vinyl floor tile in second floor corridor adjacent to 1- 208	0		6/30/21
Repair or replace rusted door frame (frame is rusted on interior side)	0		6/30/21
Provide dated flame resistance certification on stage curtain (current certification is dated April 14, 2012)	0		6/30/21
Repair phones at top of stairs for area of rescue assistance	1	NC	6/30/20
Replace damaged vinyl cover on stair riser on upper run of stairs	0		6/30/21
Post sign indicating primary and secondary evacuation routes in contrasting colors	1	NC	6/30/20

Post sign indicating primary and secondary evacuation routes in contrasting colors	1	NC	6/30/20
Replace missing signage indicating room name and number at appropriate height with raised and Braille characters	0		6/30/21
Post sign indicating primary and secondary evacuation routes in contrasting colors	1	NC	6/30/20
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Post sign indicating primary and secondary evacuation routes in contrasting colors	1	NC	6/30/20
Modify storm drainage system at portable to prevent storm water from going under portable	1	NC	6/30/20

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on inspection report	0		6/30/21
Repair damaged laminate on countertop at sink	0		6/30/21
Remove rust, prime and paint PE pavilion column bases	3	NC	6/30/18

#### Total Serious Life Safety Citations Total Non-Serious Safety Citations

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Post sign indicating primary and secondary evacuation routes in contrasting colors for all classrooms without doors directly to the exterior	1	NC	6/30/22
Modify or improve storm drainage at concrete portables to direct rain water away from portables.  Currently storm water is going under portables	1	NC	6/30/23

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Post sign indicating evacuation routes for all renumbered classrooms and assembly spaces through out school - evacuation routes should indicate primary and secondary routes	6	NC	6/30/22
Make necessary repairs to fire sprinkler systems as indicated on inspection report (Annual Report dated 9-26-18, has red annual tags attached)	0		6/30/21
Replace rusted roof flashing around entire building	0		6/30/21
Replace missing escutcheons on fire sprinkler heads (X5) in auditorium seating area	0		6/30/21
Repair rusted and perforated roof edge	1	NC	6/30/20
Coordinate with FMC to provide certification by Building Department that Coach office built inside room meets code and design requirements	3	NC	6/30/16
Prohibit use of space as a music classroom or contact FMC to have room modified to meet classroom requirements. All 3 doors swing in. Verify if space has emergency lighting	3	NC	6/30/16
Remove or provide approval from Building Department that platform structure meets code requirements and modify to provide wheel chair access	6	NC	6/30/15
Replace broken A/C grill in ceiling	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair leaking rain gutters and downspouts on building 1. Clean out all gutters and downspouts	5	NC	6/30/21
Post sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/22

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES	PRIOR	CORRECTIVE
	CITED	FY STAT	ACTION DATE
	PREV.		
		1 1	

Make repairs as noted on fire sprinkler inspection report dated July 2018	0		6/30/21
Repair rusted chiller lines in exterior chiller compound	1	NC	6/30/20

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Modify or improve site drainage to eliminate standing water from far east parking lot (4 spaces adjacent to ball field)	6	NC	6/30/14
Make repairs as noted on fire sprinkler inspection report, red annual tag dated October 2018	0		6/30/21
Repair areas of cracked, uneven sidewalk south of P-23	0		6/30/21
Repair exhaust fan at kiln	0		6/30/21
Modify or improve storm drainage from portables to direct rain water away from units. Review storm  drainage going under portables and undermining landing		NC	6/30/17

#### drainage going under portables and undermining landings.

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Post sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/21
Post sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/21
Post sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/21
Post sign indicating primary and secondary evacuation routes in contrasting colors	1	NC	6/30/19
Post sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Time clock clock motor not running. Replace clock motor	0		6/30/21
Repair exhaust fans in all bathrooms in building	0		6/30/21
Remove contractors storage from mechanical room	0		6/30/21
Provide cover on exposed electrical junction box at light switch	0		6/30/21
Remove storage from mechanical room	0		6/30/19
Repair or replace non-working kiln	1	NC	6/30/20
Storm drainage from portables collects between portables and sidewalks. Storm water ends up	4	NC	6/30/20

draining under portables. Modify drainage to get storm water away from portables. Many roof drain outlets are covered and many black plastic drainage pipes are broken

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on inspection report. Red annual and yellow quarterly tags	0		6/30/21
Primary evacuation routes on most evacuation maps have faded and are no longer visible. Redo primary evacuation routes on all evacuation maps	0		6/30/22
Replace broken cover plate for down rod on corridor door at 1-127	0		6/30/21
Replace missing cover plate for panic bar on south door at bottom of staris	0		6/30/21
Replace missing cover plate for down rod on corridor door at 1-290A	0		6/30/21
Repair or replace surge suppressor for electric panel 1H1A. Not illuminated	0		6/30/21
Replace tubes in light fixture	0		6/30/19

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
No violations observed (facility is locked, not in use)			
No violations observed (facility is locked, not in use)			
No violations observed (facility is locked, not in use)			
No violations observed (facility is locked, not in use)			
No violations observed (facility is locked, not in use)			
No violations observed (facility is locked, not in use)			
No violations observed (facility is locked, not in use)			
No violations observed (facility is locked, not in use)			
No violations observed (facility is locked, not in use)			

#### Total Serious Life Safety Citations Total Non-Serious Safety Citations

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair roof leaks at transportation Bldgs. 1 & 2	0		6/30/22
Repair damaged handrail on south ramp - broken and bent railing	1	NC	6/30/20

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE

Label all circuits on electrical panels 2 and 3 at SW corner of room	0	6/30/21
Label all circuits on electrical panel on loft	0	6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair or replace bent pole for covered walk at parent drop off	1	NC	6/30/20
Repair soft, damaged flooring at 2-104B	1	NC	6/30/20
Replace missing signs indicating primary and secondary evacuation routes for all classrooms	4	NC	6/30/17
Repair exhaust fan in bathroom	2	NC	6/30/18
Replace missing signs indicating primary and secondary evacuation routes for all classrooms	4	NC	6/30/17
Repair damaged chain link fencing around AC units on west side of building	1	NC	6/30/20
Replace missing signs indicating primary and secondary evacuation routes for all classrooms	4	NC	6/30/17

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
No access was available to 1-003. Please provide access to this room during the report review meeting	0		6/30/19
Prohibit parking on grass area at west campus parking lot	0		6/30/19
Trim trees overhanging all buildings and covered walkways	0		6/30/21
Trim trees overhanging bus loop. Buses hit branches	0		6/30/21
Modify or improve storm drainage to prevent rain from running across sidewalks in interior courtyard between buildings 1, 2, 3 and 4	5	NC	6/30/22

Clean and repair damaged rain gutters -downspouts throughout	3	NC	6/30/18
campus			
Wet column on west pavilion is rusted through. Repair column	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Replace lens on fixture	0		6/30/21
Replace missing shingles	0		6/30/21
Remove storage from mechanical room	0		6/30/19
Repair or replace door lock. Cannot be locked	0		6/30/21
Repair flush bolt on folding wall to stay in floor. Flush bolt at door	0		6/30/21
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair damaged wall in bathroom to provide impervious finish	0		6/30/21
Repair damaged wall in bathroom to provide impervious finish	0		6/30/21
Refinish bathroom wall	0		6/30/21
Repair or replace door lock. Cannot be locked	0		6/30/21
Repair drinking fountain with stopped up drain at P-8B	0		6/30/21
Repair unstable flooring (weak spongy flooring throughout portable)	1	NC	6/30/20
Replace deteriorated wood siding at stairs	0		6/30/21
	I	1	

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair purge fan to work properly	0		6/30/21
Repair or replace damaged fume hood door. Glass is cracked and door is bent.	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair 4 troubles indicated on fire alarm panel and repair punch list from report to AHJ	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Determine cause of water damaged ceiling tiles and replace tiles	0		6/30/21
No violations observed. Ramp and stairs removed			
Determine cause of water damaged ceiling tiles and replace tiles	0		6/30/21
Secure hanging heat detector	0		6/30/21
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE

Serious Life Safety Citations Non-Serious Safety Citations	0	
Non-Serious Safety Citations	14	

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Modify or improve site drainage to eliminate standing water on play court	6	NC	6/30/24
Clean out all rain gutters and downspouts on campus and repair leaks	3	NC	6/30/18
Post sign indicating primary and secondary evacuation routes in contrasting colors. Current signs have primary route only	3	NC	6/30/24
Repair ventilation fans in bathrooms and custodial closets through out building	0		6/30/22

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair exhaust fan in bathrooms 11-105A and B	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom. Classroom numbered 3-104	0		6/30/21
Repair covers of electrical panels H3 and H3B to latch	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Modify or improve drainage at portables C-7 through C-12 to prevent storm water from going under units at junction boxes	4	NC	6/30/19
Repair exhaust fan in boys bathroom	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Replace missing shingles or reshingle 2 covered pavilions	1	NC	6/30/20
Make repairs to fire alarm system so it will function according to NFPA 72,10.4.5 (school staff has indicated the fire alarm panel has been going into alarm mode, sometimes several times daily for the past year, and the false alarms have become very disruptive to teaching. They have been told the problem is in the underground wiring from one of the buildings on campus)	0		6/30/21
Repair ventilation fan in restroom	0		6/30/21
Fire damper not visible in duct supplying room. Install fire damper	1	NC	6/30/20

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair uneven surface of tennis and basketball courts to prevent ponding water and mold growth	6	NC	6/30/22
Modify home football bleachers to meet code requirements: Vertical openings between guardrails and footboards or seat boards shall be provided with intermediate construction so that a 4 inch sphere cannot pass through the opening. See report by P. Joyce for further details and other needed repairs	6	NC	6/30/20
Window frames on south walls of building 5 (cafeteria) and north wall of building 1 (Media Center) are badly corroded and leaking. Metal is perforated and ants enter the building through the window frames. Check all windows campus-wide and repair or replace as necessary	5	NC	6/30/21
Provide evacuation maps for student occupied areas throughout campus with primary and secondary routes shown in contrasting colors	4	NC	6/30/22
Provide current annual inspection tag for fire sprinkler system and fire pump and make any necessary repairs if indicated on report	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair trouble indicated on fire alarm panel	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair broken window blinds	1	NC	6/30/20
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Change swing of door to corridor to swing in direction of egress. Room used as classroom. Provide lock on other door on Media center side so room can be secured from Media Center	0		6/30/21
Repair or replace heavily rusted and deteriorated metal railing and posts at pressbox roof and at bottom of ladder side rail - area is out of use until repairs are made	2	NC	6/30/20
Repair exhaust fan in bathroom	0		6/30/21
Repair purge fan. Will not run	0		6/30/21
Repair emergency eye wash. No water	0		6/30/21
Repair leaking air handler	0		6/30/21

Replace missing thumb latch on inside of door	0		6/30/21
Repair plumbing. Low water flow	0		6/30/21
Repair emergency exhaust system for chemistry lab. Won't run	0		6/30/21
Repair exhaust fan in bathrooms 4-002B and D	0		6/30/21
Repair access door to cooling tower to latch properly. Currently held in place with wire	0		6/30/21
Repair leaking flush valves for toilets 3 and 4	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Cap open ends of guardrails at serving line at 5-108C	0		6/30/21
Provide current state inspection tag for boiler	0		6/30/21
Provide current state inspection tags for boilers. FL 89310 and FL 89280	0		6/30/21
Repair exhaust fan in bathrooms 7-001A and B	0		6/30/21
Replace missing fire extinguisher	0		6/30/20
Modify or improve storm drainage from units to prevent storm water from going under units	7	NC	6/30/22

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair punch list on report to AHJ on fire alarm inspection report	0		6/30/21
Label all circuits on electrical panel	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Remove wooden platform structure at baseball field or provide certification by Building Department that structure meets code and design requirements (stair risers not equal, bottom risers not sturdy, missing balasters & graspable handrails, not ADA accessible, electrical outlets not marked as GFCI, etc)	6	NC	6/30/15
Provide current inspection tag for elevator (current tag expired 8-1-14)	4	NC	6/30/17
Prohibit use of room for chemical storage. Use only a designated chemical storage room to store chemicals. This room was designed for Material Storage	2	NC	6/30/17
Repair non-working purge fan in science lab	0		6/30/21
Repair ventilation fan in flammable storage room ( correct fan #7-1-5 )	0		6/30/21
Remove rust from and refinish badly rusted chilled water lines	1	NC	6/30/20

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Evacuation maps in classrooms have only primary evacuation routes. Indicate secondary evacuation routes in contrasting color on all evacuation maps	4	NC	6/30/18
Repair damaged basketball court surface to eliminate exposed concrete and tripping hazards	3	NC	6/30/18
Restripe parking lot	0		6/30/22
Repair tagged light fixture	0		6/30/21
Repair exhaust fan	0		6/30/21
Repair exhaust fan	0		6/30/21
Repair exhaust fan	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Modify or improve storm drainage at all portables units to prevent storm water from going under units and undermining front and or rear landings	5	NC	

Provide covered walkway to all portables	5	NC	6/30/18
Provide window blinds for Code Red situations	0		6/30/21

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Post sign indicating primary and secondary evacuation routes in contrasting colors for all student occupied spaces through out campus	1	NC	6/30/20
Remove storage from mechanical room	3	NC	6/30/16

#### Total Serious Life Safety Citations Total Non-Serious Safety Citations

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair potholes and damaged driveways and parking lots on north and west side of campus	2	NC	6/30/19
Replace missing heat detector	0		6/30/20
Replace missing heat detector	0		6/30/20
Replace missing heat detector	0		6/30/20
Repair ventilation fan	0		6/30/21
Adjust door to latch properly	1	NC	6/30/20
Repair ventilation fan	0		6/30/21
Repair ventilation fan	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE

Repair damaged, rusted and leaking rain gutters and downspouts throughout campus and clean out gutters and downspouts	5	NC	6/30/21
Repair roof leaks in metal storage building at north campus in play fields	0		6/30/21
Repair bent footboard on portable bleachers at Ball Fields	0		6/30/21
Provide emergency disconnect valve for water in all science rooms (1-137, 1-141, 1-145, 1-147 1-167 1-171 and 1-193)	7	NC	6/30/22
School staff have been instructed not to post evacuation maps. Evacuation maps must be posted	0		6/30/19
Fire sprinklers in Mechanical Rooms will not activate as there is no ceiling in these rooms. Heat will go to high point of roof above. Provide adequate fire sprinkler coverage for all Mechanical Rooms	0		6/30/22
Repair 3 troubles indicated on fire alarm panel and punch list on report to AHJ	0		6/30/21
Un-clog sink	0		6/30/21
Remove mold from window. See Teacher	0		6/30/19
Post sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/22
Post sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/22
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Post sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/22
Deactivate dead bolt lock on walk-in refrigerator in Kitchen. No thumb latch inside refrigerator to unlock door. Door has another lock on it with a functioning emergency release	0		6/30/21
Post sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/22
Maintain clear aisle to exit to exterior	0		6/30/19
Post sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/22
	0		6/30/22
Post sign indicating primary and secondary evacuation routes in contrasting colors			

Repair exhaust fan in bathroom	0		6/30/21
Provide flammability test results for 6 couches or remove them from room	0		6/30/19
Repair exhaust fan in bathroom	0		6/30/21
Post sign indicating primary and secondary evacuation routes in contrasting colors	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan for chemical storage room	0		6/30/21
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Provide cover on open damper actuator on AHU8	0		6/30/21
Clean spider webs from room	0		6/30/19
Remove storage from electrical room	0		6/30/19
Provide current annual inspection tag for fire sprinkler system	0		6/30/21
Remove storage from mechanical room. Light tubes	0		6/30/19
Something in lock cylinder of single door to room. Repair lock	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair door to exterior that is rusted through at bottom. Large enough for mice to get into room	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Provide covered walkway to portables	17	NC	6/30/18
Repair or replace deteriorated wood trim at roof	3	NC	6/30/19
Replace deteriorated wood siding and refinish exterior	4	NC	6/30/17
Repair termite damage	2	NC	6/30/19
No violations observed. Boarded up and services disconnected awaiting demolishion	0		
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Determine cause of water damaged ceiling tiles and replace tiles	0		6/30/21
Repair termite damage	2	NC	6/30/19

Eliminate termites	5	NC	6/30/17
Repair or replace deteriorated wood siding and framing	4	NC	6/30/17
Repair or replace deteriorated wood siding	2	NC	6/30/19
Replace missing screens on soffit roof vents	1	NC	6/30/20
Provide cover on exposed power junction box at exterior and provide KO seal for opening in box	0		6/30/21
No violations observed (Jan 2013 portable not accessible, doors sealed shut, waiting for demolition)			
Repair rotted wood siding by ramp	1	NC	6/30/20
Repair or replace deteriorated wood siding, south exterior	0		6/30/21
Repair or replace deteriorated wood siding, south exterior	0		6/30/21
No violations observed. Doors boarded up and services disconnected. Waiting for demolition	0		
No violations observed. Doors boarded up and services disconnected. Waiting for demolition	0		
Repair or replace deteriorated wood siding at entry and at windows	4	NC	6/30/17
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
No violations observed. Doors boarded up and services disconnected. Waiting for demolition	0		

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on annual inspection report dated 3.23.18	0		6/30/21
Replace missing top rail in chain link fencing adjacent to perimeter exit gate west of stairwell 1-015 at NW end of campus	0		6/30/21
Post correct evacuation map indicating primary and secondary evacuation routes in contrasting colors	0		6/30/22
Post correct evacuation map indicating primary and secondary evacuation routes in contrasting colors	0		6/30/22

Post sign indicating primary and secondary evacuation routes in contrasting colors	2	NC	6/30/17
Repair exhaust fan in flammable storage room	0		6/30/21
Repair exhaust fan in bathroom	2	NC	6/30/19

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Provide covered walkway to portables	9	NC	6/30/20
Make repairs as noted on fire sprinkler inspection report, red annual inspection tag dated October 2018	0		6/30/21
Repair inoperable automatic door opener buttons for accessible restrooms	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Make necessary repairs to fire sprinkler system as indicated on inspection report	0		6/30/21
Repair damaged and missing sections of chain link fencing behind chiller Bldg. 10	3	NC	6/30/18
Repair ventilation fan in women's restroom in clinic	0		6/30/21
Repair ventilation fan in men's restroom in clinic	0		6/30/21
Post sign indicating primary and secondary evacuation routes in contrasting colors	1	NC	6/30/23
Post sign indicating primary and secondary evacuation routes in contrasting colors	1	NC	6/30/23
Change swing of door to 1-211 to create secondary egress	1	NC	6/30/22
Repair or replace rusted door frame	0		6/30/21
Repair emergency exhaust system for chemistry lab (fan does not always work and the louvers on the roof do not close after the vent fan shuts down)	4	NC	6/30/17

Remove storage from electrical room	0		
Refinish rusty areas of conditioning system to ensure it operates as designed	2	NC	6/30/19
Determine cause of rusting bar joists and remove loose paint, remove rust and refinish bar joists	1	NC	6/30/20
Repair exhaust fan in bathroom	1	NC	6/30/20
Repair exhaust fan in bathroom	1	NC	6/30/20
DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair or replace rusted door	0		6/30/21

DEFICIENCY DESCRIPTION AND CORRECTIVE ACTION	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Repair exhaust fan in bathroom - principal office	0		6/30/21
Repair exhaust fan in custodial room	0		6/30/21
Make necessary repairs to fire sprinkler system as indicated on annual inspection report dated 8.29.18	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21
Repair exhaust fan in bathroom	0		6/30/21

	TIMES CITED PREV.	PRIOR FY STAT	CORRECTIVE ACTION DATE
Provide covered walkway to and between portable units (P-1 through P-9)	3	NC	6/30/21
Modify or improve drainage at portables P-18 through P-26 to prevent rain water from going under portables. Grout gap between portables and foundations	1	NC	6/30/22
Modify or improve storm drainage to prevent storm water from going under portable at front of unit	1	NC	6/30/20